



700 West Liberty Street | Louisville, KY 40203-1911
Phone: 502.540.6000 | LouisvilleMSD.org

May 19th, 2021

Crystal Dennis
300 Sower Blvd., 3rd Floor
Frankfort, Kentucky 40601

**RE: Floyds Fork WQTC, KPDES No: KY0102784
Discharge Monitoring Report for April 2021.**

Dear Ms. Dennis:

Attached are the Discharge Monitoring Report (DMR) and the Monthly Operator Report (MOR) for the Floyds Fork WQTC, for the month of April 2021.

Also Attached is an Overflow Report

There were no exceedances or bypasses.

If you have any questions concerning the attached DMR's, please contact me at (502)587-5858.

Sincerely,

Joseph Shaun Smith
Process Supervisor

JSS/ Floyds Fork 04/21.

Cc: V. Teague
R. Shaw

81011	Solids, suspended percent removal	K - Percent Removal	0	--	Sample	=	98.0								23 - %	01/30 - Monthly	CA - CALCTD
					Permit Req.	>=	85.0 MO AV MN								23 - %	01/30 - Monthly	CA - CALCTD
					Value NODI												

Submission Note

If a parameter row does not contain any values for the Sample nor Effluent Trading, then none of the following fields will be submitted for that row: Units, Number of Excursions, Frequency of Analysis, and Sample Type.

Edit Check Errors

No errors.

Comments

Attachments

Name	Type	Size
FlyodsForkDischargeReport.pdf	pdf	17296.0
FFMOR042021.XLS	xls	330240.0
FFCOVER0421.pdf	pdf	33886.0

Report Last Saved By

Floyds Fork WQTC MSD

User: staci.huber@louisvillemsd.org
 Name: Staci Huber
 E-Mail: staci.huber@louisvillemsd.org
 Date/Time: 2021-05-20 10:39 (Time Zone: -04:00)

Report Last Signed By

User: JOSEPH.SMITH@LOUISVILLEMSD.ORG
 Name: Joseph Smith
 E-Mail: joseph.smith@louisvillemsd.org
 Date/Time: 2021-05-20 11:00 (Time Zone: -04:00)



KPDES #	Facility ID	Water Quality Treatment Center	Receiving Stream of Treatment Center	Region
KY0102784	MSD0294	FLOYDS FORK	FLOYDS FORK	NA

Facility Type	Facility ID	Facility Address	If Pump Station, Name of Pump Station:	Receiving Stream	Discharge to
SMHSewer Manhole	118639	17900 ELLERSLIE DR		BRUSH RUN	CATCH BASIN

<u>Activity Code / Description</u>	<u>WO #</u>	<u>Ref No</u>	<u>Initiated</u>	<u>Initiated By</u>	<u>Assigned To</u>	<u>Disch Status</u>	<u>Event Date</u>	<u>Problem</u>	<u>Result</u>	<u>Completed</u>	<u>Condition</u>
: DISDW: DRY WEATHER DISCHARGE	3361900		04/02/2021	BIVIN	BIVIN	REPAIRED - ISSUE RESOLVED	04/02/2021	OBSTRUCTION- NOT GREASE / ROOTS	UNAUTHORIZED DISCHARGE- WATERS	04/02/21 10:04 AM	MAIN

Discharge Reporting:

Discharge Amount:	800 GAL
Cause:	CONTRACTOR PLUG IN MH# 117799 AT 2017 CARABINER WAY.
Clean Up:	NO CLEAN REQUIRED -- NO SOLIDS.
Control Zone:	MSD ADVISED CUSTOMER TO AVOID SEWAGE CONTACT.
Impact:	FLUSHED FROM MH# 111799 AT 2017 CARABINER NEXT STREET OVER PULLED OUT CONTRACTOR PLUG OBSERVED MH# 118639 DISCHARGING.
Repair:	FLUSHED MH# 111799 AT 2017 CARABINER NEXT STREET OVER PULLED OUT CONTRACTOR PLUG.
Public Notification:	3 DISCHARGE SIGNS PLACED IN AREA.

Notifications:

4/2/21 1:14 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
----------------	--------	---

Total Facilities Printed: 1

Total Work Orders Printed: 1