

Louisville and Jefferson County Metropolitan Sewer District 700 West Liberty Street Louisville Kentucky 40203-1911 502-540-6000 www.msdlouky.org

March 24, 2008

Ms. Kathy Thurman Environmental & Public Protection Cabinet Division of Water 14 Reilly Road Frankfort, KY 40601

Re: Morris Forman Wastewater Treatment Plant (MFWTP) KPDES Permit No. KY0022411

Dear Ms. Thurman:

In accordance with the provisions of the KPDES Permit referenced above, the monthly operating report and the monthly Discharge Monitoring Report (DMR) for the reporting period February 1 to February 29, 2008 are enclosed. All permit requirements were met for the month of February, 2008.

Should you have any questions, please contact me at (502) 540-6793.

Sincerely,

Alex E. Novak Operations Manager

paw

MFDMR0208.doc

Enclosures

cc: C. Roth, DOW-Louisville

G. Harrison, EPPC

A. Freeman, EPA, Region IV

Rlex E. Moral

R. Shaw, MSD

A. Vicory, ORSANCO



PERMITTEE NAME/ADDRESS (Include Facility Name/Location if Different) NAME

MSO MURRIS FORMAN STR

ADDRESS C/G LOUISVILLE/JEFF CD MSD

ASEE ALGOROUSE PARY

ATTHE ALEX E MEDIAN DESIGNATION

LOUISVILLE

FACILITY

LOCATION

KY 40211-2497

MSD MORRIS FORM STM

KY Woell

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES) DISCHARGE MONITORING REPORT (DMR)

MONITORING PERIOD

TO

YEAR

CE

DAY

PERMIT NUMBER

MO

YEAR

FROM

DISCHARGE NUMBER

DAY

МО

MAJOR (BUSK LV) F - FINAL

JEFFE

Form Approved.

OMB No. 2040-0004

MUNICIPAL DISCHARGE

EFFLUENT

*** NO DISCHARGE : _ : **

NOTE: Read Instructions before completing this form

A STATE OF THE PARTY OF THE PAR	Luci El VI - 1 Restri	1					NOTE: Read Instru	ctions befo	re con	npleting thi	s form.
PARAMETER		QUAN	TITY OR LOADING			,		FREQUENCY OF	SAMPLE		
		AVERAGE	MAXIMUM	UNITS	MINIMUM	AVERAGE	MAXIMUM	UNITS	EX	ANALYSIS	TYPE
DXYGEM. DISEDLYED	SAMPLE	安林松田市	海绵安全部的			중심중상점점	삼삼중중중	(19)			
(DD)	MEASUREMENT				7.0				0		
QCCC 1 0 0	PERMIT	古诗诗诗诗诗	****	*****	200	: 安外条件条件	各分分分分分	1		MILY	GRAB
EFFLUENT GRUSS VALUE	 			e⊈ 3 <i>e ey</i> e 49e	INST MIM			(V) () - 1			
soo. E-pay	SAMPLE	25 672	22.240	(24)	计计计计计			(19)			
(20 BEG, 0)	MEASUREMENT	25,673	33,349			23	30		4		
701910 E C O	PERMIT	REPORT	REPERT		非特殊安全社	30	45		Ī	DAILY	COMPOS
SEC/BIDL PRCS CMPLT	REQUIREMENT	MD AVG	MX WELAV	LBEZDY		MO AVG	MX WK AV	28Q.T	4.12		
BOS. SHOAN	SAMPLE MEASUREMENT	337,513	252 165	(26)	在青发企业有			(19)			
(ZO DEG C)	<u> </u>		353,165	1		241	265		0		
70350 6 0 0	PERMIT REQUIREMENT	REPORT	REPORT		我要要营州教	REPORT	REPORT		i	MILY	COMPOS
RAW SEW/INFLUENT		MO AVG	WA WW AV	LHS/DY		MD AVG	MA WA AV	PMSW.71.			
Control of the Contro	SAMPLE MEASUREMENT	经验的证据	3. 经收款条款		6 7	经设备债券条		(12)			
 				_	6.7		7.0		0		
OCACO : 0 0 Effluent gross value	PERMIT REQUIREMENT	考查会会协会	************	公共	Ó. O	计算计算计算	9.0		Ž	PAILY	arab
SOLIDER TOTAL	SAMPLE			旅行歌歌	MINIMUM		MAKIMUM	150			
SUSPENDED	MEASUREMENT	19,558	24,732	(24)	特殊特许於發	10	20	(19)	_		
	PERMIT	REPORT	REPURT			18	23		1		
SEC/BIOL PROS OMPLT	REQUIREMENT	MO AVG		t Chatte America	强势会会外	30	45		Ï	MILY.	COMPOS
polips, norm	SAMPLE	AND MARK	MX WK AV	LBS/DY	22 80 01 30 10 22	MO AVG	MX WK AV				
SUSPENDED	MEASUREMENT	302,975	330,851	\ ೬೮.	特许安全的	215	241	(19)	^		
00520 3 0 0	PERMIT	REPORT	REPORT	1	教育学生安全	<u> </u>	REPORT		0		
BAN SEW/INFLUENT	REQUIREMENT	MO AVG	MX WK AV	LRS/DY	THE DE DE DE LEE	REPORT.			ŝ)AILY	COMPOS
BITTOGEN, ANTONIA	SAMPLE	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	7.14.20 . 833.4 . 13,3 35	(26)	***************	MO AVO	MX WK AV	£	Jac.		
TOTAL (AS N)	MEASUREMENT	6,130	7,142	F.07	26 26 65 52 35 36	5.6	6.7	(19)	0		[
20610 8 0 0	PERMIT	REPORT	REPORT		*****	20	30			5 A 5 5 5 5 5	01 7 TO 14 F 15 TO 15 F
SECZBIOL PROS CMPLT	REQUIREMENT	MO AVO	MIX WK AV	LBS/DY	*******	MO AVG		E-170 - F		MILY	COMPOS
NAME/TITLE PRINCIPAL EXECUTIVE	OFFICER I certify					I THE PROVIN	MX WK AV	FELEDUAL	:		

H. J. SCHARDEIN, JR.

EXECUTIVE DIRECTOR

TYPED OR PRINTED

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

SIGNATURE OF PRINCIPAL EXECUTIVE OFFICER OR AUTHORIZED AGENT

COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here)

a - INFLUENT

E - SECONDARY EFFLUENT

PERMITTEE NAME/ADDRESS (Include Facility Name/Location if Different)

HES MURRIS FORMAN STP

ADDRESS C/O LOUISVILLE/JEFF CO MED

45EF ALGUNGUIN PERY

LUUTSVILLE

FACILITY

MY 40211-2497

HED MORKIS FORM SIR LOCATION

KY 46211

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES) DISCHARGE MONITORING REPORT (DMR)

MONITORING PERIOD

TO

YEAR

DAY

PERMIT NUMBER

MO

YEAR

FROM

DISCHARGE NUMBER

DAY

20

МО

0.00

MAJOR (SUBR LV) F - FINAL

STREE

Form Approved.

OMB No. 2040-0004

MUNICIPAL DISCHARGE

EFFLUENT

with NO DISCHARGE !

ATTN ALEX E NOVAK,	DHER MOR	2 2 That from A at		No. 400 G	74 10 374		IOTE: Read Instru				s form.
PARAMETER		QUANTITY OR LOADING				NO. EX	OF	SAMPLE TYPE			
		AVERAGE	MAXIMUM	UNITS	MINIMUM	AVERAGE	MUMIXAM	UNITS	[^	ANALYSIS	ITPE
MITEDGER: AMMONIA TOTAL (AS N)	SAMPLE MEASUREMENT	7496	7748	(25;	安安安安长	6.9	7.0	(19)	0		
00810 G G G RAW SEW/INFLUENT	PERMIT REQUIREMENT	REPORT MD AVG	MEPORT MX WK AV	LBS/DY	经验检验检验	REFORT MO AVS	REFORT MX WK AV	141V.2		PAILY	COMPOS
FLOW: IN COMBUIT OR THRU TREATMENT PLANT	SAMPLE MEASUREMENT	131.7	169.7	(03)	建造物的物	经营业营业	张荣宗安安		0		
SCOSO E O O SEC/BIOL PROS OMPLY	PERMIT REQUIREMENT	REPORT MO AVG	REPORT DAILY MX	MSD	安安安安安	共产业企业	********	** * **		COMTIN COUS	CONTIN
CHLORING TOTAL TESIDUAL	SAMPLE MEASUREMENT	转物物价价价	公司的公司		特格特拉特	0.010	0.010	(19)	0		
NGCAC I O C <u>Effluent gross valu</u> s	PERMIT REQUIREMENT	教育學校教教	· 经分类分类等。	***** *****	整整营业营营	10.017 HO AVG	O. OIF DAILY MX	l Mozi		MILY	GRAB
COLIFORM, FECAL GENERAL	SAMPLE MEASUREMENT	经营业营业	安林安安安		安安安安安	301	817	(13)	7		
74055 : 2' 0 EFFLUENT GROSS VALUE	PERMIT REQUIREMENT	教教教教教教	基金等价资 类。	* 按特拉 技学校会	*******	1000 30DA GEO	Z DA GEG	100ML		DAILY	GRAB
SGD, S-DAY PERGENT REMOVAL	SAMPLE MEASUREMENT	长长长竹竹	安全安全		91	经安全货 条	我敢敢敢敢	a ship area a	0		
BIOIO M () <u>PERCENT REMOVAL</u>	PERMIT REQUIREMENT	安林林林林林	华女女女女女	经未按	MO MIN	安安安安安	安林长女女	ER- CENT		NCE/ MONTH	CALCID
SOLIDS: SUSPENDED PERCENT REMOVAL	SAMPLE MEASUREMENT	安林安祥分录	经营销售的		92	****	计算条件符号	(23)	0		
21011 A 0 0	PERMIT	大会会会会	**************************************	***	Sub-	装载数装套 套	安安安安安	FER-		ance/	CALCID

12 3 32 34

MO MIN

NAME/TITLE PRINCIPAL EXECUTIVE OFFICER

H. J. SCHARDEIN, JR. EXECUTIVE DIRECTOR

PERCENT REMOVAL

TYPED OR PRINTED

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

SIGNATURE OF PRINCIPAL EXECUTIVE OFFICER OR AUTHORIZED AGENT

TELEPHONE DATE 5021 540-6000 08 03 25 NUMBER YEAR MO DAY

COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here)

REQUIREMENT

SAMPLE MEASUREMENT PERMIT REQUIREMENT

9 - INFLUENT

E - SECONDARY EFFLUENT

CENT

MUNTH

PERMITTEE NAME/ADDRESS (Include Facility Name/Location if Different) NAME

MSD MORRIS FORMAN ETP

ADDRESS C/O LOUISVILLE/JEFF CO MSD

ARRE ALGENOUSE PERV

LOUISVILLE

FACILITY

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES) DISCHARGE MONITORING REPORT (DMR)

www.combooks.s.s.s PERMIT NUMBER

DOLL B DISCHARGE NUMBER MAJOR (SUBR LV) F - FINAL

JEYFE

Form Approved.

OMB No. 2040-0004

SECONDARY HYPASS EFFLUENT

*** NO DISCHARGE I I day

KY 40211-2497 MONITORING PERIOD MES MORRIS FORM STP YEAR МО DAY YEAR DAY LOCATION MO FROM KY 40211 TO 71. " ATTER ALEY & SEWAR, ARKR MAR

ATHU ALEX & MOVAK	UPIR MG	R					NOTE: Read Instri	uctions befo	ore con	npleting thi	s form.
PARAMETER		QUAN	ITITY OR LOADING		G	QUALITY OR CONC	ENTRATION		NO. EX	FREQUENCY OF	
		AVERAGE	MAXIMUM	UNITS	MINIMUM	AVERAGE	MAXIMUM	UNITS	EX	ANALYSIS	TYPE
SOD, SHDAY	SAMPLE	分於於斯特察	新安安安 安		新安安安安	·		(19)	 		
(20 DEG. C)	MEASUREME	INT	Limited and the second			163	174		0		
00310 F 0 C	PERMIT	****	*****		计设计计设计	REPORT	REPORT	1		WHEN	COMPOS
PRI/PRLM PRCS CMPLT	REQUIREME	NT		- 安安哲士		MO AVG	MX WK AV	AMOZI.		DISCH	í
BUD, 5-DAY	SAMPLE	共命会教会会	音を存在する		安全会会会			(19)	 		
(20 DEG. C)	MEASUREME	ENT				45	51		0		
00310 1 0 0	PERMIT	安保分价价量	教育学科教育 多	***	**************************************	REPORT	REPORT	1		WHEN	COMPOS
EFFLUENT GROSS VALUE	REQUIREME	NT		经证券金		MO AVO	MX WW AN	J mozt.		DISCH	P .
SOLIDS: TOTAL	SAMPLE	经经验收益额	****		***			(19)			
SUSPENDED	MEASUREME	NT				92	116		0		
20530 8 0 0	PERMIT	女士女士女女	· 经经生长营餐	+++ +++	*****	REPORT	REPORT			WHEN	COMPOS
PRI/PRLM PROS CMPLT	REQUIREME	NT		n 3 4 2		MO AVG	MX WK AL	Marl	1.75	DISCH	Ģ
TOLIDS, TOTAL	SAMPLE	拉拉拉拉拉拉	表示哲学类型		****		***************************************	(19)			
SUSPENDED	MEASUREME	NT				41	58		0		
00880 1 0 0	PERMIT	安长安安特	*******	***	*****	REPORT	REPORT			WHEN	COMPOS
EFFLUENT GROSS VALUE	REQUIREME	NT		安全教育		MO AVO	MX WK AS	/ MG/1.		DISCH	
HITROGEN: AMMONIA	SAMPLE	安全各种基本	安全安全会		***			(19)			
TOTAL (AS N)	MEASUREME	ENT				8.6	9.3		0		
00	PERMIT	*************************************	***	***	计大大大大	REPORT	REPORT	-		WHEN	COMPOS
PRI/PRLM PROS CMPLT	REQUIREME	NT		: 指重如如		MO AVG	MX WK AV	/ MG/L		DISCH	G .
MITROGEN, AMMONIA	SAMPLE	公共分计公公	经营业业		****			(17)	I		
TOTAL (AS N)	MEASUREME	:NT		-		7.3	7.4		0		
<u> </u>	PERMIT	*********	******** ***	[가장꾼 -	营养 类类类	REPORT	REPORT			WHEN	COMPOS
EFFLUENT GROSS VALUE		NT		显示表示		-MO AVG	MX WK AV	MOZL		DISCH	Ģ.
TLOVE IN COMPUTE OR	SAMPLE		65.70	(03)	*****	的资本会会会	****	-			
THRU TREATMENT PLANT		***	65.70		-				0		
60050 F 0 0	PERMIT	REPORT	REPORT		****	***	********	***		WHIEN	CONTIN
PRI/PRLM PRCS CMPLT	REQUIREME	1 1 1 2 1 1 7 2 1		MGD				特种类型		PISCH	3
NAME/TITLE PRINCIPAL EXECUTIVE	pr	ertify under penalty of law that epared under my direction or su	pervision in accordance with	h a system desim	ned	フ .		TELEPHON	VE	DA	\TE
H. J. SCHARDEIN, JR.	to	assure that qualified personnel p bmitted. Based on my inquiry of	properly gather and evaluate	the information		101					
EXECUTIVE DIRECTOR	i or	those persons directly responsib	le for eathering the informs	tion the inform-	stion / Small	MXIA	Laule				
	I a	bmitted is, to the best of my known aware that there are significated	nt penalties for submitting f	alse information.	O GIGINA	TURE OF PRINCIPAL)2 540-6		08 0	3 25
TYPED OR PRINTED	inc	duding the possibility of fine an	d imprisonment for knowin	a minintiana	' I OFFI	ICER OR AUTHORIZE	D AGENT ARE	Δ		17-1-1	

OFFICER OR AUTHORIZED AGENT

AREA NUMBER YEAR MO DAY

COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here)

MENITURING DURING PERIODS OF SECONDARY BYPASS IN ADDITION TO REGULAR MONITORING.

1 - FINAL EFFLUENT

MORRIS FORMAN WASTEWATER TREATMENT PLANT KPDE8 PERMIT NO. KY0022411

JEFFERSON COUNTY, KENTUCKY MONTH OF February PLANT CAPACITY - 105 MGD RECEIVING STREAM - OHIO RIVER

				T TE	MP	T	-11																								
	WASTE	EWATER	FLOWS	(DE			рH		ETS		SS		TS	D.O.	1	5-DAY BOD	·	7													
		ilion Gallo		100	<u>.u.</u>	+			//L,)	(m	g/L)	(mg/L)	(mg/L)	(mg/L)															
	Final	Sec.		7						İ								RETUI	RN SLL	IDGE	T	ACDA	TION BASIN			IVE		LORINA	TON	FIN	AL.
DATE	Effluent	Effluent	Bypass	raw	final	raw	final		ė			i		1		prim.		FLOW					MLVSS SE	T (%)	Sludge	Primary	Chlorine		Fecal	EFFLU	JENT
2/1	176.9							гаw 8 14.	final			raw	final	final	raw	final	final		q/L	g/L	mg/L	g/L	MLVOG SE	i avi		Sludge	Dosage	Resid	Coliform	NH3-N	Pump.
2/2	116.4	116.4										Į		11.7	293	214	68	16.5				3.2	2.8 19		MG	MG	KLBS		#/100 mi	mg/L	Hours
2/3	125.6	125.6		1		1								8.1	378	200	18	17.3		12.4	1	4.1	3.5 24		1.00	0.32		0.010	132	8	5.90
2/4	176.8	133.3	43.						_					8.3		169	19	17.4		11.2	1	3.3	2.8 20		0.98	0.30	2.23	0.010	94	10	24.00
2/5	198.9	133.0	65.9				6.	1	_ :-					7.0	163	173	45	17.2		11.7	19.5	2.7			1.02	0.22	2.08	0.010	16	11	24.00
2/6	249.8	135.6	114.			1	6,							8.4	316	195	34	19.0		9.9	19.5	3.0	2.3 22 2.5 20		0.99	0.14	4.03	0.010	1100	9	24.00
2/7	189.7	137.1	52.6				6.			1	62			14.0	126	80	55	20.7	11.6	9.3	20.0	2.9	2.3 19		0.94	0.19		0.010	68	8	24.00
2/8	175.2	136.6	38.6				6.8				39			13.4	155	133	41	20.3		8.8		2.9			0.84	0.22	4.24	0.010	450	5	24.00
2/9	163.8	130.7	33.1	1			6.9							10.6	167	161	36	20.6		8.9	1	3.0	2.2 19: 2.3 186		0.74	0.38	3.27	0.010	608	7	24.00
2/10	157.7	133.1	24.6				6.8			146				11.0	164	118	36	20.5		10.5	1	2.8			0.74	0.23	2.58	0.010	168	7	24.00
2/11	157.8	134.3	23.5			7.3	6.9				32			11.5	153	149	29	20.0		8.6	20.0	2.2	2.3 17		0.78	0.31	2.23	0.010	2300	8	24.00
2/12	222.8	134.1	88.7				6.8	1			47			14.1	235	144	32	19.1	11.8	9.4	20.0	2.3	1.9 162		0.78	0.30	2.16	0.010	2400	8	24.00
2/13	204.2	135.2	69.0			7.6	6.7				54			11.3		188	98	19.7	7.8	6.1	20.0	2.2	1.8 134 1.8 160		0.73	0.20	3.95	0.010	93	9	24.00
2/14	200.4	135.5	64.9			1	6.8	1			43			11.5	234	204	76	22.4	11.4	9.1	E	5,4		-	0.73	0.28	4.40	0.010	9900	8	24.00
2/15	211.4	135.9	75,5				6.8	1			45			8.8	209	159	53	23.4	13.5	10.8		2.6	4.4 161		0.76	0.39	3.10	0.010	2100	3	24.00
2/16	191.1	125.8	65.3			1	7.0				38			10.6	217	137	47	23.3	13.5	11.1	19.9	3.4	2.2 152		0.74	0.20	3.52	0.010	136	4	24.00
2/17	207.8	131.8	76.0				6.9	.1			36			9.5	184	131	43	23.2	12.7	11.0		4.0	2.9 162		0.77	0.29	2.56	0.010	470	7	23.90
2/18	166.6	135.8	30.8	42		7.4	6.8			,	42			10.3	191	133	56	22.9	12.8	10,3		2.6	3.4 188		0.90	0.36	3.69	0.010	420	7	24.00
2/19	140.2	137.2	3.0	45		t .	6.8				30			10.3	269	170	34	23.2	8.5	6.9		2.1	2.2 168		0.90	0.30	3.47	0.010	172	6	24.00
2/20	127.6	127.6	0.0	42	56	7.6				168	24			11.3	221	172	19	22.8	11.0	8.8	18.9	2.1	1.8 150	- 1	0.90	0.28	1.23	0.010	260	6	23.90
2/21	150.6	124.4	26.2	44	55	7.5	8.9	1		290	21			10.0	340	193	17	22.9	11.1	9.4	18.4	2.6	1.8 156		0.76	0.27	2.17	0.010	136	8	24.00
2/22	206.3	129.7	76.6	43	51	7.3	7.0				36			9.9	321	197	41	22.8	11.7	9.4	17.5	2.8	2.3 159		0.73	0.28	2.12	0.010	54	9	24.00
2/23	162.2	130.6	31.6	45	51	7.4	6.9 6.8	1	_	158	47			8.8	336	302	99	23.5	16.5	13.4	16.3	2.9	2.4 173	62	0.78	0.30	2.57	0.010	23	10	24.00
2/24	143.4	129.6	13.8	44	54	7.5	6.8			144	34			8.5	202	179	46	23.1	13.5	11.3	17.7	3.5	2.4 167	58	0.86	0.21	3.72	0.010	74700	5	24.00
2/25	136.0	134.0	2.0	45	54	7.4	6.8			180	32		i	12.3	239	142	27	23.3	11.1	9.2	20.0	2.1	3.0 183		0.89	0.22	3.71	0.010	2900	3	24.00
2/26	182.6	136.4	46.2	44	54	7.5				268	27		-	11.6	278	152	21	23.5	9.9	8.3	20.0	2.1	1.6 182		0.62	0.23	3.71	0.010	118	7	24.00
2/27	155.1	134.6	20.5	45	54	7.5	6.9 6.9			196	49		- 1	13.9	214	148	46	23.1	13.4	11.0	19.6	2.2	1.9 157	71	0.77	0.21	3.37	0.010	3	10	24.00
2/28	135.1	131.8	3.3	44	55	7.5	6.8	1		182	394			11.2	221	124	37	23.0	12.7	10.4	19.7	3.1	2.5 172		0.79	0.22	4.93	0.010	580	7	24.00
2/29	139,5	128.5	11.0	44	58	7.1	6.8		-	556	31		- 1	12.3	362	172	25	23.1	11.6	8.6	20.0	2.7	2.6 186		0.86	0.22	2.84	0.010	380	9	24.00
				• • •	٣,	1.1	0.0	16.0	0.1	258	27		l	12.9	273	160	31	23.0	12.4	10.4	20.0	3.6	2.3 178	65	0.93	0.33	2.50	0.010	74	10	24.00
					- 1						- 1		ļ	l							20.0	3.0	3.1 176	49	0.91	0.32	2.45	0.010	390	11	24.00
									·																	i					
Total		3818.8	1152.7								1												·····								
Average	171.4	131.7	39.7	45	54	7.4	6,8	95	0.4	215	المد		- 1				l	620.8		- 1					24.100	7 705					
CEWIED OF								<u> </u>	0.4	210	44			10.8	241	165	42	21.4	12.1	9.9	19.0	2.9	2.5 177	63	24.100 0.831	7.720 0.266			1	F	377.70
SEWER CO	NNECTIO)NS		135707	TIMES	4≃	542828	SEWE	a poe	I B ATTC			***										77	50	0.031	U.200	3.12	0.010	301	8	23.37

135707 TIMES 4 = 542828 SEWER POPULATION

IND. WASTER POPULATION EQ

CUSTOMERS 335 FLOW 1089849 BOD 1486931

TSS 922592

Authorized Agent Authorized Agent Authorized Agent

Certification No. 4663

JEFFERSON COUNTY, KY

Month of	Feb-08			
Average Flow				
_	Primary		Secondary	
SETTLING TANKS		Battery A	Battery B	Battery C
Average Flow (MGD)	171.4	55.30	58,94	17.46
Tanks in Service	4.00			2.97
Surface Area (Ft.2)	77000.00	69200.00	69200.00	25690.50
Volume (MG)	8.33	7.09	7.09	2.63
Weir Length (Ft.)	2860.00	2868.00	2868.00	1064.75
Avg. Weir Overflow (GPD/Ft)	59930.07	19281.73	20550.91	16398.29
Avg. Settling Rate (GPD/Ft2)	2225.97	1122.47	1013.28	755.04
Avg. Detention Time	1.17	3.08	2.89	3.62
AERATION TANKS		Battery A	Battery B	Battery C
Volume (Gallons)		4200000	4200000	2100000
Avg. Flow (MGD)		64.18	70.12	19.59
Avg. Detention Time (Hours)		1.57	1.44	2.57
CHLORINE CONTACT CHAMBERS				
Contact Chambers in Use	2.00			
Volume (Gallons)	2340000			

0.33

Remarks: BY-PASS REPORTS (See Attached)

Avg. Detention Time (Hours)

Report Selections: Treatment Plant: MSD0278 MORRIS FORMAN, Excluding PPI, CSO, Result: WUS, Act Code: DISDW, DISREV

KPDES# KY0022411

Facility iD MSD0278

Treatment Plant Name **MORRIS FORMAN**

Receiving Stream of Treatment Plant **OHIO RIVER**

Region WEST

Facility Type

SMH Sewer Manhole

Facility ID 08426

Facility Address 4315 PRUITT CT

If Pump Station, Name of Pump Station:

Receiving Stream

Discharge to SOUTH FORK GROUND

BEARGRASS CREEK

US

Activity Code / Description DISREV: RAIN EVENT

DISCHARGE

WO# 740843

Initiated 02/06/08 01:24 PM Initiated By FRENCH

Assigned To GRIFFITH

Disch Stat

Event Date 09/03/03

Problem LACK OF SYSTEM CAPACITY

Resolution DISCHARGE TO WATERS OF THE Completed 02/06/08 03:00 PM

Spot Inspections:

Discharge Amount:	2,350 GAL
Cause:	LACK OF SYSTEM CAPACITY
Clean Up:	NO DEBRIS OBSERVED, NO CLEANUP REQUIRED
Control Zone:	BARRICADES AND TEMPORARY SIGNS PLACED ON ADJACENT MANHOLE 2-3 FEET AWAY.
Impact:	SMALL AMOUNT OF DILUTE SEWAGE SEEPING FROM PICKHOLES AT MANHOLE
Repair.	A SOLUTION FOR THIS LOCATION WILL BE INCLUDED IN THE SSDP TO BE SUBMITTED TO EPA DECEMBER 2008

02/07/08 12:59 AM	Email notification of unauthorized discharge sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov
	Public notified with temporary signs and barricades

Report Selections: Treatment Plant: MSD0278 MORRIS FORMAN, Excluding PPI, CSO, Result: WUS, Act Code: DISDW, DISREV

KPDES #	
KY0822411	(Confd)

Facility ID MSD0278

Treatment Plant Name MORRIS FORMAN

Receiving Stream of Treatment Plant OHIO RIVER

Region WEST

Facility Type

SMH Sewer Manhole

Facility ID 08430

Facility Address 4341 PRUITT CT

If Pump Station, Name of Pump Station:

Receiving Stream

Discharge to SOUTH FORK GROUND

BEARGRASS CREEK

us

Activity Code / Description DISREV: RAIN EVENT DISCHARGE

WO # 740646 Initiated 02/06/08 01:24 AM Initiated By GRIFFITH

Assigned To GRIFFITH

Disch Stat D

Event Date 02/17/00

Problem LACK OF SYSTEM CAPACITY

Resolution DISCHARGE TO WATERS OF THE Completed 02/08/08 07:10 AM

Spot Inspections:

Discharge Amount:	1,800 GAL
Cause:	LACK OF SYSTEM CAPACITY - HEAVY RAIN
Clean Up:	CLEAN UP NEEDED
Control Zone:	DOOR HANGERS WERE POSTED
Impact	SEWAGE AND DEBRIS FOUND ON THE GROUND
Repair:	THIS LOCATION WILL BE IN THE SANITARY SEWER DISCHARGE PLAN TO BE SUBMITTED BY DEC. 31, 2008

02/06/08 12:58 PM	Supplemental Email notification of unauthorized discharge has been sent to ireland sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov
02/06/08 01:24 PM	ADVISED CUSTOMERS BY DOOR HANGERS
02/06/08 12:58 PM	Email notification of unauthorized discharge sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov

Report Selections: Treatment Plant: MSD0278 MORRIS FORMAN, Excluding PPI, CSO. Result: WUS. Act Code: DISDW, DISREV

KPDES #	
KY0022411	(Cont'd)

Facility ID MSD0278

Treatment Plant Name **MORRIS FORMAN**

Receiving Stream of Treatment Plant **OHIO RIVER**

Region WEST

Facility Type SMH Sewer Manhole

Facility ID 08935-SM

Facility Address

If Pump Station, Name of Pump Station:

Receiving Stream

MIDDLE FORK

BEARGRASS CREEK

Discharge to STREAM

Completed

Activity Code / Description DISREV: RAIN EVENT DISCHARGE

WO# 740271

Initiated 02/05/08 12:58 PM

Initiated By **GRIFFITH**

1001 BRECKENRIDGE LN

Assigned To GRIFFITH

Disch Stat D

Event Date 11/29/01

Problem LACK OF SYSTEM

Resolution DISCHARGE TO CAPACITY WATERS OF THE

us

02/11/08 12:45 PM

Spot Inspections:

Discharge Amount:	1,620,000 GAL
Cause:	LACK OF SYSTEM CAPACITY - HEAVY RAIN
Clean Up:	NONE POSSIBLE DUE TO MAGNITUDE OF STORM
Control Zone:	NO CONTROL ZONE NEEDED
Impact:	NO IMPACT OBSERVED
Repair:	THIS LOCATION WILL BE IN THE SANITARY SEWER DISCHARGE PLAN TO BE SUBMITTED BY DECEMBER 31, 2008

02/05/08 12:58 PM	Supplemental Email notification of unauthorized discharge has been sent to ireland sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov
02/05/08 12:58 PM	ADVISED CUSTOMERS WITH PERMANENT SIGNS
02/05/08 12:58 PM	Email notification of unauthorized discharge sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov

Report Selections: Treatment Plant: MSD0278 MORRIS FORMAN, Excluding PPI, CSO, Result: WUS, Act Code: DISDW, DISREV

KPDES # KY0022411 (Cont'd)

Facility ID MSD0278

Treatment Plant Name MORRIS FORMAN

Receiving Stream of Treatment Plant OHIO RIVER

Region WEST

Activity Code / Description DISREV: RAIN EVENT DISCHARGE

WO# 743419 Initiated 02/12/08 05:05 PM

Initiated By GRIFFITH Assigned To GRIFFITH

Disch Stat

Event Date Problem
11/29/01 LACK OF

Problem Resolution
LACK OF SYSTEM DISCHARGE TO
CAPACITY WATERS OF THE

us

Completed O 02/13/08 01:00 AM

Spot Inspections:

Discharge Amount:	585,268 GAL
Cause:	LACK OF SYSTEM CAPACITY - HEAVY RAIN
Clean Up:	NO CLEAN UP NEEDED
Control Zone:	PERMANENT SIGNS POSTED
lmpact	NO IMPACT OBSERVED
Repair:	THIS LOCATION WILL BE IN THE SANITARY SEWER DISCHARGE PLAN TO BE SUBMITTED BY DEC. 31, 2008

02/12/08 12:58 PM	Supplemental Email notification of unauthorized discharge has been sent to ireland sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov
02/12/08 05:05 PM	ADVISED CUSTOMERS BY PERMANENT SIGNS
02/12/08 12:58 PM	Email notification of unauthorized discharge sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov
	S. 1-19-1-19-19-19-19-19-19-19-19-19-19-19-

Report Selections: Treatment Plant: MSD0278 MORRIS FORMAN, Excluding PPI, CSO, Result: WUS, Act Code: DISDW, DISREV

KPDES# KY0022411 (Cont'd)

Facility ID MSD0278

Treatment Plant Name MORRIS FORMAN

Receiving Stream of Treatment Plant OHIO RIVER

Region WEST

Facility Type

SMH Sewer Manhole

Facility ID 16649

Facility Address 1726 FRASER DR If Pump Station, Name of Pump Station:

Receiving Stream

Discharge to DITCH

Completed

02/08/08 11:00 AM

SOUTH FORK BEARGRASS CREEK

Activity Code / Description

DISREV: RAIN EVENT DISCHARGE

WO# 740659

Initiated 02/06/08 10:15 AM Initiated By GRIFFITH

Assigned To GRIFFITH

Disch Stat D

Event Date 01/24/02

Problem LACK OF SYSTEM

Resolution DISCHARGE TO CAPACITY WATERS OF THE

UŞ

Spot Inspections:

Discharge Amount:	481,013 GAL	
Cause:	LACK OF SYSTEM CAPACITY - HEAVY RAIN	
Clean Up:	NONE NEEDED	
Control Zone:	NO CONTROL ZONE NEEDED	
Impact:	NO IMPACT OBSERVED	
Repair:	WILL BE MONITORED AND EVALUATED FOR REPAIR	

02/06/08 12:58 PM	Supplemental Email notification of unauthorized discharge has been sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov
02/06/08 10:15 AM	ADVISED CUSTOMERS BY DOOR HANGERS
02/06/08 12:58 PM	Email notification of unauthorized discharge sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov

Report Selections: Treatment Plant: MSD0278 MORRIS FORMAN, Excluding PPI, CSO, Result: WUS, Act Code: DISDW, DISREV

KPDES #
KY0022411 (Cont'd)

Facility ID MSD0278

Treatment Plant Name MORRIS FORMAN

Receiving Stream of Treatment Plant OHIO RIVER

Region WEST

Activity Code / Description
DISREV: RAIN EVENT
DISCHARGE

<u>WO #</u> 743394 Initiated 02/12/08 04:00 PM

Initiated By MITCHELL Assigned To GRIFFITH

Disch Stat

Event Date F

Problem LACK OF SYSTEM CAPACITY

Resolution DISCHARGE TO WATERS OF THE US Completed 02/13/08 01:15 PM

Spot Inspections:

Discharge Amount:	74,013 GAL
Cause:	LACK OF SYSTEM CAPACITY - HEAVY RAIN
Clean Up:	NO CLEAN UP NEEDED
Control Zone:	PERMANENT SIGNS POSTED
Impact:	NO IMPACT OBSERVED
Repair:	THIS LOCATION WILL BE INCLUDED IN THE SANITARY SEWER DISCHARGE PLAN TO BE SUBMITTED BY DEC. 31, 2008

02/12/08 12:58 PM	Supplemental Email notification of unauthorized discharge has been sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov
02/12/08 04:00 PM	ADVISED CUSTOMERS BY DOOR HANGERS
02/12/08 12:58 PM	Email notification of unauthorized discharge sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov
	C 7/3 TIL DES COMINGEN, SUV

Report Selections: Treatment Plant: MSD0278 MORRIS FORMAN, Excluding PPI, CSO, Result: WUS, Act Code: DISDW, DISREV

KPDFS # KY0022411 (Cont'd)

Facility ID MSD0278

Treatment Plant Name **MORRIS FORMAN**

Receiving Stream of Treatment Plant OHIO RIVER

Region WEST

Facility Type

SMH Sewer Manhole

Facility ID 17571

Facility Address 3035 CARSON WAY

If Pump Station, Name of Pump Station:

Receiving Stream

Discharge to SOUTH FORK CATCH BASIN

BEARGRASS CREEK

Activity Code / Description DISREV: RAIN EVENT DISCHARGE

WO# 740338

Initiated 02/06/08 01:15 AM

Initiated By BRIGHT

Assigned To BRIGHT

Disch Stat D

Event Date 02/17/00

Problem PUMPED OVERFLOW

Resolution DISCHARGE TO WATERS OF THE

Completed 02/06/08 12:00 PM

Spot Inspections:

Discharge Amount:	838,500 GAL
Cause:	SET PUMPS TO ALLEVIATE PROPERTY DAMAGE AND FLOODING DURING A SIGNIFICANT RAIN EVENT
Clean Up:	MSD PERSONNEL CLEANED AND SANITIZED THE OVERFLOW SITE ONCE THE RAIN SUBSIDED
Control Zone:	MSD PERSONNEL SET OUT BARRICADES AND TEMPORARY SIGNS ON THE PUMPS
Impact:	SEWAGE VISIBLE AROUND PUMPED DISCHARGE SITE
Repair:	THIS LOCATION IS IN THE INTERIM SANITARY SEWER DISCHARGE PLAN

02/06/08 01:15 AM	MSD PERSONNEL PLACED SIGNS	1
02/06/08 12:58 AM	Email notification of unauthorized discharge sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov	and the best of th
	The Local Control of the Control of	

Report Selections: Treatment Plant: MSD0278 MORRIS FORMAN, Excluding PPI, CSO, Result: WUS, Act Code: DISDW, DISREV

KPDES# KY0022411 (Cont'd)

Facility ID MSD0278

Treatment Plant Name MORRIS FORMAN

Receiving Stream of Treatment Plant OHIO RIVER

Region WEST

Facility Type

SMH Sewer Manhole

Facility ID

18471

Facility Address

3107 DELL BROOKE AVE

Pump Station, Name of Pump Station:

Receiving Stream

Discharge to SOUTH FORK CATCH BASIN

BEARGRASS CREEK

US

Activity Code / Description DISREV: RAIN EVENT DISCHARGE

WO# 740349

Initiated 02/06/08 02:10 AM Initiated By BRIGHT

Assigned To BRIGHT

Disch Stat D

Event Date Problem 02/17/00

Resolution PUMPED OVERFLOW

DISCHARGE TO WATERS OF THE

Completed 02/07/08 02:58 AM

Spot Inspections:

Discharge Amount:	2,080,400 GAL
Cause:	SET PUMPS TO ALLEVIATE PROPERTY DAMAGE AND FLOODING DURING A SIGNIFICANT RAIN EVENT
Clean Up:	MSD PERSONNEL CLEANED AND SANITIZED THE OVERFLOW SITE ONCE THE RAIN SUBSIDED
Control Zone:	MSD PERSONNEL SET OUT BARRICADES AND TEMPORARY SIGNS ON THE PUMPS
Impact	SEWAGE VISIBLE AROUND PUMPED DISCHARGE SITE
Repair.	THIS LOCATION IS IN THE INTERIM SANITARY SEWER DISCHARGE PLAN

02/06/08 12:58 AM	Supplemental Email notification of unauthorized discharge has been sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov
02/06/08 02:10 AM	MSD PERSONNEL PLACED SIGNS
02/06/08 12:58 AM	Email notification of unauthorized discharge sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov

Report Selections: Treatment Plant: MSD0278 MORRIS FORMAN, Excluding PPI, CSO, Result: WUS, Act Code: DISDW, DISREV

KPDES # KY0022411 (Cont'd)

Facility ID MSD0278

Treatment Plant Name MORRIS FORMAN

Receiving Stream of Treatment Plant OHIO RIVER

Region WEST

Facility Type SMH Sewer Manhole

Facility ID 18483

Facility Address 3015 BOAIRES LN If Pump Station, Name of Pump Station:

Receiving Stream

BEARGRASS CREEK

US

Discharge to SOUTH FORK CATCH BASIN

Activity Code / Description DISREV: RAIN EVENT DISCHARGE

WO# 740350

Initiated 02/06/08 02:18 AM nitiated By BRIGHT

Assigned To BRIGHT

Disch Stat D

Event Date Problem 02/17/00 PUMPED OVERFLOW

Resolution DISCHARGE TO WATERS OF THE Completed 02/07/08 01:03 AM

Spot Inspections:

Discharge Amount:	1,725,400 GAL
Cause:	SET PUMPS TO ALLEVIATE PROPERTY DAMAGE AND FLOODING DURING A SIGNIFICANT RAIN EVENT
Clean Up:	MSD PERSONNEL CLEANED AND SANITIZED THE OVERFLOW SITE ONCE THE RAIN SUBSIDED
Control Zone:	MSD PERSONNEL SET OUT BARRICADES AND TEMPORARY SIGNS ON THE PUMPS
Impact:	SEWAGE VISIBLE AROUND PUMPED DISCHARGE SITE
Repair.	THIS LOCATION IS IN THE INTERIM SANITARY SEWER DISCHARGE PLAN

1	
02/06/08 12:58 AM	Supplemental Email notification of unauthorized discharge has been sent to ireland sean@epa.gov, eppc,ert@ky.gov and LisaA.Jeffries@ky.gov
02/06/08 02:18 AM	MSD PERSONNEL PLACED SIGNS
02/06/08 12:58 AM	Email notification of unauthorized discharge sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov

Report Selections: Treatment Plant: MSD0278 MORRIS FORMAN, Excluding PPI, CSO, Result: WUS, Act Code: DISDW, DISREV

KPDES #
KY0022411 (Cont'd)

Facility ID MSD0278

Treatment Plant Name MORRIS FORMAN

Receiving Stream of Treatment Plant OHIO RIVER

Region WEST

Activity Code / Description DISREV: RAIN EVENT DISCHARGE

<u>WO#</u> 743412

Initiated 02/12/08 06:13 PM Initiated By BRIGHT

Assigned To D

Disch Stat D

Event Date Problem
02/17/00 PUMPED OVERFLOW

Resolution
DISCHARGE TO
WATERS OF THE

US

Completed 02/13/08 02:10 AM

Spot Inspections:

Discharge Amount:	620,100 GAL
Cause:	SET PUMPS TO ALLEVIATE PROPERTY DAMAGE AND FLOODING DURING A SIGNIFICANT RAIN EVENT
Clean Up:	MSD PERSONNEL CLEANED AND SANITIZED THE OVERFLOW SITE ONCE THE RAIN SUBSIDED
Control Zone:	MSD PERSONNEL SET OUT BARRICADES AND TEMPORARY SIGNS ON THE PUMPS
mpact:	SEWAGE VISIBLE AROUND PUMPED DISCHARGE SITE
Repair.	THIS LOCATION IS IN THE INTERIM SANITARY SEWER DISCHARGE PLAN

Notifications:

T	
02/12/08 12:58 PM	Supplemental Email notification of unauthorized discharge has been sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov
02/12/08 06:13 PM	MSD PERSONNEL PLACED SIGNS
02/12/08 12:58 PM	Email notification of unauthorized discharge sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov
	The state of the s

3/21/2008

Page 10 of 37

5:01:49 PM

Report Selections: Treatment Plant: MSD0278 MORRIS FORMAN, Excluding PPI, CSO, Result: WUS, Act Code: DISDW, DISREV

KPDES # KY0022411 (Cont'd)

Facility ID MSD0278

Treatment Plant Name MORRIS FORMAN

Receiving Stream of Treatment Plant OHIO RIVER

Region WEST

Facility Type

SMH Sewer Manhole

Facility ID

Facility Address

If Pump Station, Name of Pump Station:

Receiving Stream
WEDGEWOOD DITCH

US

Discharge to DITCH

Activity Code / Description DISREV: RAIN EVENT DISCHARGE

WO # 740340 Initiated 02/06/08 01:32 AM Initiated By BRIGHT

3101 WEDGEWOOD WAY

Assigned To BRIGHT Disch Stat D Event Date 02/17/00

Problem PUMPED OVERFLOW

Resolution DISCHARGE TO WATERS OF THE

Completed 02/06/08 11:45 AM

Spot Inspections:

Discharge Amount:	790,400 GAL
Cause:	SET PUMPS TO ALLEVIATE PROPERTY DAMAGE AND FLOODING DURING A SIGNIFICANT RAIN EVENT
Clean Up:	MSD PERSONNEL CLEANED AND SANITIZED THE OVERFLOW SITE ONCE THE RAIN SUBSIDED
Control Zone:	MSD PERSONNEL SET OUT BARRICADES AND TEMPORARY SIGNS ON THE PUMPS
Impact:	SEWAGE VISIBLE AROUND PUMPED DISCHARGE SITE
Repair:	THIS LOCATION IS IN THE INTERIM SANITARY SEWER DISCHARGE PLAN

1			
	02/06/08 01:32 AM	MSD PERSONNEL PLACED SIGNS	parent parent
	02/06/08 12:58 AM	Email notification of unauthorized discharge sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov	

Report Selections: Treatment Plant: MSD0278 MORRIS FORMAN, Excluding PPI, CSO, Result: WUS, Act Code: DISDW, DISREV

KPDES #	
KY0022411	(Cont'd)

Facility ID MSD0278

Treatment Plant Name MORRIS FORMAN

Receiving Stream of Treatment Plant OHIO RIVER

Region WEST

Facility Type
SMH Sewer Manhole

Facility ID 21061

Facility Address
4432 CORDOVA RD

If Pump Station, Name of Pump Station:

Receiving Stream
UPPER SINKING FORK

US

Discharge to CATCH BASIN

Activity Code / Description DISREV: RAIN EVENT DISCHARGE

<u>WO#</u> 740335

Initiated 02/06/08 12:56 AM Initiated By BRIGHT Assigned To BRIGHT

Disch Stat

Event Date 02/17/00

PUMPED OVERFLOW

Resolution DISCHARGE TO WATERS OF THE

Completed 02/07/08 05:40 AM

Spot Inspections:

Discharge Amount:	2,413,600 GAL
Cause:	SET PUMPS TO ALLEVIATE PROPERTY DAMAGE AND FLOODING DURING A SIGNIFICANT RAIN EVENT
Clean Up:	MSD PERSONNEL CLEANED AND SANITIZED THE OVERFLOW SITE ONCE THE RAIN SUBSIDED
Control Zone:	MSD PERSONNEL SET OUT BARRICADES AND TEMPORARY SIGNS ON THE PUMPS
Impact	SEWAGE VISIBLE AROUND PUMPED DISCHARGE SITE
Repair:	THIS LOCATION IS IN THE INTERIM SANITARY SEWER DISCHARGE PLAN

	
02/06/08 12:58 AM	Supplemental Email notification of unauthorized discharge has been sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov
02/06/08 12:56 AM	MSD PERSONNEL PLACED SIGNS
02/06/08 12:58 AM	Email notification of unauthorized discharge sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov
	- Commonwealth and the common and th

Report Selections: Treatment Plant: MSD0278 MORRIS FORMAN, Excluding PPI, CSO, Result: WUS, Act Code: DISDW, DISREV

KPDES # KY0022411 (Cont'd)

Facility ID MSD0278

Treatment Plant Name MORRIS FORMAN

Receiving Stream of Treatment Plant OHIO RIVER

Region WEST

Facility Type

SMH Sewer Manhole

Facility ID 21089

Facility Address 207 BRUNSWICK RD

If Pump Station, Name of Pump Station:

Receiving Stream UPPER SINKING FORK

US

Discharge to CATCH BASIN

Activity Code / Description DISREV: RAIN EVENT DISCHARGE

WO # 740343 Initiated 02/06/08 01:50 AM

Initiated By BRIGHT

Assigned To BRIGHT

Disch Stat ח

Event Date Problem 02/17/00

Resolution PUMPED OVERFLOW

Completed DISCHARGE TO WATERS OF THE

02/07/08 03:15 AM

Spot Inspections:

Discharge Amount:	2,297,700 GAL
Cause:	SET PUMPS TO ALLEVIATE PROPERTY DAMAGE AND FLOODING DURING A SIGNIFICANT RAIN EVENT
Clean Up:	MSD PERSONNEL CLEANED AND SANITIZED THE OVERFLOW SITE ONCE THE RAIN SUBSIDED
Control Zone:	MSD PERSONNEL SET OUT BARRICADES AND TEMPORARY SIGNS ON THE PUMPS
Impact	SEWAGE VISIBLE AROUND PUMPED DISCHARGE SITE
Repair:	THIS LOCATION IS IN THE INTERIM SANITARY SEWER DISCHARGE PLAN

02/06/08 12:58 AM	Supplemental Email notification of unauthorized discharge has been sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov	7
 02/06/08 01:50 AM	MSD PERSONNEL PLACED SIGNS	merin migrae
02/06/08 12:58 AM	Email notification of unauthorized discharge sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov	**************************************
	3,300	

Report Selections: Treatment Plant: MSD0278 MORRIS FORMAN, Excluding PPI, CSO, Result: WUS, Act Code: DISDW, DISREV

KPDES #
KY0022411 (Cont'd)

Facility ID MSD0278

Treatment Plant Name
MORRIS FORMAN

Receiving Stream of Treatment Plant OHIO RIVER

Region WEST

Facility Type
SMH Sewer Manhole

DISCHARGE

Facility ID 21101 Facility Address

if Pump Station, Name of Pump Station:

Receiving Stream

UPPER SINKING FORK

US

Discharge to DITCH

Activity Code / Description
DISREV: RAIN EVENT

WO# 740332

Initiated 02/06/08 12:43 AM Initiated By BRIGHT

4302 SHELBYVILLE RD

Assigned To BRIGHT Disch Stat D Event Date Problem
02/17/00 PUMPED OVERFLOW

Resolution DISCHARGE TO WATERS OF THE

Completed 02/07/08 02:00 PM

Spot Inspections:

Discharge Amount:	3,131,800 GAL
Cause:	SET PUMPS TO ALLEVIATE PROPERTY DAMAGE AND FLOODING DURING A SIGNIFICANT RAIN EVENT
Clean Up:	MSD PERSONNEL CLEANED AND SANITIZED THE OVERFLOW SITE ONCE THE RAIN SUBSIDED
Control Zone:	MSD PERSONNEL SET OUT BARRICADES AND TEMPORARY SIGNS ON THE PUMPS
Impact:	SEWAGE VISIBLE AROUND PUMPED DISCHARGE SITE
Repair:	THIS LOCATION IS IN THE INTERIM SANITARY SEWER DISCHARGE PLAN

**************************************	Market and the second s	
02/05/08 12:58 PM	Supplemental Email notification of unauthorized discharge has been sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov	1
02/06/08 12:43 AM	MSD PERSONNEL PLACED SIGNS	
02/05/08 12:58 PM	Email notification of unauthorized discharge sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov	

Report Selections: Treatment Plant: MSD0278 MORRIS FORMAN, Excluding PPI, CSO, Result: WUS, Act Code: DISDW, DISREV

KPDES #	
KY0022411	(Cont'd)

Facility ID MSD0278

Treatment Plant Name MORRIS FORMAN

Receiving Stream of Treatment Plant OHIO RIVER

Region WEST

Facility Type
SMH Sewer Manhole

Facility ID 21153 Facility Address
4522 CORDOVA RD

If Pump Station, Name of Pump Station:

Receiving Stream
UPPER SINKING FORK

US

Discharge to CATCH BASIN

Activity Code / Description DISREV: RAIN EVENT DISCHARGE

<u>WO #</u> 740339 Initiated 02/06/08 01:27 AM Initiated By BRIGHT

Assigned To BRIGHT Disch Stat

Event Date 02/17/00

Problem.
PUMPED OVERFLOW

Resolution DISCHARGE TO WATERS OF THE Completed 02/07/08 06:29 AM

Spot Inspections:

Discharge Amount:	2,438,800 GAL	
Cause:	SET PUMPS TO ALLEVIATE PROPERTY DAMAGE AND FLOODING DURING A SIGNIFICANT RAIN EVENT	
Clean Up:	MSD PERSONNEL CLEANED AND SANITIZED THE OVERFLOW SITE ONCE THE RAIN SUBSIDED	
Control Zone:	MSD PERSONNEL SET OUT BARRICADES AND TEMPORARY SIGNS ON THE PUMPS	
Impact	SEWAGE VISIBLE AROUND PUMPED DISCHARGE SITE	
Repair:	THIS LOCATION IS IN THE INTERIM SANITARY SEWER DISCHARGE PLAN	

02/06/08 12:58 AM	Supplemental Email notification of unauthorized discharge has been sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov	-
02/06/08 01:27 AM	MSD PERSONNEL PLACED SIGNS	-
02/06/08 12:58 AM	Email notification of unauthorized discharge sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov	-
		1

Report Selections: Treatment Plant: MSD0278 MORRIS FORMAN, Excluding PPI, CSO, Result: WUS, Act Code: DISDW, DISREV

KPDES# KY0022411 (Cont'd)

Facility ID MSD0278

Treatment Plant Name MORRIS FORMAN

Receiving Stream of Treatment Plant **OHIO RIVER**

Region WEST

Facility Type

SMH Sewer Manhole

Facility ID 21156

Facility Address

4601 STONEHENGE DR

If Pump Station, Name of Pump Station:

Receiving Stream

Discharge to UPPER SINKING FORK CATCH BASIN

Activity Code / Description DISREV: RAIN EVENT DISCHARGE

WO# 740341 Initiated 02/06/08 01:40 AM

Initiated By BRIGHT

Assigned To BRIGHT

Disch Stat D

Event Date 02/17/00

<u>Problem</u> PUMPED OVERFLOW

Resolution DISCHARGE TO WATERS OF THE US

Completed 02/07/08 06:56 AM

Spot Inspections:

Discharge Amount	2,792,000 GAL
Cause:	SET PUMPS TO ALLEVIATE PROPERTY DAMAGE AND FLOODING DURING A SIGNIFICANT RAIN EVENT
Clean Up:	MSD PERSONNEL CLEANED AND SANITIZED THE OVERFLOW SITE ONCE THE RAIN SUBSIDED
Control Zone:	MSD PERSONNEL SET OUT BARRICADES AND TEMPORARY SIGNS ON THE PUMPS
Impact	SEWAGE VISIBLE AROUND PUMPED DISCHARGE SITE
Repair:	THIS LOCATION IS IN THE INTERIM SANITARY SEWER DISCHARGE PLAN

02/06/08 12:58 AM	Supplemental Email notification of unauthorized discharge has been sent to ireland sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov	gun
02/06/08 01:40 AM	MSD PERSONNEL PLACED SIGNS	
02/06/08 12:58 AM	Email notification of unauthorized discharge sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov	androne a secondario
		1

Report Selections: Treatment Plant: MSD0278 MORRIS FORMAN, Excluding PPI, CSO, Result: WUS, Act Code: DISDW, DISREV

KPDES# KY0022411 (Cont'd)

Facility ID MSD0278

Treatment Plant Name **MORRIS FORMAN**

Receiving Stream of Treatment Plant **OHIO RIVER**

Region WEST

Facility Type

SMH Sewer Manhole

Facility ID 21506

Facility Address 901 FALGATE CT

If Pump Station, Name of Pump Station:

Receiving Stream BEARGRASS CREEK

US

Discharge to MUDDY FORK CATCH BASIN

Activity Code / Description DISREV: RAIN EVENT DISCHARGE

WO# 740524 Initiated 02/06/08 11:05 AM Initiated By BRIGHT

Assigned To BRIGHT

Disch Stat ח

Event Date Problem 02/17/00 PUMPED OVERFLOW

Resolution DISCHARGE TO WATERS OF THE Completed 02/07/08 11:37 AM

Spot Inspections:

Discharge Amount:	1,913,600 GAL
Cause:	SET PUMPS TO ALLEVIATE PROPERTY DAMAGE AND FLOODING DURING A SIGNIFICANT RAIN EVENT
Clean Up:	MSD PERSONNEL CLEANED AND SANITIZED THE OVERFLOW SITE ONCE THE RAIN SUBSIDED
Control Zone:	MSD PERSONNEL SET OUT BARRICADES AND TEMPORARY SIGNS ON THE PUMPS
Impact:	SEWAGE VISIBLE AROUND PUMPED DISCHARGE SITE
Repair:	THIS LOCATION IS IN THE INTERIM SANITARY SEWER DISCHARGE PLAN

02/06/08 12:58 AM	Supplemental Email notification of unauthorized discharge has been sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov
02/06/08 11:05 AM	MSD PERSONNEL PLACED SIGNS
02/06/08 12:58 AM	Email notification of unauthorized discharge sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov

Report Selections: Treatment Plant: MSD0278 MORRIS FORMAN, Excluding PPI, CSO, Result: WUS, Act Code: DISDW, DISREV

KPDES#	
KY0022411	(Confd)

Facility ID MSD0278

Treatment Plant Name MORRIS FORMAN

Receiving Stream of Treatment Plant OHIO RIVER

Region WEST

Facility Type

SMH Sewer Manhole

Facility ID 21628-W

Facility Address

7404 ARROWWOOD RD

If Pump Station, Name of Pump Station:

Receiving Stream
GOOSE CREEK

Discharge to DITCH

Activity Code / Description DISREV: RAIN EVENT DISCHARGE **WO #** 740393

Initiated 02/06/08 05:30 AM

Initiated By MARKS JR

Assigned To DUNN JR Disch Stat D 12/16/00

Problem
LACK OF SYSTEM
CAPACITY

Resolution DISCHARGE TO WATERS OF THE US

Completed 02/06/08 12:00 PM

Spot Inspections:

Discharge Amount:	682,500 GAL	
Cause:	LACK OF SYSTEM CAPACITY	
Clean Up:	AREA CLEANED AND SANITIZED DEBRIS REMOVED	
Control Zone:	TEMP SIGNS POSTED AND AREA WAS TAPED OFF.	
Impact	DISCOLORATION OF STREAM AND SOME DEBRIS	
Repair	WILL HAUL TO PREVENT DISCHARGE	_

The state of the s	
02/06/08 12:58 AM	Supplemental Email notification of unauthorized discharge has been sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov
02/06/08 08:26 AM	Temporary signs posted and area taped off
02/06/08 12:58 AM	Email notification of unauthorized discharge sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov

Report Selections: Treatment Plant: MSD0278 MORRIS FORMAN, Excluding PPI, CSO, Result: WUS, Act Code: DISDW, DISREV

KPDES #	
KY0022411	(Cont'd)

Facility ID MSD0278

Treatment Plant Name MORRIS FORMAN

Receiving Stream of Treatment Plant OHIO RIVER

Region WEST

Facility Type

Facility ID

Facility Address

If Pump Station, Name of Pump Station:

Receiving Stream

Discharge to

Completed

SMH Sewer Manhole

25012

4641 BEAVER RD

UPPER SINKING FORK

DITCH

Activity Code / Description DISREV: RAIN EVENT DISCHARGE

WO# 740693 Initiated 02/06/08 11:24 AM

Initiated By GRIFFITH

Assigned To GRIFFITH

Disch Stat D

Event Date 05/28/04

<u>Problem</u> Resolution LACK OF SYSTEM DISCHARGE TO CAPACITY

WATERS OF THE US

02/06/08 02:45 PM

Spot Inspections:

Discharge Amount:	900 GAL
Cause:	LACK OF SYSTEM CAPACITY - HEAVY RAIN
Clean Up:	CLEAN UP IS NEEDED
Control Zone:	TEMPORARY SIGNS, CONES AND DOOR HANGERS HAVE BEEN POSTED
Impact:	SEWAGE AND DEBRIS FOUND ON THE GROUND
Repair:	THIS LOCATION IS IN THE SANITARY SEWER DISCHARGE PLAN TO BE SUBMITTED BY DEC. 31, 2008

02/06/08 12:58 PM	Supplemental Email notification of unauthorized discharge has been sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov
02/06/08 11:24 AM	ADVISED CUSTOMERS BY TEMP, SIGNS, DOOR HANGARS AND CONES
02/06/08 12:58 PM	Email notification of unauthorized discharge sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaAJeffries@ky.gov

Report Selections: Treatment Plant: MSD0278 MORRIS FORMAN, Excluding PPI, CSO, Result: WUS, Act Code: DISDW, DISREV

KPDES#	
KY0022411	(Confd)

Facility ID MSD0278

Treatment Plant Name MORRIS FORMAN

Receiving Stream of Treatment Plant OHIO RIVER

Region WEST

Facility Type

SMH Sewer Manhole

Facility ID 27005

Facility Address 1012 ALTA CIR

If Pump Station, Name of Pump Station:

Receiving Stream

Discharge to MIDDLE FORK GROUND

BEARGRASS CREEK

Activity Code / Description DISREV: RAIN EVENT DISCHARGE

WO# 740424 Initiated

Initiated By 02/06/08 02:25 AM **GRIFFITH**

Assigned To GRIFFITH

Disch Stat ח

Event Date 09/02/03

Problem LACK OF SYSTEM CAPACITY

Resolution DISCHARGE TO WATERS OF THE

บร

Completed 02/07/08 06:20 PM

Spot Inspections:

Discharge Amount:	432,000 GAL
Cause:	LACK OF SYSTEM CAPACITY - HEAVY RAIN
Clean Up:	A DISCLN WORK ORDER HAS BEEN CREATED FOR IFP TO COMPLETE THIS WORK
Control Zone:	PERMANENT SIGNS HAVE BEEN POSTED
Impact:	SOLIDS AND DEBRIS OBSERVED ON GROUND, CLEAN UP REQUIRED
Repair.	THIS LOCATION WILL BE IN THE SANITARY SEWER DISCHARGE PLAN TO BE SUBMITTED BY DEC. 31, 2008

02/06/08 12:58 AM	Supplemental Email notification of unauthorized discharge has been sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov
02/06/08 12:58 AM	Email notification of unauthorized discharge sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov
02/06/08 02:25 AM	ADVISED CUSTOMERS BY PERMANENT SIGNS

Report Selections: Treatment Plant: MSD0278 MORRIS FORMAN, Excluding PPI, CSO, Result: WUS, Act Code: DISDW, DISREV

KPDES # KY0022411 (Cont'd)

Facility ID MSD0278

Treatment Plant Name MORRIS FORMAN

Receiving Stream of Treatment Plant OHIO RIVER

Region WEST

Activity Code / Description DISREV: RAIN EVENT DISCHARGE

WO# 743364 Initiated 02/12/08 01:17 PM Initiated By

Assigned To GRIFFITH

Disch Stat

Event Date 09/02/03 Problem LACK OF SYSTEM CAPACITY

Resolution DISCHARGE TO WATERS OF THE US Completed 02/13/08 11:00 AM

Spot Inspections:

Discharge Amount:	9,000 GAL
Cause:	LACK OF SYSTEM CAPACITY - HEAVY RAIN
Clean Up:	NO CLEAN UP NEEDED
Control Zone:	PERMANENT SIGNS POSTED
Impact	NO IMPACT OBSERVED
Repair:	THIS LOCATION WILL BE IN THE SANITARY SEWER DISCHARGE PLAN TO BE SUBMITTED BY DEC. 31, 2008

02/12/08 12:58 PM	Supplemental Email notification of unauthorized discharge has been sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov
02/12/08 01:17 PM	ADVISED CUSTOMERS BY PERMANENT SIGNS
02/12/08 12:58 PM	Email notification of unauthorized discharge sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov
	3,7,3,3

Report Selections: Treatment Plant: MSD0278 MORRIS FORMAN, Excluding PPI, CSO. Result: WUS. Act Code: DISDW, DISREV

KPDFS # KY0022411 (Cont'd)

Facility ID MSD0278

Treatment Plant Name **MORRIS FORMAN**

Receiving Stream of Treatment Plant OHIO RIVER

Region WEST

Facility Type

SMH Sewer Manhole

Facility ID

Facility Address

if Pump Station, Name of Pump Station:

Receiving Stream

Discharge to

40872

2105 INDIAN HILLS TRU

MUDDY FORK BEARGRASS CREEK GROUND

Activity Code / Description DISREV: RAIN EVENT DISCHARGE

WO# 740575 Initiated 02/06/08 09:45 AM

Initiated By MARKS JR

Assigned To KUSTES

Disch Stat D

Event Date 12/15/07

Problem LACK OF SYSTEM CAPACITY

Resolution DISCHARGE TO WATERS OF THE Completed 02/06/08 03:40 PM

US

Spot Inspections:

Discharge Amount:	5,400 GAL	
Cause:	STORM FLOW CAUSED LACK OF SYSTEM CAPACITY	
Clean Up:	AREA CLEANED AND SANITIZED DEBRI WAS REMOVED	
Control Zone:	TEMP SIGNS POSTED AND AREA TAPED OFF	
Impact:	SOME DEBRI AND SLIGHT STREAM DISCOLORAZTION	
Repair.	HAULING TO PREVENT DISCHARGE	

02/06/08 12:58 AM	Supplemental Email notification of unauthorized discharge has been sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov	-
	Email notification of unauthorized discharge sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov	more despessed and
		ş

Report Selections: Treatment Plant: MSD0278 MORRIS FORMAN, Excluding PPI, CSO, Result: WUS, Act Code: DISDW, DISREV

KPDES #
KY0022411 (Cont'd)

Facility ID MSD0278

Treatment Plant Name MORRIS FORMAN

Receiving Stream of Treatment Plant OHIO RIVER

Region WEST

Facility Type

SMH Sewer Manhole

Facility ID 45835 Facility Address

If Pump Station, Name of Pump Station:

Receiving Stream

Discharge to

1132 ROSTREVOR CIR

rump station, name or rump station:

MIDDLE FORK

GROUND

BEARGRASS CREEK

Activity Code / Description

DISREV: RAIN EVENT DISCHARGE WO# 740421 Initiated 02/06/08 02:05 AM Initiated By GRIFFITH Assigned To GRIFFITH Disch Stat D Event Date P

Problem

LACK OF SYSTEM

CAPACITY

Resolution DISCHARGE TO WATERS OF THE US Completed 02/07/08 06:15 PM

Spot Inspections:

Discharge Amount:	432,000 GAL
Cause:	LACK OF SYSTEM CAPACITY - HEAVY RAIN
СІеал Up:	CLEAN UP NEEDED
Control Zone:	PERMANENT SIGNS HAVE BEEN POSTED
Impact	SEWAGE AND DEBRIS FOUND ON THE GROUND
Repair:	THIS LOCATION WILL BE IN THE SANITARY SEWER DISCHARGE PLAN TO BE SUBMITTED BY DEC. 31, 2008

02/06/08 12:58 AM	Supplemental Email notification of unauthorized discharge has been sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov
02/06/08 12:58 AM	Email notification of unauthorized discharge sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov
02/06/08 02:05 AM	ADVISED CUSTOMERS BY PERMANENT SIGNS

Report Selections: Treatment Plant: MSD0278 MORRIS FORMAN, Excluding PPI, CSO, Result: WUS, Act Code: DISDW, DISREV

KPDES #	
KY0022411	(Cont'd)

Facility ID MSD0278

Treatment Plant Name MORRIS FORMAN

Receiving Stream of Treatment Plant OHIO RIVER

Region WEST

Facility Type
SMH Sewer Manhole

Facility ID 47583 Facility Address
202 OXMOOR LN

If Pump Station, Name of Pump Station:

Receiving Stream

Discharge to STREAM

MIDDLE FORK BEARGRASS CREEK

uş

Activity Code / Description DISREV: RAIN EVENT DISCHARGE WO# 740696

Initiated 02/06/08 11:41 AM Initiated By GRIFFITH Assigned To GRIFFITH

Disch Stat

Event Date Pr

Problem
LACK OF SYSTEM
CAPACITY

Resolution DISCHARGE TO WATERS OF THE Completed 02/07/08 06:35 PM

Spot Inspections:

Discharge Amount:	117,120 GAL
Cause:	LACK OF SYSTEM CAPACITY - HEAVY RAIN
Clean Up:	A DISCLN WORK ORDER HAS BEEN CREATED FOR IFP TO COMPLETE THIS WORK
Control Zone:	NO CONTROL ZONE REQUIRED AT THIS LOCATION
Impact:	SEWAGE OBSERVED IN STREAM
Repair.	THIS LOCATION IS IN THE SANITARY SEWER DISCHARGE PLAN TO BE SUBMITTED BY DEC. 31, 2008

02/06/08 12:58 PM	Supplemental Email notification of unauthorized discharge has been sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov
02/06/08 11:42 AM	PERMANENT SIGNS POSTED ALONG CREEK
02/06/08 12:58 PM	Email notification of unauthorized discharge sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov

Report Selections: Treatment Plant: MSD0278 MORRIS FORMAN, Excluding PPI, CSO, Result: WUS, Act Code: DISDW, DISREV

KPDES#	
KY0022411	(Cont'd)

Facility ID

Treatment Plant Name MORRIS FORMAN

Receiving Stream of Treatment Plant OHIO RIVER

Region WEST

Facility Type

SMH Sewer Manhole

Facility ID 49647

Facility Address
4315 PRUITT CT

If Pump Station, Name of Pump Station:

Receiving Stream

SOUTH FORK

Discharge to GROUND

BEARGRASS CREEK

Activity Code / Description
DISREV: RAIN EVENT
DISCHARGE

<u>WO #</u> 740651 Initiated 02/06/08 01:25 AM Initiated By GRIFFITH Assigned To GRIFFITH

Disch Stat

11/29/01

Problem LACK OF SYSTEM CAPACITY

Resolution DISCHARGE TO WATERS OF THE US

Completed 02/06/08 07:15 AM

Spot Inspections:

Discharge Amount:	1,800 GAL
Cause:	LACK OF SYSTEM CAPACITY - HEAVY RAIN
Clean Up:	A DISCLN WORK ORDER HAS BEEN CREATED FOR IFP TO COMPLETE THIS WORK
Control Zone:	DOOR HANGERS WERE POSTED
Impact	SEWAGE AND DEBRIS FOUND ON THE GROUND
Reраіг.	THIS LOCATION WILL BE IN THE SANITARY SEWER DISCHARGE PLAN TO BE SUBMITTED BY DEC. 31, 2008

02/06/08 12:58 PM	Supplemental Email notification of unauthorized discharge has been sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov	green
02/06/08 01:25 PM	ADVISED CUSTOMERS BY DOOR HANGERS	**************************************
02/06/08 12:58 PM	Email notification of unauthorized discharge sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov	and the second second
		i

Report Selections: Treatment Plant: MSD0278 MORRIS FORMAN, Excluding PPI, CSO, Result: WUS, Act Code: DISDW, DISREV

KPDES#	
KY0022411	(Cont'd)

Facility ID MSD0278

Treatment Plant Name MORRIS FORMAN

Receiving Stream of Treatment Plant OHIO RIVER

Region WEST

Facility Type

DISCHARGE

SMH Sewer Manhole

Activity Code / Description

DISDW: DRY WEATHER

Facility ID 51200-W

WO#

744451

Facility Address
3337 NEWBURG RD

If Pump Station, Name of Pump Station:

Receiving Stream

SOUTH FORK
BEARGRASS CREEK

Discharge to CATCH BASIN

Initiated 02/18/08 12:45 PM Initiated By RICHARDSO Assigned To RICHARDSO N

Disch Stat R Event Date Problem 02/18/08 OBSTRU

OBSTRUCTION-NOT GREASE / ROOTS Resolution
DISCHARGE TO

Completed 02/18/08 01:45 PM

WATERS OF THE US

Spot Inspections:

Discharge Amount:	4 GAL
Cause:	PROBLEM WITH THE PUMP STATION
Clean Up:	MSD PERSONNEL CLEANED AND SANITIZED THE IMPACTED AREA
Control Zone:	ADVISED CUSTOMER TO AVOID DIRECT CONTACT WITH SEWAGE
Impact:	SEWAGE COMING FROM THE MSD MANHOLE AND FLOWING TO CATCH BASIN
Repair.	MSD PERSONNEL (OPERATIONS) REPAIRED THE PUMP STATION AND NOW THE MAIN SEWER IS FLOWING FINE

	
02/18/08 12:45 PM	ADVISED CUSTOMER BY DOORCARDS AND POSTED SIGNS
02/18/08 12:58 PM	Email notification of unauthorized discharge sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov

Report Selections: Treatment Plant: MSD0278 MORRIS FORMAN, Excluding PPI, CSO, Result: WUS, Act Code: DISDW, DISREV

KPDES # KY0022411 (Cont'd)

Facility ID MSD0278 Treatment Plant Name MORRIS FORMAN

Receiving Stream of Treatment Plant OHIO RIVER

Region WEST

Facility Type

SMH Sewer Manhole

Facility ID

Facility Address
4315 PRUITT CT

If Pump Station, Name of Pump Station:

Receiving Stream

SOUTH FORK BEARGRASS CREEK Discharge to GROUND

BEAR

Activity Code / Description DISREV: RAIN EVENT DISCHARGE WO# 740654

Initiated 02/06/08 01:27 AM Initiated By GRIFFITH Assigned To GRIFFITH Disch Stat

Event Date 02/17/00

Problem

LACK OF SYSTEM

CAPACITY

Resolution DISCHARGE TO WATERS OF THE

Completed 02/06/08 07:05 AM

Spot Inspections:

Discharge Amount:	1,800 GAL
Cause:	LACK OF SYSTEM CAPACITY - HEAVY RAIN
Clean Up:	CLEAN IS NEEDED
Control Zone:	DOOR HANGERS WAS POSTED
Impact	SEWAGE AND DEBRIS FOUND ON THE GROUND
Repair:	THIS LOCATION WILL BE IN THE SANITARY DISCHARGE PLAN TO BE SUBMITTED BY DEC. 31, 2008

02/06/08 12:58 PM	Supplemental Email notification of unauthorized discharge has been sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov
02/06/08 01:26 PM	ADVISED CUSTOMERS BY DOOR HANGERS
02/06/08 12:58 PM	Email notification of unauthorized discharge sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov

Report Selections: Treatment Plant: MSD0278 MORRIS FORMAN, Excluding PPI, CSO, Result: WUS, Act Code: DISDW, DISREV

KPDES # KY0022411 (Cont'd)

Facility ID MSD0278

Treatment Plant Name MORRIS FORMAN

Receiving Stream of Treatment Plant OHIO RIVER

Region WEST

Facility Type

SMH Sewer Manhole

Facility ID 72571-X

Facility Address

4600 CHAMPIONS TRACE IN

If Pump Station, Name of Pump Station:

Receiving Stream

SOUTH FORK

Discharge to STREAM

BEARGRASS CREEK

Activity Code / Description DISREV: RAIN EVENT DISCHARGE

WO # 740328

Initiated 02/05/08 10:52 PM

Initiated Bv GRIFFITH Assigned To GRIFFITH Disch Stat

Event Date 11/29/01 Problem LACK OF SYSTEM CAPACITY Resolution DISCHARGE TO WATERS OF THE

HS

Completed 02/08/08 11:58 AM

Spot Inspections:

Discharge Amount:	1,200,000 GAL
Cause:	LACK OF SYSTEM CAPACITY - HEAVY RAIN
Clean Up:	NONE POSSIBLE DUE TO MAGNITUDE OF STORM
Control Zone:	NO CONTROL ZONE NEEDED
Impact:	NO IMPACT OBSERVED
Repair	THIS LOCATION WILL BE IN THE INTERIM SANITARY SEWER DISCHARGE PLAN

}	
02/05/08 12:58 PM	Supplemental Email notification of unauthorized discharge has been sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov
02/05/08 10:52 PM	ADVISED CUSTOMERS WITH PERMNANET SIGNS
02/05/08 12:58 PM	Ernail notification of unauthorized discharge sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov

Report Selections: Treatment Plant: MSD0278 MORRIS FORMAN, Excluding PPI, CSO, Result: WUS, Act Code: DISDW, DISREV

KPDES #
KY0022411 (Cont'd)

Facility ID MSD0278

Treatment Plant Name MORRIS FORMAN

Receiving Stream of Treatment Plant OHIO RIVER

Region WEST

Activity Code / Description
DISREV: RAIN EVENT
DISCHARGE

<u>WO #</u> 743421 Initiated 02/12/08 07:34 PM

Initiated By LASLEY JR Assigned To GRIFFITH <u>Disch Stat</u> D Event Date 11/29/01

Problem LACK OF SYSTEM CAPACITY Resolution DISCHARGE TO WATERS OF THE US

Completed 02/13/08 11:54 PM

Spot Inspections:

Discharge Amount:	29,119 GAL	***************************************
Cause:	LACK OF SYSTEM CAPACITY - HEAVY RAIN	
Clean Up:	CLEAN UP NEEDED	
Control Zone:	PERMANENT SIGNS POSTED	
Impact	NO IMPACT OBSERVED	
Repair.	THIS LOCATION IS IN THE INTERIM SANITARY SEWER DISCHARGE PLAN	Bernard (

02/12/08 12:58 PM	Supplemental Email notification of unauthorized discharge has been sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov
02/12/08 07:34 PM	ADVISED CUSTOMERS BY PERMANENT SIGNS
02/12/08 12:58 PM	Email notification of unauthorized discharge sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov

Report Selections: Treatment Plant: MSD0278 MORRIS FORMAN, Excluding PPI, CSO, Result: WUS, Act Code: DISDW, DISREV

KPDES# KY0022411 (Cont'd)

Facility ID MSD0278

Treatment Plant Name **MORRIS FORMAN**

Receiving Stream of Treatment Plant OHIO RIVER

Region WEST

Facility Type

SLS Sewer Lift Station

Facility ID MSD0012-PS

Facility Address

3246 RADIANCE RD

If Pump Station, Name of Pump Station:

HIGHGATE SPRINGS

Receiving Stream

SOUTH FORK BEARGRASS CREEK

us

Discharge to STREAM

Activity Code / Description DISREV: RAIN EVENT DISCHARGE

WO# 740191

Initiated

02/05/08 12:35 PM

Initiated By SINGLETON Assigned To PORTER JR

Disch Stat Event Date D 12/16/00

Problem

LACK OF SYSTEM CAPACITY

Resolution DISCHARGE TO

Completed 02/08/08 12:00 PM WATERS OF THE

Spot Inspections:

Discharge Amount:	5,566,980 GAL
Cause;	LACK OF SYSTEM CAPACITY
Clean Up:	CLEAN UP NOT POSSIBLE DUE TO ELEVATED CREEK LEVEL
Control Zone:	TEMPORARY SIGNS POSTED
Impact:	NONE NOTICED BY MSD PERSONNEL WATER WASHED AWAY DUE TO ELEVATED CREEK LEVEL.
Repair:	THIS LOCATION IS IN THE INTERIM SANITARY SEWER DISCHARGE PLAN

02/05/08 12:58 PM	Supplemental Email notification of unauthorized discharge has been sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov	
02/05/08 01:24 PM	Temporary signs posted	-
02/05/08 12:58 PM	Email notification of unauthorized discharge sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov	-
02/05/08 12:58 PM		

Report Selections: Treatment Plant: MSD0278 MORRIS FORMAN, Excluding PPI, CSO, Result: WUS, Act Code: DISDW, DISREV

KPDES # KY0022411 (Cont'd)

Facility ID MSD0278

Treatment Plant Name MORRIS FORMAN

Receiving Stream of Treatment Plant OHIO RIVER

Region WEST

Activity Code / Description
DISREV: RAIN EVENT
DISCHARGE

<u>WO #</u> 743358 Initiated 02/12/08 01:00 PM Initiated By MARKS JR Assigned To PORTER JR Disch Stat

Event Date 12/16/00

Problem

LACK OF SYSTEM

CAPACITY

Resolution DISCHARGE TO WATERS OF THE US Completed 02/13/08 06:00 PM

Spot Inspections:

Discharge Amount:	1,469,400 GAL
Cause:	LACK OF SYSTEM CAPACITY
Clean Up:	MSD PERSONNEL CLEANED AND SANITIZED THE AREA
Control Zone:	AREA TAPED OFF AND TEMPORARY SIGNS POSTED
Impact	NO IMPACT OBSERVED
Repair:	THIS LOCATION IS IN THE INTERIM SANITARY SEWER DISCHARGE PLAN

02/12/08 12:58 PM	Supplemental Email notification of unauthorized discharge has been sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov
02/12/08 02:32 PM	Area taped off, temporary signs posted
02/12/08 12:58 PM	Email notification of unauthorized discharge sent to ireland.sean@epa.gov, eppc.en@ky.gov and LisaA.Jeffries@ky.gov

Report Selections: Treatment Plant: MSD0278 MORRIS FORMAN, Excluding PPI, CSO, Result: WUS, Act Code: DISDW, DISREV

KPDES #
KY0022411 (Cont'd)

Facility ID MSD0278 Treatment Plant Name MORRIS FORMAN

Receiving Stream of Treatment Plant OHIO RIVER

Region WEST

Activity Code / Description DISREV: RAIN EVENT

DISCHARGE

<u>WO #</u> 744225 Initiated 02/16/08 12:00 PM Initiated By ELDER Assigned To PORTER JR Disch Stat Event Date
D 12/16/00

Problem

LACK OF SYSTEM

CAPACITY

Resolution DISCHARGE TO WATERS OF THE US Completed 02/16/08 04:00 PM

Spot inspections:

Discharge Amount:	183,000 GAL
Cause:	SNOW MELT FROM REV 02/12/2008
Clean Up:	CLEANUP NOT POSSIBLE DUE TO ELEVATED CREEK LEVEL.
Control Zone:	PERMANENT SIGNS INSTALLED
Impact:	NOT OBSERVED BY MSD PERSONNEL
Repair:	THIS LOCATION IS IN THE INTERIM SANITARY SEWER DISCHARGE PLAN

02/16/08 12:00 PM	PERMANENT SIGNS POSTED	7
03/10/08 04:52 PM	Email notification of unauthorized discharge sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov	***************************************

Report Selections: Treatment Plant: MSD0278 MORRIS FORMAN, Excluding PPI, CSO, Result: WUS, Act Code: DISDW, DISREV

KPDES # KY0022411 (Cont'd)

Facility ID

Treatment Plant Name MORRIS FORMAN

Receiving Stream of Treatment Plant OHIO RIVER

Region WEST

Activity Code / Description DISREV: RAIN EVENT DISCHARGE

WO# 744227 Initiated 02/17/08 12:15 PM

initiated By ELDER Assigned To PORTER JR Disch Stat

Event Date 12/16/00

Problem LACK OF SYSTEM CAPACITY

Resolution DISCHARGE TO WATERS OF THE US Completed 02/17/08 08:00 PM

Spot Inspections:

Discharge Amount:	130,200 GAL	
Cause:	RAIN EVENT 02/17/2007 & SNOW MELT FROM 02/12/2008	
Clean Up:	CLEANUP NOT POSSIBLE DUE TO ELEVATED CREEK LEVEL	
Control Zone:	PERMANENT SIGNS POSTED	TOTAL
Impact	NON OBSERVED BY MSD PERSONNEL	
Repair:	THIS LOCATION IS IN THE INTERIM SANITARY SEWER DISCHARGE PLAN	

Notifications:

02/17/08 12:58 PM	Supplemental Email notification of unauthorized discharge has been sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov
02/17/08 12:58 PM	Email notification of unauthorized discharge sent to ireland sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov
02/18/08 07:23 AM	Permanent signs posted around area

3/21/2008

Page 33 of 37

5:01:49 PM

Report Selections: Treatment Plant: MSD0278 MORRIS FORMAN, Excluding PPI, CSO, Result: WUS, Act Code: DISDW, DISREV

KPDES# KY0022411 (Cont'd)

Facility ID MSD0278

Treatment Plant Name MORRIS FORMAN

Receiving Stream of Treatment Plant **OHIO RIVER**

Region WEST

Facility Type

SLS Sewer Lift Station

Facility ID

MSD0023-PS

Facility Address

501 MOCKINGBIRD VALLEY RD

If Pump Station, Name of Pump Station:

MELLWOOD AVENUE

Receiving Stream

MUDDY FORK

Discharge to STREAM

Completed

02/06/08 09:55 PM

BEARGRASS CREEK

Activity Code / Description DISREV: RAIN EVENT DISCHARGE

WO# 740415

Initiated 02/06/08 08:30 AM

Initiated By MARKS JR

Assigned To COOMER

Disch Stat D

Event Date 01/02/04

<u>Problem</u> LACK OF SYSTEM CAPACITY

Resolution DISCHARGE TO WATERS OF THE

US

Spot Inspections:

Discharge Amount:	120,750 GAL
Cause:	LACK OF SYSTEM CAPACITY
Clean Up:	AREA CLEANED AND SANITIZED AND DEBRIS REMOVED
Control Zone:	TEMP SIGNS POSTED AND AREA TAPED OFF
Impact	DISCOLORATION OF STREAM AND SOME DEBRIS
Repair:	HAULING TO PREVENT DISCHARGE

1		
02/06/08 12:58 AM	Supplemental Email notification of unauthorized discharge has been sent to ireland,sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov	
02/06/08 09:07 AM	Temporary signs posted and area taped off	
02/06/08 12:58 AM	Email notification of unauthorized discharge sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov	
	6.13	

Report Selections: Treatment Plant: MSD0278 MORRIS FORMAN, Excluding PPI, CSO, Result: WUS, Act Code: DISDW, DISREV

KPDES# KY0022411 (Cont'd)

Facility ID MSD0278

Treatment Plant Name MORRIS FORMAN

Receiving Stream of Treatment Plant **OHIO RIVER**

Region WEST

Facility Type

Facility ID SLS Sewer Lift Station MSD0082-PS Facility Address 816 N 34TH ST

If Pump Station, Name of Pump Station: 34TH STREET

Receiving Stream OHIO RIVER

Discharge to GROUND

Activity Code / Description DISDW: DRY WEATHER DISCHARGE

W0# 742855 Initiated 02/08/08 01:45 PM

Initiated By COWARD

Assigned To HUMPHREY

Disch Stat R

Event Date 01/19/01

Problem PUMPED DUE TO COE MANUAL

Resolution DISCHARGE TO WATERS OF THE US

Completed 02/12/08 08:00 AM

Spot Inspections:

Discharge Amount:	7,600,000 GAL
Cause:	STATION PLACED IN IDLE MODE PER USACE PROTOCOL DURING ELEVATED RIVER LEVELS
Clean Up:	NO CLEAN UP PERFORMED - PIPES DISCHARGE UNDERWATER, DIRECTLY INTO RIVER
Control Zone:	NO CONTROL ZONE SET UP - PIPES DISCHARGE UNDERWATER, DIRECTLY INTO RIVER
Impact	NONE OBSERVED - OUTLETS SUBMERGED
Repair:	IN COMPLIANCE WITH USACE FLOOD PUMPING PROTOCOLS

02/08/08 12:58 PM	Supplemental Email notification of unauthorized discharge has been seet to be a
02/08/08 02:01 PM	Supplemental Email notification of unauthorized discharge has been sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov Given by voluntary email notification system
02/08/08 12:58 PM	Email notification of unauthorized discharge sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov
	O 7 - 3 - 1 - FFELON (@.K.), gov and LisaA, Jefffies (@.K.), gov

Report Selections: Treatment Plant: MSD0278 MORRIS FORMAN, Excluding PPI, CSO, Result: WUS, Act Code: DISDW, DISREV

KPDES#	
KY0022411	(Cont'd)

Facility ID MSD0278

Treatment Plant Name MORRIS FORMAN

Receiving Stream of Treatment Plant OHIO RIVER

Region WEST

Facility Type

SLS Sewer Lift Station

Facility ID MSD0087-PS

Facility Address 342 W MAIN ST

If Pump Station, Name of Pump Station:

Receiving Stream
OHIO RIVER

Discharge to GROUND

Activity Code / Description DISDW: DRY WEATHER DISCHARGE

WO # 742833 initiated 02/07/08 11:21 PM

Initiated By COWARD Assigned To HUMPHREY

Disch Stat

4TH STREET

Event Date 02/07/08

Problem
PUMPED DUE TO COE
MANUAL

Resolution DISCHARGE TO WATERS OF THE US

Completed 02/12/08 07:00 PM

Spot Inspections:

9,200,000 GAL
STATION PLACED IN IDLE MODE PER USACE PROTOCOL DURING ELEVATED RIVER LEVELS
NO CLEAN UP PERFORMED - PIPES DISCHARGE UNDERWATER, DIRECTLY INTO RIVER
NO CONTROL ZONE SET UP - PIPES DISCHARGE UNDERWATER, DIRECTLY INTO RIVER
NONE OBSERVED - OUTLETS SUBMERGED
IN COMPLIANCE WITH USACE FLOOD PLUMPING PROTOCOLS

None of the state		
02/08/08 12:58 AM	Supplemental Email notification of unauthorized discharge has been sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov	
02/07/08 06:45 PM	Given by voluntary email notification system	
02/08/08 12:58 AM	Email notification of unauthorized discharge sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov	

Report Selections: Treatment Plant: MSD0278 MORRIS FORMAN, Excluding PPI, CSO, Result: WUS, Act Code: DISDW, DISREV

KPDES# KY0022411 (Cont'd)

Facility ID MSD0278

Treatment Plant Name MORRIS FORMAN

Receiving Stream of Treatment Plant **OHIO RIVER**

Region WEST

Facility Type

Facility ID SLS Sewer Lift Station MSD0123-PS

Facility Address

6600 SEMINARY WOODS PL

If Pump Station, Name of Pump Station:

WEST GOOSE CREEK

Receiving Stream GOOSE CREEK

Discharge to DITCH

Activity Code / Description DISREV: RAIN EVENT

DISCHARGE

WO# 740504

Initiated 02/06/08 09:15 AM

Initiated By MARKS JR

Assigned To COOMER

Disch Stat D

Event Date Problem. 09/28/02

Resolution LACK OF SYSTEM DISCHARGE TO CAPACITY WATERS OF THE

Completed 02/06/08 09:30 PM

Spot Inspections:

Discharge Amount:	36,750 GAL	
Cause:	STORM FLOW LACK OF CAPACITY IN COLLECTION SYSTEM	
Clean Up:	AREA WAS CLEANED AND SANITIZED DEBRI WAS REMOVED	
Control Zone:	TEMP SIGNS POSTED AND AREA TAPED OFF	
mpact:	SLIGHT DISCOLORATION OF STREAM	
Repair:	HAULING TO PREVENT DISCHARGE	

Notifications:

02/06/08 12:58 AM	Supplemental Email notification of unauthorized discharge has been contact.
02/06/08 12:58 AM	Supplemental Email notification of unauthorized discharge has been sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaAJeffries@ky.gov Email notification of unauthorized discharge sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaAJeffries@ky.gov
	to iteratio.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov

Total Facilities Printed: 29