

Louisville and Jefferson County Metropolitan Sewer District 700 West Liberty Street Louisville Kentucky 40203-1911 502-540-6000 www.msdlouky.org

September 21, 2009

Ms. Carolena Bentley Kentucky Division of Water 200 Fair Oaks Lane Frankfort, Kentucky 40601

RE: Derek R Guthrie Water Quality Treatment Center, KPDES No: KY0078956

Discharge Monitoring Report

August 2009

Dear Ms. Bentley:

Attached are the Discharge Monitoring Report (DMR) and the Monthly Operating Report (MOR) for the Derek R Guthrie Water Quality treatment Center for the month of August 2009.

Also included are August overflow reports.

If you have any questions concerning the attached DMR's, please contact me at (502)540-6031.

Sincerely,

John Kessel

Process Supervisor, West Region

JMK/DRG 0809

Enclosures

cc: C. Roth

T. Singleton

R. Shaw



NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES)
DISCHARGE MONITORING REPORT (DMR)

Form Approved. OMB No. 2040-0004

DEREK R SUTHRIE WOTO MSD ADDRESS CIO CEDAR CREEK WOTO

SACE CELAR CREEK RD

LOUISVILLE MY 40211

DEFER A GUTHRIE WOTC MED **JUISVILLE** KY 40272 <u>atim: Dennie Thomasson, sr metro ops</u> KY0078956 PERMIT NUMBER DISCHARGE NUMBER

MAJOR KSUBR LV) F - FIMAL

DEFFE

MONITORING PERIOD YEAR MO DAY YEAR MO DAY FROM 100 ರ TO [", .2. A D 1,5

MUNICIPAL WASTEWATER EFFLUENT

*** NO DISCHARGE !! NOTE: Read Instructions before completing this form.

PARAMETER		QUAN	ENTRATION		NO.	FREQUENCY	SAMPLE					
		AVERAGE	MAXIMUM	UNITS	MINIMUM	AVERAGE	MAXIMUM	UNITS	EX	ANALYSIS	TYPE	
OXYGEN, DISBOLVED	SAMPLE MEASUREMENT	本作表示作品	经存在存款的		6	******	雪护 经安存金	(14)	0	0/3,	ER.	
POSCO (C G FFELVENT ORDSS VALUE	PERMIT REQUIREMENT	*****	在 在在本本本章	한참감 한참참	INST MIN	*************************************	***	MG/L	100 L		MAE	
988, 54344 (20 888, 6)	SAMPLE MEASUREMENT	- 30,00 <i>s</i>	35,737	(26)	全体水水水水	148	177	(19)	Ö	21/01	CP	
20310 > 0 0 RAW SEW/INFLUENT	PERMIT REQUIREMENT	REPORT MO AVG			在本本本本	REPORT MD AVG	REPORT MX WK AV	MOZL	10 E	AILY	OMP DE	
SUD BHRAY (EG Deg. C)	SAMPLE MEASUREMENT	2138	4046	(24)	***	10	12	(19)	0	01/0:	CP	
DOZIO : G O <u>Effluent großs value</u>	PERMIT REQUIREMENT	7506 MD AVG	MX WK AV	_BS/DY	**************************************	OVA DM	MX WK AV	MG/L		MILLY (WWW.	
To 544	SAMPLE MEASUREMENT	*************************************	· 安林安林安长 ·		× × 6.9	9 经安格格条件	7.4	(12)	0	01/01	ER	
20400 ! C 0 <u>Effluent gross value</u>	PERMIT REQUIREMENT	计型标识计		· · · ·	e.o. Minimum	教育教教教教	7.0 Maximum	5U		PALLY (W.A.B	
BUBLIDS: TOTAL. BUBLENDED	SAMPLE MEASUREMENT	39,124	52,626		非常存在容器	189	227	(19)	9	01/01	CP.	
POSCO G G G PAN SEW/INFLUENT	PERMIT REQUIREMENT	MEPORT MO AVO	REPORT MX WK AV	LBS/DY	特殊非典物學	REPORT MD AVG	REPORT MX WK AV	MG /L	iri L	WILY I	JJMHUO	
FOLIDA, FUTAL SUSPENDED	SAMPLE MEASUREMENT	1870	3990	(26;	नेक कि हैंग हैंग सक	ঠ	/ 1	(19)	0	01/01	CP	
DOSCO 1 0 0 <u>Effluent gross value</u>	PERMIT REQUIREMENT	7506 MD AVG	MI WK AV	_BS/DY	** **	30 MO AVG	AS MX WW AW	MG/L	3 ±	ALLY	. Control of the cont	
WITHOGEN, AMMONIA FOTAL (AS N)	SAMPLE MEASUREMENT	2730	2838	(26)	存分分分分分	14	17	(17)	0	01/01	Cio.	
DC610 3 (0 RAM SEM/INFLUENT	PERMIT REQUIREMENT	REPORT MD AVG	REPORT MX WK AV	_BS/DY		REPORT MO AVG	REPORT MX WK AV	MG/L	1807 9 4		<i>jurir</i> us	
NAME/TITLE PRINCIPAL EXECUTIVE LAS COLOR TYPED OR PRINTED	prepare to assur submiti or those submiti	y under penalty of law that the ed under my direction or sup- te that qualified personnel pri- ted. Based on my inquiry of the persons directly responsible ted is, to the best of my knowl ware that there are significant	ervision in accordance with a operly gather and evaluate the ie person or persons who ma for gathering the information edge and belief, true, accura	system designed ne information mage the system, on, the information te, and complete.		THE OF PRINCIPAL	EXECUTIVE 50	TELEPHON		09 09		

including the possibility of fine and imprisonment for knowing violations. COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here)

USE MD AVG FOR BODYTSS BENY, REPT IN MINIMUM COLUMN.

YEAR

DAY

OF

NUMBER

OFFICER OR AUTHORIZED AGENT

TYPED OR PRINTED

BEREN R GUTHRIE WOTC MSD

ADDRESS C/O CEDAR CREEK WOTO

EAGS CEDAR CREEK RD

LOUISVILLE FACILITY

KY 40211

DEREK & GUTHRIE WOTC MED LOCATION LOUISVILLE

KY 40272 ATTAL DENMIS THOMASSON, SR METRO OPS NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES)
DISCHARGE MONITORING REPORT (DMR)

MONITORING PERIOD

TO

YEAR

KY0078956 **PERMIT NUMBER**

DAY

U. 1.

YEAR

الرا في ا

FROM

MO

JE

001 2 DISCHARGE NUMBER

DAY

-J- J.

MO

U

ROUMM (SUBR LV) F - FIMAL Form Approved. OMB No. 2040-0004

WEFFE

MUNICIPAL WASTEWATER EFFLUENT

*** NO DISCHARGE 1

NOTE: Read Instructions before completing this form.

	PLANT CHE CHE	rread ear, and			NOTE: Head instructions before completing this form.												
PARAMETER		QUAN	TITY OR LOADING			QUALITY OR CON	NO.	FREQUENCY OF	SAMPLE								
		AVERAGE	MUMIXAM	UNITS	MINIMUM	AVERAGE	MAXIMUM	UNITS	EX	ANALYSIS	TYPE						
WITEDOER, AMMONIA	SAMPLE MEASUREMENT	600	1016	(26)	经安存条款	3	3	(19)	0	01/	CP						
DOGLO ; C D EFFLUENT GROSS VALUS	PERMIT REQUIREMENT	5004 MD AVG	ZSOS MX WK AV	LBS/DY	***	NO AVE	MX WK AS	me/L	1	ALLY	JUMF US						
NITROGEN: MUELDAML FOTAL (AS N)	SAMPLE MEASUREMENT	971	1262	(Z6)	李宗宗宗宗	5	6	(17)	0	01/0	CP						
DCASS : () EFFLUENT GROSS VALUE	· · · · · · · · · · · · · · · · · · ·	REPORT MO AVG	REFORT MX WX AV	_RS/DY	· 基本条件条件。	REPORT MO AVO	REPORT MX WK AV	MG/L	10 4	eeney.	<i>เมาเทย</i> ธ						
THOSTHORUS, TOTAL (AS F)	SAMPLE MEASUREMENT	461	5 65	(26)	水水水水水水	2.4	3.5	(19)	<u>.</u> ⊙	01/07	OP						
00665 (0 0 EFFLUENT GROSS VALUE		REPORT MO AVS	REPORT MX WK AV	_BS/DY	****	REPORT MO AVS	REPORT MX WA AV	MG/L	¥		Amrus						
TLOW IN COMPUTE OR THRU TREATMENT PLANT			70.79	(03)	****	安安安安安	经安全安全会		0	CN	CN						
30050 9 0 0 RAW SEW/INFLUENT	PERMIT REQUIREMENT	MEFORT MO AVO	REPORT DAILY MX	TOD	· 技术长龄标识	特殊教育技術	and the	***		UNIJAK UDUS	1912 1 William						
FLOW, IN COMBUIT OR THRU TREATMENT PLANT			76.98	(03)	安安安安安安	安安安安安安	经条条条件		Ó	وس	en						
BEFFLUENT GROSS VALUE	PERMIT REQUIREMENT	REPORT MO AVO		YGD	特殊於於於特	李爷爷爷女女	(1) 数字的长衫长。大	****** *****	370 344	UNTIN VOUS	DIVI LITE						
CHLORING, TOTAL RESIDUAL	SAMPLE MEASUREMENT	经经营营业	特条特殊转载		安安安安安	教育教育教育	(0.010	(177	0	%	GÊ						
50060 1 0 0 EFFLUENT GROSS VALUE	PERMIT REQUIREMENT	李本本本本	**************************************	644 6444	安全安全的	*****	DAILY MX	M9/L		HILY I	M HI						
COLIFORM. FECAL BENERAL	SAMPLE MEASUREMENT	格拉格格格	茶水水水水		李本帝亲来家	,	1	(13)	Ö	01/21	GR						
	PERMIT REQUIREMENT	茶粉茶茶料		公安安全	*****	BODA GEO	400 1 7 DA GEQ	/ 100ML	, L	MALY 3	MAR						
NAME/TITLE PRINCIPAL EXECUTIVE	prepared to assume submitted or those submitted in a management including including a submitted in a management including including including a submitted in a management including includ	under penalty of law that the dunder my direction or supper that qualified personnel prod. Based on my inquiry of the persons directly responsible dis, to the best of my knowlare that there are significant g the possibility of fine and it	rvision in accordance with a pperly gather and evaluate the person or persons who mat for gathering the information and belief, true, accura- nepalties for submitting fels.	system designed he information mage the system, on, the information te, and complete, to information	SIGNA	NTURE OF PRINCIPAL FIGER OR AUTHORIZE	SUO 60	, Uo	OS () YEAR MO	121							

COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here)

JSE MO AVG FOR BODYTSS REMVIREPT IN MINIMUM COLUMN.

DEREK R GUTHRIE WOTO MED ADDRESS C/O CEDAR CREEK WOTO

MADS CHOAR CREEK AD

LOUISVILLE

KY 40211

FACILITY DEREN R SUTHRIE WETC MED

LOCATION LOUISVILLE

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES)
DISCHARGE MONITORING REPORT (DMR)

MONITORING PERIOD

YEAR

DAY

XY0078956 PERMIT NUMBER

MO

VXX

YEAR

FROM

001 2 DISCHARGE NUMBER

DAY

MO

MAJOR (SUBR LV) F - FINAL

JETFE

MUNICIPAL WASTEWATER

EFFLUENT

*** NO DISCHARGE 1

Form Approved.

OMB No. 2040-0004

QI TO 17.2 Ę ATTN: DENNIS THOMASSON, SR METRO DES NOTE: Read Instructions before completing this form. **PARAMETER** QUANTITY OR LOADING FREQUENCY NO. SAMPLE QUALITY OR CONCENTRATION ΕX TYPE ANALYSIS **AVERAGE** MAXIMUM UNITS MINIMUM **AVERAGE** MAXIMUM UNITS BOD, H-JAY FERGEMT SAMPLE 经营销营业价值 经营业营业 松松香香茶香 经存储额收益 237 94% MEASUREMENT REMOVAL Biolo a c o PERMIT 特特特特特特 市家中 夢 在安存存存 85 水性染物性体 外外的外面的 **王冠一** NCEZ 14 L. C. L. REQUIREMENT AVONAS TRECAS 安安安安 MO AVO MONTH CENT SCLIDE, SUSPENDED SAMPLE 经营业营业 (23) 经营业营业 经营业营业 经营业营业 MEASUREMENT 130 PERCENT REMOVAL PERMIT 经收款的原始 51011 / 6 C 林林林 经一次申请 SALCID 巴斯 **沙安林安安** · 好会的依然你。FF 巨尺一 OMCEZ REQUIREMENT PERCENT REMOVAL ·安安安 MIN OM MONTH CENT SAMPLE MEASUREMENT PERMIT REQUIREMENT NAME/TITLE PRINCIPAL EXECUTIVE OFFICER I certify under penalty of law that this document and all attachments were **TELEPHONE** DATE prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system. or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. 19 SIGNATURE-OF PRINCIPAL EXECUTIVE I am aware that there are significant penalties for submitting false information, TYPED OR PRINTED including the possibility of fine and imprisonment for knowing violations. OFFICER OR AUTHORIZED AGENT NUMBER YEAR MO DAY

COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here)

USE MO AVS FOR SODITSS REMY: REPT IN MINIMUM COLUMN.

NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES) DISCHARGE MONITORING REPORT (DMR)

Form Approved.	
OMB No. 2040-0004	

KYOOMBARR PERMIT NUMBER

001 R DISCHARGE NUMBER MAJOR (SUBR LV) F - FINAL

JEFFE

LOUISVILLE KY 40211 FACILITY DEPEN R QUITHRIE WOTE MED LOCATION LOUISVILLE

ADDRESS C/O CEDAR OREEK WOTO

RAGE CEDAR CREEK RD

KY 40272

MONITORING PERIOD YEAR MO DAY YEAR MO DAY FROM J. 7 C L

EFFLUENT *** NO DISCHARGE (

REASONABLE POTENTIAL

<u>DEMNIS THOMASSON, SR METRO OPS</u> NOTE: Read Instructions before completing this form. PARAMETER QUANTITY OR LOADING FREQUENCY QUALITY OR CONCENTRATION NÓ. SAMPLE OF EX TYPE **ANALYSIS** AVERAGE MAXIMUM UNITS MINIMUM **AVERAGE** MAXIMUM UNITS HREMIEND MENAVALENT SAMPLE 经营营营业的 经营营税税款 特性特殊分裂 (19) 10.01 10.0 O MEASUREMENT (AS CR) 130 SECIE 1 C 0 PERMIT 经营营营营业 计分类 经营业证券 李松松女女女女 REPORT REPORT 対に出て いんけい ひと EFFLUENT CROSS VALUE REQUIREMENT 经验证券 DAILY MX MG/L MO AVO MONTH SAMPLE MEASUREMENT PERMIT REQUIREMENT SAMPLE MEASUREMENT PERMIT REQUIREMENT SAMPLE **MEASUREMENT** PERMIT REQUIREMENT SAMPLE MEASUREMENT PERMIT REQUIREMENT SAMPLE MEASUREMENT PERMIT REQUIREMENT SAMPLE MEASUREMENT PERMIT REQUIREMENT NAME/TITLE PRINCIPAL EXECUTIVE OFFICER I certify under penalty of law that this document and all attachments were **TELEPHONE** prepared under my direction or supervision in accordance with a system designed DATE Exce Di to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, H.J. Schurden Jr or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. 540-600 SIGNATURE OF PRINCIPAL EXECUTIVE 21 I am aware that there are significant penalties for submitting (also information, TYPED OR PRINTED including the possibility of fine and imprisonment for knowing violations, OFFICER OR AUTHORIZED AGENT NUMBER YEAR DAY

COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here)

Name of Sewage Treatment Plant: West County WTP										onth of:	nth of: At					August																
KPDES	DES Pormit Numbor: KY0078956 Plant Copacity;				30 N	/IGD	Count	y		Rocoivi	ng Strocu	m:	Ohio River																			
							· · ·										Activated															
	1	Row						spended		Total		5-	day BOI								gration			Dig			Final					
		Sewage pH		Solids (mL/L) Oxygen (mg/L)				S	Solids (mg/L)		(mg/L)			Ro	otum	WAS	Bas			Basin			Sludge	- 1								
	(MG)	noved (cu.		6	000	e A De	low		r Sec.)		r Sec.)			(or Sec.)		Gal/Day	_	1990	lg/.	ng/L)	(mg/L) #18#2	ng/L) 8#2	Setts.			ŝ	2	Chlorine Residual (mg/L)	(JV)	ll mo	ا ء ء	
	Total Flow (세요)	Ren	-a	aw dman fo	I	aam Ab	am Be	,	rimary (o	-	rimary (or	<u>-</u>	ڃ	rimary (o	ī	ion Ga	LSS mg/L 1000	X veQ/	Oxygen (mg/L)	Oxygen (mg/L)	MLSS (mg X1000 #1	MLVSS (mg/L) X1000 #18#2	in in	_	Solids	Phosphorus (mg/L)	TKN (mg/L)	lorine sidual	чНЗ-N (mg/L)	Fecal Coliform Col./100ml	Hexavalent Chrom\um	Hardness
Date	卢	Sar Ray	Fina	6 C	Ē . Ē	Strear	\$ S	Raw	-Z	Final Raw	<u>.</u>	Fina	e.	굺	든	ž	₹ <u>%</u>	ő	§ŏ∓	<u>564</u>	<u> </u>		. ୧	§	85	£ E			- Fel		<u> </u>	<u> </u>
1	31.09	7,3	7.1			7.0		144		10		<u> </u>	102		9		2910			<u> </u>	1170	930	80.0	0.07				0.01	2.60	1		├ ──
	27.02	7.0	6.9			7.5		198		12	-		157	·	14		3430		-	<u> </u>	2190	1580	80.0	0.04			5.60	0.01	3.80	1		
	24.98	7.1	6.9			6.9		166		9	-		129		11	<u> </u>	3320		┼	-	1700	1310	100.0	80.0		1.04		0.01	3.40	1		
4	49.54	7.2	7.0	-	+	7.0		206		17	-		95		16		3330		 	-	1610	1260	100.0	0.06		1.21		0.01 0.01	2.30	1	-	—
	76,98	7.0	7.1			7.5 7.2		96 154		10			63 126		9 14		3330 3120			 	510 1300	470 930	40.0	0.07				0,01	3.80	1	-	
7	44,36 32,42	7.2	7.2			6.9		178		11			126		11		3330			 	1330	950	60.0	0.05				0.01	2.90	1	-	\vdash
<u> </u>	28.10	7.2	7.1	-		7.0		166		11			135		8		3590		 	·	1600	1130	100.0	0.06				0.01	3.60	1	\neg	\vdash
_	25.93	7.2	7.2		+	6.9	+ + -	164		11	+	1	161		7	-	4390			1	2210	1600	100.0	0.05			5.40	0.01	3.60	1		
	24.65	7.2	6.9			6.5	+ -	188		8			155		13		3680		1	—	1850	1350	110.0	0.06				0.01	3.80	1		
	31.35	7.2	7.1			6.9	+ + -	156		8			138		4		4910				2010	1440	120.0	0,06		1.31		0.01	2.60	1	0.01	240
	27.74	7.2	7.0			6.8		140		5	1		91		6		4670				2180	1590	120,0	0.06		1.40		0,01	2.10	1		
13	25.41	7.3	7.0			6.9		76		5			123		8		4110				1910	1370	120,0	0.06				0.01	1.30	1		
14	22.90	7,4	7,2			6.4	l l	230		4			144		7		3580				2410	1780	120,0	0.05				0.01	1.30	1		
15	22.80	7.2	7.0			6.4		152		7		<u> </u>	124		7		3700		ļ	ļ	1970	1460	120,0	0.06				0.01	2.10	1		
	22.17	7.2	7.0			6.7		176		7			135		10		3340		<u> </u>	ļ <u> </u>	2290	1630	110.0	0.05			4.70	0.01	2.80	1		
	23.06	7.2	7.0			6.5		166		7	1		158		11		3450		-	 	1780	1390	120,0	0.07				0.01		1		
	20.10	7.2	7.0		4	7.1		212		6	1		184		11		3740		-	 	1610	1250	100.0	0.06		2.45		0.01	2.50 1.70	1		
	21,00	7.5	7.2		+ -	6,5		506		6	+		200	1	11		3350		+	-	1810 1780	1400	110.0	0,06	-		-	0.01	2.00	- 1		-
	20,43	7.3	6.9		-	6.3		258		7		-	186	_	8		3380 3740		+	-	1940	1540 1490	120.0	0.06				0.01	2.70			
	21.45	7.2	6.9 6.9			6.7		118 278	_	5	┼		161 176	-	7		3740		-	 	1930	1510	140.0	0.07				0.01	2.10	1		-
22	19.45	7.3	7.2		-	6.0		168		5	+	+	203		10		3420				2070	1620	160.0	0.08			4.70	0.01	2,90	1		
	20,36	7.3	7.1			6.3		200	- -	5	+		177		9		2870		1	1	2400	1910	180.0	0,08		3.74		0.01	2.30	1	\neg	\vdash
25	18.41	7.2	7.2			6.5		286		9	1		199		18		3350				1680	1320	120.0	0.07				0.01	4.00	1	\neg	
26	18.23	7.4	7.0			6.3	+	148		8	1-		122	_	5		3190		1	1	2020	1610	140.0	0.07				0.01	1.50	1	0.01	
27	17.86	7.2	7.0			5,7	1	262		6	1	1	251		12		3050				1880	1530	120.0	0.06		3,32		0.01	4.40	1		
28	18.12	7.3	7.0			6.2		190		6			109		6		2820				1710	1530	110.0	0,06				0.01	1,70	1	0.01	↓
29	18.40	7.3	7,1			6.7		80		8			96		6		4060				2050	1610	100,0	0.05		3,38		0.01	2.90	1	!	
30	18.34	7,8	7.4			6.4		234		8			193		11		3340		L		1800	1380	100.0	0.06	- 1		5.20	0.01	3.50	1		
31	17,30	7.4	7,0			6.1		198		7			175		11		2810			<u> </u>	1750	1390	100.0	0.06				0.01	2.80	1		ļ
Total	810.6	0 0						_		1 2 2					·	0.0		0,0	<u> </u>			prosentation of the	\$41.981 JF E		e er i e sê					` 		
Avg.	26.15	7.3	7,1			6.6	il	189		8			148	ــــــــــــــــــــــــــــــــــــــ	10	.,	3501.0			<u></u>	1824.19	1395.48	108.06	0		2,40	5.12	0.01	2.73	1	0.01	240
J																																
																Occuptor								K-via Thomasa								
		Sewer Connections:			- (0	Indi	istrial	Waste Pop	pulation Equivalent							Operator							Kavin Thompson								
		nections:					-		49019			190259	n	•	1967	762					Cort.#					#188	171					
		nnections:							Flow			BOD			TS						Coil. #	-		#1007 (
	ial Conne Consecti	octions; lons X 4 ⊨		<u>.</u>			-		LIUW			טטם			15	-					Phone #											
Sowar	Junual					•															. 115.10 x	-				540-0						





KPDES# KY0078956 Facility ID MSD0277

Water Quality Treatement Center **DEREK R. GUTHRIE**

Receiving Stream of Treatment Center OHIO RIVER

Region WEST

Facility Type

Facility ID

Facility Address

If Pump Station, Name of Pump Station:

Receiving Stream

Discharge to

SMH Sewer Manhole

04542

3434 FERN LEA RD

HEATHERFIELD DITCH

DITCH

Activity Code / Description

WO#

<u>Initiated</u>

Initiated By SINGLETON Assigned To KESSEL

Disch Status

Event Date

Problem

Result

Completed

Condition

DISREV: RAIN EVENT DISCHARGE

938278

08/04/09 09:00 AM

DOCUMENTED

12/15/07

LACK OF SYSTEM CAPACITY

UNAUTHORIZED DISCHAGE -

08/05/09 05:30

PM

WATERS

Spot Inspections:

Discharge Amount

9,999 GAL

Cause:

LACK OF SYSTEM CAPACITY- AREA FLOODED

Clean Up:

MSD CLEANED & SANITIZED THE AREA

Control Zone:

TEMPORARY SIGNS POSTED

Impact

SOLIDS & DEBRIS OBSERVED

Repair.

THIS SITE WAS FOUND DURING RAIN EVENT RECON- WILL MONITOR & EVALUATE FOR REPAIR

Notifications:

08/04/09 01:00 PM

DI\$NOT

Email notification of unauthorized discharge sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov

08/04/09 09:00 AM

DISPUB

TEMPORARY SIGNS POSTED

08/04/09 01:00 PM

DISSNO



KPDES#

KY0078956 (Cont'd)

Facility ID MSD0277

Water Quality Treatement Center

DEREK R. GUTHRIE

Receiving Stream of Treatment Center

OHIO RIVER

Region WEST

Facility Type

DISCHARGE

Facility ID

Facility Address

If Pump Station, Name of Pump Station:

Receiving Stream

Discharge to

Condition

SMH Sewer Manhole

04699-W

1714 LAMKINS CT

MILL CREEK

GROUND

Activity Code / Description DISREV: RAIN EVENT

WO# 938646

initiated 08/04/09 10:00 AM Initiated By ELDER

Assigned To KESSEL

Disch Status

Event Date 12/15/07

Problem

Result

WATER\$

Completed

DOCUMENTED

LACK OF SYSTEM CAPACITY

UNAUTHORIZED DISCHAGE -

AM

08/05/09 03:30

Spot Inspections:

Discharge Amount

9,999 GAL

Cause:

LACK OF SYSTEM CAPACITY DUE TO FLOODING

Clean Up:

DISCHARGE PIPE SUBMERGED - NO CLEAN UP DUE TO FLOODING

Control Zone:

TEMPORARY SIGNS POSTED

Impact

NO IMPACT OBSERVED - DISCHARGE PIPE SUBMERGED

Repair:

THIS SITE FOUND DURING RAIN EVENT RECON- WILL MONITOR & EVALUATE FOR REPAIR

Notifications:

08/05/09 11:11 AM

DISNOT

Manual email notification of unauthorized discharge sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov


08/04/09 08:00 PM

DISPUB

TEMPORARY SIGNS POSTED

08/04/09 01:00 PM

DISSNO





KPDES #

KY0078956 (Cont'd)

Facility ID MSD0277

Water Quality Treatement Center

DEREK R. GUTHRIE

Receiving Stream of Treatment Center

OHIO RIVER

Region WEST

Facility Type

DISCHARGE

Facility ID

Facility Address

If Pump Station, Name of Pump Station:

Receiving Stream UPPER MILL CREEK Discharge to

SMH Sewer Manhole

06915-W

3712 ROSA TER

GROUND

Activity Code / Description

WO#

Initiated

Initiated By **ELDER**

Assigned To

Disch Status

Event Date

Problem

Result

Completed

Condition

DISREV: RAIN EVENT

938638

08/04/09 12:00 PM

HEACOCK

FORCE MAJEURE 08/04/09

LACK OF SYSTEM CAPACITY

UNAUTHORIZED DISCHAGE -

08/04/09 07:30

PM

WATERS

Spot inspections:

Discharge Amount

9.999 GAL

Cause:

LACK OF SYSTEM CAPACITY- STATION FLOODED.

Clean Up:

NO DEBRIS- STATION UNDER WATER

Control Zone:

TEMPORARY SIGNS POSTED

impact;

NO IMPACT OBSERVED- STATION UNDER WATER

Repair.

SITE FOUND DURING RAIN EVENT RECON- WILL BE MONITORED & EVALUATED FOR REPAIR

Notifications:

08/05/09 11:01 AM

DISNOT

Manual email notification of unauthorized discharge sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov

08/04/09 12:00 PM

DISPUB

TEMPORARY SIGNS POSTED

08/04/09 01:00 PM

DISSNO



KPDES#

KY0078956 (Cont'd)

Facility ID MSD0277

Water Quality Treatement Center

DEREK R. GUTHRIE

Receiving Stream of Treatment Center

OHIO RIVER

Region WEST

Facility Type

Facility ID

Facility Address

If Pump Station, Name of Pump Station;

Receiving Stream

Discharge to

SMH Sewer Manhole

32682

6707 W ORELL RD

ALVEY DITCH

STREAM

Activity Code / Description

DISREV: RAIN EVENT

WO #

Initiated

Initiated By

Assigned To

Disch Status

Event Date

Problem LACK OF SYSTEM Result

WATERS

Completed AM

Condition

DISCHARGE

938662 08/04/09 08:20 AM **GRIFFITH**

GRIFFITH

DOCUMENTED

03/12/06 CAPACITY UNAUTHORIZED DISCHAGE -

08/05/09 05:00

Spot Inspections:

Discharge Amount

27,000 GAL

Cause:

LACK OF SYSTEM CAPACITY-HEAVY RAIN

Clean Up:

DISCLN WORK ORDER #940869 CREATED FOR I&FP FOR THIS LOCATION

Control Zone:

NO CONTORL NEEDED- VERY REMOTE AREA

Impact

LIGHT IMPACT OBSERVED DUE TO MAGNITUDE OF THE STORM

Repair.

THIS LOCATION IS ON A TELEMETRY ALARM SYSTEM AND IE VERY CLOSELY MONITORED

Notifications:

08/04/09 01:00 PM

DISNOT

Email notification of unauthorized discharge sent to ireland, sean@epa.gov, eppc,ert@ky.gov and LisaA. Jeffries@ky.gov


08/05/09 09:26 PM

DISPUB

PUBLIC NOTIFIED THROUGH PERMANENT SIGNS TO AVOID DIRECT CONTACT WITH DISCHARGED CONTENT

08/04/09 01:00 PM

DISSNO





KPDES#

KY0078956 (Cont'd)

Facility ID MSD0277

Water Quality Treatement Center

DEREK R. GUTHRIE

Receiving Stream of Treatment Center

OHIO RIVER

Region WEST

Facility Type

Facility ID

Facility Address

If Pump Station, Name of Pump Station:

Receiving Stream

Discharge to

Condition

SMH Sewer Manhole

60709-W

10805 ORELAND MILL RD

PENNSYLVANIA RUN

DITCH

Activity Code / Description

WO# 938639 Initiated

Initiated By

Assigned To

Disch Status

Event Date

Problem

POWER OUTAGE

Result UNAUTHORIZED Completed

DISCHARGE

DISREV: RAIN EVENT

08/04/09 04:00 PM

ELDER

HEACOCK

REPAIRED -ISSUE

08/04/09

(LG&E)

DISCHAGE -

08/04/09 04:30 PM

RESOLVED

WATERS

Spot inspections:

Discharge Amount

1,500 GAL

Cause:

LG&E POWER OUTAGE

Clean Up:

NO DEBRIS

Control Zone:

TEMPORARY SIGNS POSTED

Impact:

NO VISUAL IMPACT

Repair.

THIS SITE FOUND DURING RAIN EVENT RECON- WILL BE MONITORED & EVALUATED FOR REPAIR

Notifications:

08/04/09 01:00 PM

DISNOT

Email notification of unauthorized discharge sent to ireland, sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov


08/04/09 04:00 PM

DISPUB

TEMPORARY SIGNS POSTED

08/04/09 01:00 PM

DISSNO





KPDES#

KY0078956 (Cont'd)

Facility ID MSD0277

Water Quality Treatement Center

DEREK R. GUTHRIE

Receiving Stream of Treatment Center

OHIO RIVER

Region WEST

Facility Typo

DISCHARGE

Facility ID

Facility Address

If Pump Station, Name of Pump Station:

Receiving Stream

Discharge to

Condition

SMH Sower Manhole

81814-W

2601 PIONEER RD

MILL CREEK

DITCH

Activity Code / Description DISREV: RAIN EVENT

WO# 938273 Initiated 08/04/09 09:00 AM

Initiated By SINGLETON

Assigned To PATTERSON Disch Status DOCUMENTED **Event Date** 01/24/02

<u>Problem</u> LACK OF SYSTEM

CAPACITY

Result UNAUTHORIZED Completed 08/05/09 03:00

PM

DISCHAGE -

WATERS

Spot Inspections:

Discharge Amount

9,999 GAL

Cause:

THE STATION AND THE AREA AROUND IT FLOODED DUE TO HEAVY RAIN

Clean Up:

NO DEBRIS- AREA FLOODED

Control Zone:

TEMPORARY SIGNS POSTED

Impact;

NO IMPACT OBSERVED DUE TO FLOODING

Repair:

THIS SITE WAS FOUND DURING RAIN EVENT RECON- WILL MONITOR & EVALUATE FOR REPAIR

Notifications:

08/04/09 01:00 PM

DISNOT

Email notification of unauthorized discharge sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Joffries@ky.gov


08/04/09 09:00 AM

DISPUB

TEMPORARY SIGNS POSTED

08/04/09 01:00 PM

DISSNO





KPDES# KY0078956 (Cont'd) Facility ID MSD0277

Water Quality Treatement Center DEREK R. GUTHRIE

Receiving Stream of Treatment Center OHIO RIVER

Region WEST

Facility Type

Facility ID

Facility Address

If Pump Station, Name of Pump Station:

Receiving Stream

Discharge to

Condition

SMH Sewer Manhole

92098

7801 EDSELLN

FERN CREEK

GROUND

Activity Code / Description

DISREV: RAIN EVENT

WO # 938269 <u>Inițiated</u>

Initiated By

Assigned To

Disch Status

Event Date

Problem

Result UNAUTHORIZED Completed 08/04/09 02:14

DISCHARGE

08/04/09 01:00 PM

SINGLETON

VIERLING

DOCUMENTED

05/16/08

POWER OUTAGE (LG&E)

DISCHAGE -WATERS

PM

Spot Inspections:

Discharge Amount:

3,700 GAL

Cause:

LG&E POWER FAILURE

Clean Up:

MSD RAKED & BAGGED DEBRIS

Control Zone:

TEMPORARY SIGNS POSTED

Impact

NO VISUAL IMPACT OBSERVED

Repair:

LG&E RESTORED POWER

Notifications:

08/04/09 01:00 PM

DISPUB

TEMPORARY SIGNS POSTED

08/04/09 01:00 PM

DISNOT

Email notification of unauthorized discharge sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov

08/04/09 01:00 PM

DISSNO



KPDES#

KY0078956 (Cont'd)

Facility ID MSD0277

Water Quality Treatement Center DEREK R. GUTHRIE

Receiving Stream of Treatment Center

OHIO RIVER

Region WEST

Facility Type

Facility ID

Facility Address

If Pump Station, Name of Pump Station:

Receiving Stream

Discharge to

Condition

SMH Sewer Manhole

92099

7801 EDSELLN

FERN CREEK

GROUND

Activity Code / Description

DISREV: RAIN EVENT

WO# 938261 <u>Initiated</u>

Initiated By SINGLETON Assigned To

Disch Status REPAIRED -

Event Date 08/04/09

<u>Problem</u> POWER OUTAGE

Result Completed UNAUTHORIZED

08/04/09 02:14

DISCHARGE

08/04/09 01:00 PM

VIERLING

ISSUE RESOLVED

(LG&E)

DISCHAGE -

PM

WATERS

Spot Inspections:

Discharge Amount

7,400 GAL

Cause:

LG&E POWER FAILURE - STORMS IN THE AREA

Clean Up:

MSD RAKED & BAGGED DEBRIS

Control Zone:

TEMPORARY SIGNS POSTED

Impact

NO IMPACT OBSERVED

Repair.

LG&E RESTORED POWER

Notifications:

08/04/09 01:00 PM

DISPUB

TEMPORARY SIGNS POSTED

08/04/09 01:00 PM

DISNOT

Email notification of unauthorized discharge sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov

08/04/09 01:00 PM

DISSNO



KPDES#

KY0078956 (Cont'd)

Facility ID MSD0277

Water Quality Treatement Center DEREK R. GUTHRIE

Receiving Stream of Treatment Center

OHIO RIVER

Region WEST

Facility Type

Facility ID

Facility Address

If Pump Station, Name of Pump Station:

Receiving Stream

Discharge to

Condition

SLS Sewer Lift Station

MSD0044-PS

3951 CANE RUN RD

JACKS LANE

LYNNVIEW DITCH

GROUND

Activity Code / Description

WO#

<u>Initiated</u>

Initiated By

Assigned To HEACOCK

Disch Status REPAIRED -

Event Date 08/04/09

Problem ELECTRICAL Result

Completed

DISREV: RAIN EVENT

938647

08/04/09 10:10 AM

ELDER

ISSUE

PROBLEMS AT MSD

UNAUTHORIZED DISCHAGE -

08/04/09 01:00

PM

DISCHARGE

RESOLVED

WATERS

Spot Inspections:

Discharge Amount

100 GAL

Cause:

ELECTRICAL SHORT IN CONTROL PANEL DUE TO FLOODING

Clean Up:

NO DEBRIS

Control Zone:

TEMPORARY SIGNS POSTED

Impact

NO VISUAL IMPACT OBSERVED

Repair:

GENERATOR PLACED & CONTROLS REPAIRED

Notifications:

08/05/09 11:14 AM

DISNOT

Manual email notification of unauthorized discharge sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov

08/04/09 10:10 AM

DISPUB

TEMPORARY SIGNS POSTED

08/04/09 01:00 PM

DISSNO



KPDES#

KY0078956 (Cont'd)

Facility ID MSD0277

Water Quality Treatement Center DEREK R. GUTHRIE

Receiving Stream of Treatment Center OHIO RIVER

Region WEST

Facility Type

Facility ID

Facility Address

If Pump Station, Name of Pump Station:

Receiving Stream

Discharge to

Condition

SLS Sewer Lift Station

MSD0133-PS

10212 CAVEN AVE

CAVEN AVE

MUD CREEK

GROUND

Activity Code / Description DISREV: RAIN EVENT

WO# 938643

Initiated 08/04/09 07:20 PM Initiated By **ELDER**

Assigned To **FERRIELL**

Disch Status DOCUMENTED **Event Date** Problem 04/04/08

Result PUMPED OVERFLOW

Completed UNAUTHORIZED

08/05/09 08:45

PM DISCHAGE -WATERS

DISCHARGE

Spot Inspections:

Discharge Amount:

21,250 GAL

Cause:

LACK OF SYSTEM CAPACITY

Clean Up:

NO DEBRIS

Control Zone:

TEMPORARY SIGNS POSTED

impact

NO IMPACT OBSERVED

Repair.

SET PUMP TO PREVENT BASEMENT FLOODING UNTIL HAULING FROM STATION WAS AVAILABLE

Notifications:

08/04/09 07:20 PM

DISPUB

MSD ADVISED CUSTOMER ON SITE & POSTED TEMPORARY SIGNS


08/04/09 01:00 PM

DISNOT

Email notification of unauthorized discharge sent to ireland.sean@opa.gov, eppc.ort@ky.gov and LisaA.Jeffries@ky.gov

08/04/09 01:00 PM

DISSNO





KPDES#

KY0078956 (Cont'd)

Facility ID

MSD0277

Water Quality Treatement Center

DEREK R. GUTHRIE

Receiving Stream of Treatment Center

OHIO RIVER

Region WEST

Facility Type

Facility ID

Facility Address

If Pump Station, Name of Pump Station:

Receiving Stream

Discharge to

SLS Sewer Lift Station

MSD0140-PS

423 ECHAPPE LN

TREE LINE

BEE LICK CREEK

DITCH

Activity Code / Description

WO#

Initiated

Initiated By

Assigned To

Disch Status

Event Date

Problem

Result

Completed AM

Condition

DISREV: RAIN EVENT

938282

08/04/09 12:06 PM SINGLETON KESSEL

FORCE MAJEURE 08/04/09

LACK OF SYSTEM CAPACITY

UNAUTHORIZED DISCHAGE -WATERS

08/05/09 12:45

DISCHARGE

Spot Inspections:

61,500 GAL

Causo:

LACK OF SYSTEM CAPACITY

Clean Up:

Discharge Amount

MSD CLEANED & SANITIZED THE AREA

Control Zone:

TEMPORARY SIGNS POSTED

Impact

SEWAGE & DEBRIS OBSERVED

Repair,

THIS SITE FOUND DURING RAIN EVENT RECON- WILL BE MONITORED & EVALUATED FOR REPAIR.

Notifications:

08/04/09 12:06 PM

DISPUB

TEMPORARY SIGNS POSTED

08/04/09 01:00 PM

DISNOT

Email notification of unauthorized discharge sent to ireland, sean@epa,gov, eppc,ert@ky.gov and LisaA.Jeffries@ky.gov

08/04/09 01:00 PM

DISSNO



KPDES#

KY0078956 (Cont'd)

Facility ID

MSD0277

Water Quality Treatement Center

DEREK R. GUTHRIE

Receiving Stream of Treatment Center

OHIO RIVER

Region WEST

Facility Type

Facility ID

Facility Address

If Pump Station, Name of Pump Station:

Receiving Stream

Discharge to

SLS Sewer Lift Station

MSD0163-LS

11006 WAYCROSS AVE

WAYCROSS AVENUE

PENNSYLVANIA RUN

DITCH

Activity Code / Description

WO#

<u>Initiated</u>

Initiated By

Assigned To HEACOCK

Disch Status FORCE

Event Date Problem Result

Completed

AM

Condition

DISREV: RAIN EVENT DISCHARGE

938640

08/04/09 05:45 PM

ELDER

MAJEURE

08/04/09

PUMPED OVERFLOW

UNAUTHORIZED

08/05/09 03:00

DISCHAGE -

WATERS

Spot Inspections:

Discharge Amount

138,750 GAL

Cause:

LACK OF SYSTEM CAPACITY

Clean Up:

MSD CLEANED & SANITIZED THE AREA

Control Zone:

TEMPORARY SIGNS POSTED

Impact:

SEWAGE OBSERVED

Repair.

THIS SITE FOUND DURING RAIN EVENT RECON- WILL BE MONITORED & EVALUATED FOR REPAIR.

Notifications:

08/04/09 05:45 PM

DISPUB

TEMPORARY SIGNS POSTED

08/05/09 10:56 AM

DISNOT

Manual email notification of unauthorized discharge sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov

08/04/09 01:00 PM

DISSNO



KPDES#

KY0078956 (Cont'd)

Facility ID MSD0277

Water Quality Treatement Center

DEREK R. GUTHRIE

Receiving Stream of Treatment Center

OHIO RIVER

Region WEST

Facility Type

Facility ID

Facility Address

If Pump Station, Name of Pump Station:

Receiving Stream

Discharge to

Condition

SLS Sewer Lift Station

MSD1010-PS

5006 LEA ANN WAY

LEA ANN WAY

NORTHERN DITCH

STREAM

Activity Code / Description DISREV: RAIN EVENT

WO# 938595

Initiated

Initiated By 08/04/09 12:00 PM SINGLETON

Assigned To οπο

Disch Status DOCUMENTED **Event Date** 12/15/07

<u>Problem</u> LACK OF SYSTEM CAPACITY

Result

DISCHAGE -

WATERS

Completed 08/05/09 01:00 UNAUTHORIZED

AM

DISCHARGE

Spot Inspections:

Discharge Amount

468,000 GAL

Cause:

LACK OF SYSTEM CAPACITY

Clean Up:

MSD CLEANED & SANITIZED THE AREA

Control Zone:

TEMPORARY SIGNS POSTED

Impact

DEBRIS OBSERVED

Repair:

THIS SITE WAS FOUND DURING RAIN EVENT RECON- WILL MONITOR & EVALUATE FOR REPAIR.

Notifications:

08/04/09 01:00 PM

DISNOT

Email notification of unauthorized discharge sent to ireland.sean@epa.gov, eppc.ert@ky.gov and LisaA.Jeffries@ky.gov

08/04/09 12:00 PM

DISPUB

TEMPORARY SIGNS POSTED

08/04/09 01:00 PM

DISSNO



KPDES#

KY0078956 (Cont'd)

Facility ID MSD0277

Water Quality Treatement Center

DEREK R. GUTHRIE

Receiving Stream of Treatment Center

OHIO RIVER

Region WEST

Facility Type

Facility ID

Facility Address

If Pump Station, Name of Pump Station:

Receiving Stream

Discharge to

Condition

SLS Sewer Lift Station

MSD1013-PS

9114 CINDERELLA LN

CINDERELLA

FISHPOOL CREEK

DITCH

Activity Code / Description DISREV: RAIN EVENT

<u>WO#</u> 940818

Init<u>iated</u> 08/04/09 11:00 AM Initiated By SINGLETON

Assigned To THOMPSON

Disch Status DOCUMENTED **Event Date** 11/29/01

Problem LACK OF SYSTEM CAPACITY

Result UNAUTHORIZED DISCHAGE -

WATERS

Completed 08/05/09 01:00

ΑМ

DISCHARGE

Spot inspections:

Discharge Amount

9.999 GAL

Cause:

LACK OF SYSTEM CAPACITY DUE TO AREA FLOODING

Clean Up:

MSD CLEANED & SANITIZED THE AREA

Control Zone:

TEMPORARY SIGNS POSTED

Impact

STATION COMPLETELY SUBMERGED - SEWAGE OBSERVED

Repair.

HAULING- WO#938692

Notifications:

08/04/09 11:00 AM

DISPUB

TEMPORARY SIGNS POSTED

08/07/09 01:11 PM

DISNOT