



Louisville and Jefferson County Metropolitan Sewer District
700 West Liberty Street
Louisville Kentucky 40203-1911
502-540-6000
www.msdlouky.org

Aug 19, 2015

Cheryl Edwards
DMR Coordinator
200 Fair Oaks Lane
Frankfort, Kentucky 40601

**Re: MSD Metro Operations
Hunting Creek South WQTC; KPDES No.: KY 0029114
Discharge Monitoring Report for July 2015**

Dear Ms. Edwards:

Attached are the Discharge Monitoring Reports (DMRs) and the Monthly Operator Report (MOR) for the Hunting Creek South WQTC; KPDES No.: KY0029114 for the month of July.

This plant stopped discharging flow on July 16, 2015. MSD personnel emailed a No Discharge Certification letter to Ann Workman on July 21, 2015.

There were no overflow, exceedences or bypasses reports for the month of July.

Also included are the July overflow reports.

If you have any questions concerning the attached DMRs, please contact me at (502) 587-5832

Sincerely,

John Kessel
Process Supervisor, West region

JK/Hunting Creek South 7/15

Enclosures

CC T. Singleton
R. Shaw
C.Roth



Beneficial Use of Louisville's Biosolids
www.louisvillegreen.com

DMR Copy of Record

Permit

Permit #:

KY0029114

Major:

No

Permittee:

HUNTING CREEK S WQTC MSD

Permittee Address:

6530 MONTERO DR
PROSPECT, KY 40059

Facility:

HUNTING CREEK S WQTC MSD

Facility Location:

6530 MONTERO DR
PROSPECT, KY 40059

Permitted Feature:

001
External Outfall

Discharge:

001-1
MUNICIPAL DISCHARGE

Report Dates & Status

Monitoring Period:

From 07/01/15 to 07/31/15

DMR Due Date:

08/28/15

Status:

NetDMR Validated

Considerations for Form Completion

Principal Executive Officer

First Name:

Greg

Last Name:

Hetizman

Title:

Exec Director

Telephone:

502-540-6000

No Data Indicator (NODI)

Form NODI:

--

51040	E. coli	1 - Effluent Gross	0	--	Sample								=	1	=	1	13 - #/100mL	0	02/30 - Twice Per Month	GR - GRAB
					Permit Req.								<=	130 30DA GEO	<=	240 7 DA GEO	13 - #/100mL		01/07 - Weekly	GR - GRAB
					Value NODI															
80082	BOD, carbonaceous [5 day, 20 C]	1 - Effluent Gross	0	--	Sample	=	2.7	=	2.82	26 - lb/d			=	2	=	2	19 - mg/L	0	02/30 - Twice Per Month	CP - COMPOS
					Permit Req.	<=	20.9 30DA AVG	<=	31.42 DAILY MX	26 - lb/d			<=	10 30DA AVG	<=	15 DAILY MX	19 - mg/L		01/07 - Weekly	24 - COMP24
					Value NODI															

Submission Note

If a parameter row does not contain any values for the Sample nor Effluent Trading, then none of the following fields will be submitted for that row: Units, Number of Excursions, Frequency of Analysis, and Sample Type.

Edit Check Errors

No errors.

Comments

Attachments

Name	Type	Size
Huntsouth_MOR_072015.pdf	pdf	27143
HuntSouth_cover_072015.pdf	pdf	51047
2015_7_HuntingCreekSouth_OverflowReport.pdf	pdf	72799

Report Last Saved By

HUNTING CREEK S WQTC MSD

User: kevin.ries@louisvillemasd.org

Name: Kevin Ries

E-Mail: kevin.ries@louisvillemasd.org

Date/Time:

2015-08-21 09:27 (Time Zone: -04:00)

[illegible]



Report Selections: Period: 07/01/2015 00:00 thru 07/31/2015 23:59, Excluding PPI Excluding CSO Excluding LAT, Result: WUS, Act Code: DISDW, DISREV

KPDES #	Facility ID	Water Quality Treatment Center	Receiving Stream of Treatment Center	Region
KY0029114	MSD0292	HUNTING CREEK SOUTH	HARRODS CREEK	EAST

Facility Type	Facility ID	Facility Address	If Pump Station, Name of Pump Station:	Receiving Stream	Discharge to
SLS Sewer Lift Station	MSD1063-PS	6210 DEEP CREEK CT	DEEP CREEK	HARRODS CREEK	STREAM

Activity Code / Description	WO #	Ref No	Initiated	Initiated By	Assigned To	Disch Status	Event Date	Problem	Result	Completed	Condition
: DISREV: RAIN EVENT DISCHARGE	2388160		07/13/2015	MARKS JR	OPS CSHIFT	DOCUMENTED	12/16/2000	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE - WATERS	07/13/15 06:06 PM	

Discharge Reporting:

Discharge Amount:	2,750 GAL
Cause:	LACK OF SYSTEM CAPACITY DUE TO RAIN EVENT
Clean Up:	PIPE DISCHARGE SUBMERGED- NO CLEANUP
Control Zone:	TEMPORARY SIGNS
Impact:	SEWAGE OBSERVED
Repair:	A SOLUTION FOR THIS LOCATION IS INCLUDED IN THE IOAP
Public Notification:	TEMPORARY SIGNS PLACED AROUND THE AFFECTED AREA

Notifications:

7/13/15 1:00 pm	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO 'DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV'
7/13/15 1:00 pm	DISSNO	SUPPLEMENTAL EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE HAS BEEN SENT TO 'DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV'



Report Selections: Period: 07/01/2015 00:00 thru 07/31/2015 23:59, Excluding PPI Excluding CSO Excluding LAT, Result: WUS, Act Code: DISDW, DISREV

KPDES #	Facility ID	Water Quality Treatment Center	Receiving Stream of Treatment Center	Region
KY0029114	MSD0292	HUNTING CREEK SOUTH	HARRODS CREEK	EAST

Facility Type	Facility ID	Facility Address	If Pump Station, Name of Pump Station:	Receiving Stream	Discharge to
SLS Sewer Lift Station	MSD1064-PS	8619 WESTOVER DR	WESTOVER	HARRODS CREEK	STREAM

Activity Code / Description	WO #	Ref No	Initiated	Initiated By	Assigned To	Disch Status	Event Date	Problem	Result	Completed	Condition
: DISREV: RAIN EVENT DISCHARGE	2388841		07/14/2015	SINGLETON	OPS BSHIFT EAST	BEYOND APPROVED DESIGN STORM	04/03/2015	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE - WATERS	07/14/15 03:15 PM	

Discharge Reporting:

Discharge Amount:	23,400 GAL
Cause:	LACK OF SYSTEM CAPACITY DUE TO RAIN EVENT
Clean Up:	MSD CLEANED & SANITIZED THE AREA
Control Zone:	TEMPORARY SIGNS PLACED
Impact:	SEWAGE OBSERVED
Repair:	A SOLUTION FOR THIS LOCATION IS LOCATED IN THE IOAP
Public Notification:	TEMPORARY SIGNS PLACED AROUND THE AREA

Notifications:

7/14/15 1:00 am	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO 'DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV'
7/14/15 1:00 am	DISSNO	SUPPLEMENTAL EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE HAS BEEN SENT TO 'DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV'