

700 West Liberty Street | Louisville, KY 40203-1911 Phone: 502.540.6000 | LouisvilleMSD.org

March 12, 2025

Crystal Dennis 300 Sower Blvd., 3rd Floor Frankfort, Kentucky 40601

# RE: Hillview #3 STP, KPDES No: KY0034177 Discharge Monitoring Report for February 2025.

Dear Ms. Dennis:

Attached is the Discharge Monitoring Report (DMR) for the Hillview #3 STP, for the month of February 2025.

There was one exceedance for the month. TSS Maximum weekly average sample result 46 mg/l, Permit limit 45mg/l This exceedance was due to heavy flow at plant and cycle blowers on and off from timers.

There was one bypass at the plant for the month. Lack of capacity caused by a rain event.

There was one discharge at a pump station due to rain event and lack of capacity.

Also attached is overflow report.

If you have any questions concerning the attached DMR's, please contact me at (502)540-6717.

Sincerely,

ah

Jon Baldridge Process Supervisor

JOB/ HV#3 02/25.

Cc: V. Teague/B. Tinnell

## **DMR Copy of Record**

EPA may make all the information submitted through this form (including all attachments) available to the public without further notice to you. Do not use this online form to submit personal information (e.g., non-business cell phone number or non-business email address), confidential business information (CBI), or if you intend to assert a CBI claim on any of the submitted information. Pursuant to 40 CFR 2.203(a), EPA is providing you with notice that all CBI claims must be asserted at the time of submission. EPA cannot accommodate a late CBI claim to cover previously submitted information because efforts to protect the information are not administratively practicable since it may already be disclosed to the public. Although we do not foresee a need for persons to assert a claim of CBI based on the types of information requested in this form, if persons wish to assert a CBI claim we direct submitters to contact the NPDES eReporting Help Desk for further guidance. Please note that EPA may contact you after you submit this report for more information.

This collection of information is approved by OMB under the Paperwork Reduction Act, 44 U.S.C. 3501 et seq. (OMB Control No. 2040-0004). Responses to this collection of information are mandatory in accordance with this permit and EPA NPDES regulations 40 CFR 122.41(I)(4)(i). An agency may not conduct or sponsor, and a person is not required to respond to, a collection of information unless it displays a currently valid OMB control number. The public reporting and recordkeeping burden for this collection of information are estimated to average 2 hours per outfall. Send comments on the Agency's need for this information, the accuracy of the provided burden estimates and any suggested methods for minimizing respondent burden to the Regulatory Support Division Director, U.S. Environmental Protection Agency (2821T), 1200 Pennsylvania Ave., NW, Washington, D.C. 20460. Include the OMB control number in any correspondence. Do not send the completed form to this address.

Permit																		
Permit #:		(Y00341	177		1	Permittee:			Louio	/ille and Jet	forces Cr			Feel	ility:		SCSD HILLVIEW #3	
			177															
Major:	Ν	10				Permittee	Address:			700 W Liberty St Louisville, KY 40203					ility Location:		12325 WESTERN RD HILLVIEW, KY 40129	
Permitted		01 External	Outfall							001-1 Domestic Wastewater								
Report Da	ates & Status				ľ													
Monitoring	g Period: F	rom 02	/01/25 to 02/28/25			DMR Due	Date:		03/28/	/25				Stat	us:	٢	letDMR Validated	
Considera	ations for Form Completion													1				
Principal	Executive Officer																	
First Name		ames A			ŀ	Title:			Execu	itive Directo	or			Tele	phone:	5	02-540-6000	
Last Name		Parrott																
	ndicator (NODI)				l													
Form NOE		_																
TOTILINOL	Parameter		Monitoring Location Season #	Param, NOD	1		Qı	antity or Loa	dina				Quality or Conce	entration			# of Ex. Frequency of Analysis	s Sample Type
Code	Name					Qualifier 1		Qualifier 2	-	Units	Qualifier 1	Value 1 Qualifi		Qualifier 3	3 Value 3	Units		
					Sample							7.0				19 - mg/L		GR - Grab
00300	Oxygen, dissolved [DO]		1 - Effluent Gross 0		Permit Req						>=	7.0 INST MIN				19 - mg/L	0 01/07 - Weekly	GR - Grab
					Value NOD													
					Sample							7.3 6.0 MINIMUM			7.8	12 - SU	01/07 - Weekly	GR - Grab GR - Grab
00400	рН		1 - Effluent Gross 0		Permit Req						>=			<=	9.0 MAXIMUM	12 - SU	0 01/07 - Weekly	GR - Grab
					Value NOD	1												
					Sample Permit Reg							=	21.0 30.0 MO AVG	= <=	46.0 45.0 MX WK AV	19 - mg/L 19 - mg/L	01/07 - Weekly 01/07 - Weekly	CP - Composite CP - Composite
X 00530	Solids, total suspended		1 - Effluent Gross 0		Value NOD							~=	50.0 MO AVO	~=		19 - mg/L	1	Ci - Composite
						'I							14.3		19.2	10	04/07 M/s slike	
00000			1 Effluent Onesse 0		Sample Permit Reg							=	Req Mon MO AVG	=	Req Mon DAILY MX	19 - mg/L 19 - mg/L	01/07 - Weekly 01/07 - Weekly	CP - Composite CP - Composite
00600	Nitrogen, total [as N]		1 - Effluent Gross 0		Value NOD											0	0	
					Sample	-							1.1	=	2.2	19 - mg/L	01/07 - Weekly	CP - Composite
00610	Nitrogen, ammonia total [as N]		1 - Effluent Gross 2		Permit Req							<=	10.0 MO AVG	<=	15.0 DAILY MX	19 - mg/L	0 01/07 - Weekly	CP - Composite
00010					Value NOD	1											0	
					Sample							=	1.3	=	2.2	19 - mg/L	01/07 - Weekly	CP - Composite
00665	Phosphorus, total [as P]		1 - Effluent Gross 0		Permit Req								Req Mon MO AVG		Req Mon DAILY MX	19 - mg/L	0 01/07 - Weekly	CP - Composite
					Value NOD	0												
					Sample	=	0.293	=	0.679	03 - MGD							99/99 - Continuous	RC - Recorder (auto)
50050	Flow, in conduit or thru treatmen	t plant	1 - Effluent Gross 0		Permit Req		Req Mon MO AV	G	Req Mon DAILY	MX 03 - MGD							0 99/99 - Continuous	RC - Recorder (auto)
					Value NOD	1												
					Sample													
50060	Chlorine, total residual		1 - Effluent Gross 0		Permit Req	ŀ						<=	0.011 MO AVG	<=	0.019 DAILY MX	19 - mg/L	01/07 - Weekly	GR - Grab
					Value NOD	1							2 - Operation Shutdown		2 - Operation Shutdown			
					Sample							=	67.0	=	204.0	13 - #/100mL	01/07 - Weekly	GR - Grab
51040	E. coli		1 - Effluent Gross 0		Permit Req							<=	130.0 30DA GEO	<=	240.0 7 DA GEO	13 - #/100mL	0 01/07 - Weekly	GR - Grab
					Value NOD	1												
													0.0		14.0	19 - mg/L	04/07 14/	CP - Composite
					Sample Permit Req							= <=	9.0 15.0 MO AVG	= <=	22.5 MX WK AV	19 - mg/L	01/07 - Weekly 01/07 - Weekly	CP - Composite

			Value NODI											
Submissi	ion Note													
If a param	neter row does not contain any v	values for the Sample nor Efflue	ent Trading, then none of the following	g fields will be submitted	d for tha	at row: Units, Number of	Excursions, Freq	quency of Ana	lysis, and Sample	Туре.				
Edit Chec	ck Errors													
	Parameter	Menitoring Looptics	Field	-					Deseri					Asknowladaa
Code	Name	Monitoring Location	Field		Туре				Descri	ption				Acknowledge
00530	Solids, total suspended	1 - Effluent Gross	Quality or Concentration Sample Value	ue 3 Sof	oft	The provided sample valu	e is outside the per	mit limit. Please	e verify that the valu	ie you have pro	vided is correct.			Yes
Comment	its													
Plant no lo	onger uses chlorine. Uses UV p	per client.												
Attachme	ents													
			Name								Туре		Size	
Feb_2025_	_All_Other_Service_area.pdf								pc	df		174890.0		
Hillview3cc	overletter.pdf								pc	df		191780.0		
Report La	ast Saved By													
Louisville	e and Jefferson County MSD													
User:		JON.BAL	DRIDGE@LOUISVILLEMSD.ORG											
Name:		Jonathan	n Baldridge											
E-Mail:		jon.baldri	idge@louisvillemsd.org											
Date/Time	э:	2025-03-2	21 10:04 (Time Zone: -04:00)											
Report La	ast Signed By													
User:		JON.BAL	DRIDGE@LOUISVILLEMSD.ORG											
Name:		Jonathan	n Baldridge											
E-Mail:		jon.baldri	idge@louisvillemsd.org											

2025-03-21 10:04 (Time Zone: -04:00)

Date/Time:



KPDES #	Facility ID	Water 0	Quality Treatm	ent Center	Recieving Stea	am of Discharge	Region						
KY0078956	MSD0277	DEREK	R. GUTHRIE		OHIO RIVER		NA						
Facility Type	Facility ID	Facility	Address	If Pump Statio	n, Name of Static	on	Recieving St	ream	Discharge To				
Sewer Manhole	32682	6707 W	ORELL RD	DEREK R. GU	THRIE		ALVEY DITC	4	STREAM				
Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition		
DISREV:RAIN EVENT DISCHARGE	3899268		2/15/2025 11:00:00 PM	SANTEE 1	SANTEE	QUEUED FOR INVESTIGATIO N / REPAIR	2/15/2025 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE- WATERS	02/17/25 10:10 AM			

## Discharge Reporting:

Discharge Amount:	3,000 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	MSD PERSONNEL CLEANED AND SANITIZED THE IMPACTED AREA.
Control Zone:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.
Impact:	SEWAGE/DEBRIS FOUND ON THE GROUND.
Repair:	MSD CONTRACTOR VACTORED SCUM THROUGH AND REMOVED HEAVY SCUM.
Public Notification:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.

2/16/25 1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
2/16/25 1:00 AM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



KPDES #	Facility ID	Water C	uality Treatm	ent Center	Recieving Stea	Recieving Steam of Discharge		Region					
KY0078956	MSD0277	DEREK	R. GUTHRIE		OHIO RIVER		NA						
Facility Type	Facility ID	Facility	Address	If Pump Statio	n, Name of Statio	on	Recieving St	ream	Discharge To				
Sewer Manhole	93703	8800 A	DMIRAL DR	DEREK R. GU	THRIE		PENNSYLVA	NIA RUN	GROUND				
Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition		
DISREV:RAIN EVENT DISCHARGE	3902774		2/18/2025 3:15:00 PM	PARKER	PARKER	DOCUMENTED	3/24/2018 12:00:00 AM	ELECTRICAL PROBLEMS AT MSD	UNAUTHORIZED DISCHARGE- WATERS	02/18/25 08:15 PM			

#### Discharge Reporting:

Discharge Amount:	600,000 GAL
Cause:	POWER OUTAGE (MAIN BREAKER MALFUNCTION).
Clean Up:	CLEANED AND SANITIZED THE IMPACTED AREA.
Control Zone:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.
Impact:	SEWAGE DEBRIS.
Repair:	BYPASSED MAIN BREAKER.
Public Notification:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.

#### Notifications:

2/19/25 1:00 AM DISNOT EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV



KPDES #	Facility ID	Water 0	Water Quality Treatment Center			am of Discharge	Region					
KY0102784	MSD0294	FLOYD	S FORK		FLOYDS FORK	K	NA					
Facility Type	Facility ID	Facility	Address	If Pump Station	n, Name of Statio	on	Recieving St	ream	Discharge To			
Sewer Treatment Plant	MSD0294	1100 E RD	BLUE HERON	FLOYDS FORK	ζ.		FLOYDS FOF	RK	STREAM			
Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition	
DISREV:RAIN EVENT DISCHARGE	3897554		2/5/2025 5:39:00 PM	SANTEE	SANTEE	REPAIRED - ISSUE RESOLVED	2/5/2025 12:00:00 AM	BYPASS AT WQTC	UNAUTHORIZED DISCHARGE- WATERS	02/05/25 05:57 PM		

### Discharge Reporting:

Discharge Amount:	23,750 GAL
Cause:	BYPASS AT WASTEWATER TREATMENT PLANT.
Clean Up:	CLEANUP NOT POSSIBLE DUE TO ELEVATED CREEK LEVEL.
Control Zone:	PERMANENT SIGN IN PLACE – NO ADDITIONAL CONTROL ZONE SET UP.
Impact:	NO IMPACT OBSERVED – BYPASS WAS DUE TO UV SYSTEM FAULT, END OF TREATMENT PROCESS.
Repair:	INVESTIGATION INDICATED THAT ADDITIONAL REPAIRS WERE NOT REQUIRED BY MSD.
Public Notification:	5 DAY LETTER TO THE STATE.

2/6/25 1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG,
		SAYRE.DENNIS@EPAMAIL.EPA.GOV



KPDES #	Facility ID	D Water Quality Treatment Center			Recieving Stea	am of Discharge	Region					
KY0111716	MSD0414	SOUTH	OLDHAM		SOUTH FORK CREEK	HARRODS	NA					
Facility Type	Facility ID	Facility	Address	If Pump Statio	on, Name of Static	on	Recieving St	ream	Discharge To			
Sewer Treatment Plant	MSD0414	6115 H	HITT LN	SOUTH OLDH	АМ		SOUTH FOR	K HARRODS CREEK	STREAM			
Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition	
DISREV:RAIN EVENT DISCHARGE	3898557		2/12/2025 3:15:00 AM	ROY	OPERATOR	REPAIRED - ISSUE RESOLVED	2/12/2025 12:00:00 AM	BYPASS AT WQTC	UNAUTHORIZED DISCHARGE- WATERS	02/12/25 03:20 AM		

### Discharge Reporting:

Discharge Amount:	150 GAL
Cause:	ELECTRICAL PROBLEM WITH MSD EQUIPMENT (UV SYSTEM OVER TEMP FAULT).
Clean Up:	CLEANED AND SANITIZED THE IMPACTED AREA.
Control Zone:	NO CONTROL ZONE SET UP.
Impact:	EFFLUENT ON GROUND.
Repair:	RESET FAULT.
Public Notification:	5 DAY LETTER.

2/12/25 1:00 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
2/12/25 1:00 PM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



KPDES #	Facility ID	Water Quality Treatment Center		Recieving Steam of Discharge		Region					
KY0034151	MSD0506	BCSD H	HILLVIEW #1		TANYARD BRA	ANCH					
Facility Type	Facility ID	Facility	Facility Address If Pump Station		, Name of Station		Recieving Stream		Discharge To		
Sewer Treatment Plant	MSD0506	253 LE	EES LN BCSD HILLVIEW #1			TANYARD BRANCH		STREAM			
Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3899146		2/15/2025 6:14:00 PM	SANTEE	SANTEE	DOCUMENTED	1/8/2022 12:00:00 AM	BYPASS AT WQTC	UNAUTHORIZED DISCHARGE- WATERS	02/16/25 12:21 AM	

### Discharge Reporting:

Discharge Amount:	8,400 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	CLEANED AND SANITIZED THE IMPACTED AREA.
Control Zone:	OVERFLOW CONTAINED ON MSD PROPERTY.
Impact:	INF TO CONCRETE DITCH.
Repair:	FLOW WENT DOWN ALLOWED PUMPS TO CATCH UP.
Public Notification:	PERMANENT SIGN IN PLACE – NO ADDITIONAL CONTROL ZONE SET UP.

2/16/25	5 1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
2/16/25	5 1:00 AM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



KPDES #	Facility ID	Water Quality Treatment Center		Recieving Steam of Discharge		Region					
KY0034169	MSD0507	BCSD H	HILLVIEW #2		BROOKS RUN						
Facility Type	Facility ID	Facility Address If Pump Station		, Name of Station		Recieving Stream		Discharge To			
Sewer Treatment Plant	MSD0507	376 NG	376 NORWOOD DR BCSD HILLVIEV		V #2		BROOKS RUN		STREAM		
Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3897589		2/6/2025 1:13:00 AM	SANTEE	SANTEE	DOCUMENTED	12/6/2021 12:00:00 AM	BYPASS AT WQTC	UNAUTHORIZED DISCHARGE- WATERS	02/06/25 11:00 PM	

### Discharge Reporting:

Discharge Amount:	17,490 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	CLEANED AND SANITIZED THE IMPACTED AREA.
Control Zone:	OVERFLOW CONTAINED ON MSD PROPERTY.
Impact:	INF TO CONCRETE DITCH.
Repair:	FLOW WENT DOWN ALLOWED PUMPS TO CATCH UP.
Public Notification:	PERMANENT SIGN IN PLACE – NO ADDITIONAL CONTROL ZONE SET UP.

2/6/25 1	:00 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
2/6/25 1	:00 PM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



KPDES #	Facility ID	Water Quality Treatment Center		Recieving Steam of Discharge		Region					
KY0034169	MSD0507	BCSD H	HILLVIEW #2		BROOKS RUN						
Facility Type	Facility ID	Facility Address If Pump Station			, Name of Station		Recieving Stream		Discharge To		
Sewer Treatment Plant	MSD0507	376 NG	NORWOOD DR BCSD HILLVIEW #2		N #2	BROOKS RUN			STREAM		
Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3898063		2/8/2025 7:00:00 AM	SUTHERLAND	SUTHERLAND	DOCUMENTED	12/6/2021 12:00:00 AM	BYPASS AT WQTC	UNAUTHORIZED DISCHARGE- WATERS	02/08/25 11:00 PM	

### Discharge Reporting:

Discharge Amount:	19,200 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	CLEANED AND SANITIZED THE IMPACTED AREA.
Control Zone:	OVERFLOW CONTAINED ON MSD PROPERTY.
Impact:	SEWAGE FOUND IN THE DITCH.
Repair:	FLOW WENT DOWN ALLOWED PUMPS TO CATCH UP.
Public Notification:	PERMANENT SIGN IN PLACE – NO ADDITIONAL CONTROL ZONE SET UP

2/8/25 1:00 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
2/8/25 1:00 PM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



KPDES #	Facility ID	Water Quality Treatment Center		Recieving Steam of Discharge		Region					
KY0034169	MSD0507	BCSD H	HILLVIEW #2		BROOKS RUN						
Facility Type	Facility ID	Facility Address If Pump Station			n, Name of Static	, Name of Station		Recieving Stream		Discharge To	
Sewer Treatment Plant	MSD0507	376 NORWOOD DR BCSD HILLVIE			N #2		BROOKS RUN		STREAM		
Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3898545		2/11/2025 7:50:00 PM	SANTEE	SANTEE	DOCUMENTED	12/6/2021 12:00:00 AM	BYPASS AT WQTC	UNAUTHORIZED DISCHARGE- WATERS	02/11/25 08:15 PM	

### Discharge Reporting:

Discharge Amount:	500 GAL
Cause:	ELECTRICAL PROBLEM WITH MSD EQUIPMENT (PUMP OVERLOADED).
Clean Up:	CLEANUP NOT POSSIBLE DUE TO ELEVATED CREEK LEVEL.
Control Zone:	PERMANENT SIGN IN PLACE – NO ADDITIONAL CONTROL ZONE SET UP.
Impact:	SEWAGE FOUND AROUND MANHOLE.
Repair:	REPAIRED THE (RESET PUMP, SCHEDULED TO PULL).
Public Notification:	5 DAY LETTER TO STATE.

2	(12/25 1:00 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
2	(12/25 1:00 PM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



KPDES #	Facility ID	Water C	Quality Treatm	ent Center	Recieving Stea	am of Discharge	Region				
KY0034169	MSD0507	BCSD H	HILLVIEW #2		BROOKS RUN						
Facility Type	Facility ID Facility Address If Pump Station, Name of Station		on	Recieving Stream		Discharge To					
Sewer Treatment Plant	MSD0507	376 NG	DRWOOD DR	BCSD HILLVIE	SD HILLVIEW #2 BROOKS RUN		Ν	STREAM			
Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3899141		2/15/2025 5:38:00 PM	SANTEE	SANTEE	DOCUMENTED	12/6/2021 12:00:00 AM	BYPASS AT WQTC	UNAUTHORIZED DISCHARGE- WATERS	02/16/25 09:30 PM	

### Discharge Reporting:

Discharge Amount:	51,870 GAL
Cause:	BYPASS AT WASTEWATER TREATMENT PLANT.
Clean Up:	CLEANUP NOT POSSIBLE DUE TO ELEVATED CREEK LEVEL.
Control Zone:	PERMANENT SIGN IN PLACE – NO ADDITIONAL CONTROL ZONE SET UP.
Impact:	SEWAGE FOUND AROUND MANHOLE.
Repair:	REPAIRED THE (RESET PUMP, SCHEDULED TO PULL).
Public Notification:	5 DAY LETTER TO STATE.

2/16/25 1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
2/16/25 1:00 AM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



KPDES #	Facility ID	Water C	Quality Treatm	ent Center	Recieving Stea	am of Discharge	Region				
KY0034177	MSD0508	BCSD H	IILLVIEW #3		BROOKS RUN						
Facility Type	Facility ID	ID Facility Address If Pump Station, Name of Station		Recieving Stream		Discharge To					
Sewer Treatment Plant	MSD0508	126 W	ESTERN RD	BCSD HILLVIE	ILLVIEW #3 BROOKS RUN		N	STREAM			
Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3899192		2/15/2025 9:02:00 PM	SANTEE	SANTEE	DOCUMENTED	3/29/2023 12:00:00 AM	BYPASS AT WQTC	UNAUTHORIZED DISCHARGE- WATERS	02/16/25 08:16 PM	

### Discharge Reporting:

Discharge Amount:	71,650 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	CLEANED UP DEBRIS FROM EFF CONTACT TANK AND DISCHARGE.
Control Zone:	INSIDE OF PLANT.
Impact:	INF TO THE CHLORINE CONTACT TANK.
Repair:	FLOW DROPPED AND PUMPS CAUGHT UP.
Public Notification:	SIGN NEXT TO DISCHARGE.

2	/16/25 1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
2	/16/25 1:00 AM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



KPDES #	Facility ID	Water C	Quality Treatm	ent Center	Recieving Steam of Discharge Region						
KY0034801	MSD0509	BULLIT	T HILLS		TANYARD BRA	NCH					
Facility Type	cility Type Facility ID Facility Address If Pump Station, Name of Station		n	Recieving Stream Discharge T		Discharge To					
Sewer Treatment Plant	MSD0509	233 M/ RD	AYFLOWER	BULLITT HILLS			TANYARD BRANCH		STREAM		
Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3899484		2/16/2025 12:24:00 PN	ROY	ROY	DOCUMENTED	3/9/2023 12:00:00 AM	BYPASS AT WQTC	UNAUTHORIZED DISCHARGE- WATERS	02/16/25 12:40 PM	

### Discharge Reporting:

Discharge Amount:	480 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	NO CLEAN UP PERFORMED.
Control Zone:	INSIDE THE FENCE. SIGNS POSTED.
Impact:	NONE OBSERVED BY MSD PERSONNEL.
Repair:	PLACING PLUG INTO PIPE.
Public Notification:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.

2	2/16/25 1:00 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
2	2/16/25 1:00 PM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



KPDES #	Facility ID	Water C	Quality Treatm	ent Center	Recieving Stea	am of Discharge	Region				
KY0034185	MSD0512	PIONEE	ER VILLAGE # <sup>2</sup>	1	BROOKS RUN						
Facility Type	acility Type Facility ID Facility Address If Pump Station, Name of Station		on	Recieving Stream Discharge To							
Sewer Treatment Plant	MSD0512	815 JC HWY	OHN HARPER	PIONEER VILL	AGE #1		BROOKS RUN		STREAM		
Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3899143		2/15/2025 5:43:00 PM	SANTEE	SANTEE	DOCUMENTED	3/8/2023 12:00:00 AM	BYPASS AT WQTC	UNAUTHORIZED DISCHARGE- WATERS	02/15/25 11:21 PM	

### Discharge Reporting:

Discharge Amount:	16,500 GAL
Cause:	HEAVY RAIN LACK OF CAPACITY.
Clean Up:	NONE NEEDED, INF WAS CONTAINED IN THE PLANT BEFORE DISCHARGING TO EFF.
Control Zone:	NONE NEEDED.
Impact:	INF BYPASS TO CHLORINE CONTACT TANK.
Repair:	SET UP ADDITIONAL PUMP TO PUMP TO PLANT AND STOP BYPASS.
Public Notification:	NONE NEEDED.

2/16/25 1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
2/16/25 1:00 AM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



KPDES #	Facility ID	Water Quality Treatment Center			Recieving Stea	Recieving Steam of Discharge Region					
KY0034185	MSD0512	PIONEE	R VILLAGE #	1	BROOKS RUN						
Facility Type	Facility ID	Facility	acility Address If Pump Station, Nam			Name of Station		Recieving Stream		Discharge To	
Sewer Treatment Plant	MSD0512	815 JC HWY			AGE #1		BROOKS RUN		STREAM		
Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3899505		2/16/2025 1:33:00 PM	ROY	ROY	DOCUMENTED	3/8/2023 12:00:00 AM	BYPASS AT WQTC	UNAUTHORIZED DISCHARGE- WATERS	02/16/25 02:04 PM	

### Discharge Reporting:

Discharge Amount:	1,080 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	MSD PERSONNEL CLEANED AND SANITIZED THE IMPACTED AREA.
Control Zone:	INSIDE FENCE OF PLANT.
Impact:	DEBRIS ON GROUND.
Repair:	INFLUENT FLOW SLOWED DOWN LETTING PUMPS CATCH UP.
Public Notification:	5 DAY LETTER TO STATE.

2/1	7/25 1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
2/1	7/25 1:00 AM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



KPDES #	Facility ID	Water 0	Water Quality Treatment Center			am of Discharge	Region				
KY0034801	MSD0509	BULLIT	T HILLS		TANYARD BRA	NCH					
Facility Type	Facility ID	Facility Address If Pump Statio		, Name of Station		Recieving Stream		Discharge To			
Sewer Lift Station	SSPSBH- TSP1	258 CI DR					TANYARD BRANCH		STREAM		
Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3899379		2/16/2025 8:00:00 AM	LONG	BOUTIN	BEYOND APPROVED DESIGN STORM	2/15/2025 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE- WATERS	02/16/25 01:00 PM	

### Discharge Reporting:

Discharge Amount:	15,000 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	CLEANED AND SANITIZED THE IMPACTED AREA.
Control Zone:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.
Impact:	SEWAGE/DEBRIS/SOLIDS/PERSONAL HYGIENE PRODUCTS FOUND AROUND MANHOLE.
Repair:	SITE FOUND DURING RAIN EVENT RECON - WILL BE MONITORED AND EVALUATED FOR REPAIR.
Public Notification:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.

2/16/25 1:00 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
2/16/25 1:00 PM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



KPDES #	Facility ID	Water Quality Treatment Center			Recieving Stea	am of Discharge	Region					
KY0078956	MSD0277	DEREK	REK R. GUTHRIE		OHIO RIVER	OHIO RIVER		NA				
Facility Type	Facility ID	Facility	Address	If Pump Statio	n, Name of Static	, Name of Station		Recieving Stream		Discharge To		
Sewer Lift Station	SSPSDG- ADMI	8800 A	ADMIRAL DR	DEREK R. GU	HRIE		PENNSYLVANIA RUN		STREAM			
Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition	
DISREV:RAIN EVENT DISCHARGE	3899312		2/16/2025 1:24:00 AM	HUBER IV	HUBER IV	DOCUMENTED	4/20/2019 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE- WATERS	02/17/25 11:20 AM		

### Discharge Reporting:

Discharge Amount:	800 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	CLEAN AND SANITIZE IMPACTED AREA.
Control Zone:	PLACED TEMPORARY SIGNS AT SITE.
Impact:	SEWAGE DEBRIS AROUND AREA.
Repair:	SCADA INDICATED.
Public Notification:	PLACED TEMPORARY SIGNS AT SITE.

2/	(16/25 1:00 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
2/	(16/25 1:00 PM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



KPDES #	Facility ID	Water Quality Treatment Center		Recieving Steam of Discharge		Region					
KY0078956	MSD0277	DEREK R. GUTHRIE			OHIO RIVER		NA				
Facility Type	Facility ID	Facility Address If Pump Statio			n, Name of Station		Recieving Stream		Discharge To		
Sewer Lift Station	SSPSDG- CIND	9114 C LN				HRIE		FISHPOOL CREEK		DITCH	
Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3899270		2/16/2025 11:20:00 AN	SOSA I RODRIGUEZ	SOSA RODRIGUEZ	BEYOND APPROVED DESIGN STORM	2/15/2025 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE- WATERS	02/17/25 07:38 AM	

### Discharge Reporting:

Discharge Amount:	108,000 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	MSD PERSONNEL CLEANED AND SANITIZED THE IMPACTED AREA.
Control Zone:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.
Impact:	SITE FOUND DURING RAIN EVENT RECON- WILL MONITOR & EVALUATE FOR REPAIR.
Repair:	NO REPAIRS REQUIRED.
Public Notification:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.

2/16/25 1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
2/16/25 1:00 AM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



KPDES #	Facility ID	Water C	Quality Treatm	ent Center	Recieving Stea	am of Discharge	Region							
KY0078956	MSD0277	DEREK	R. GUTHRIE		OHIO RIVER	OHIO RIVER		NA						
Facility Type	Facility ID	Facility	Address	If Pump Statio	n, Name of Station		Recieving Stream		Discharge To					
Sewer Lift Station	SSPSDG- LAN1	9317 L	ANTANA DR	DEREK R. GUI	HRIE		PENNSYLVANIA RUN		DITCH					
Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition			
DISREV:RAIN EVENT DISCHARGE	3600326		2/16/2025 12:11:00 AM	BUTLER	BUTLER	DOCUMENTED	3/18/2013 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE- WATERS	02/18/25 09:19 AM				

### Discharge Reporting:

Discharge Amount:	42,000 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	CLEANUP NOT POSSIBLE DUE TO MAGNITUDE OF STORM.
Control Zone:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.
Impact:	SEWAGE/DEBRIS/SOLIDS/PERSONAL HYGIENE PRODUCTS FOUND ON THE GROUND.
Repair:	SITE FOUND DURING RAIN EVENT RECON - WILL BE MONITORED AND EVALUATED FOR REPAIR.
Public Notification:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.



KPDES #	Facility ID	Water C	Quality Treatm	ent Center	Recieving Stea	am of Discharge	Region				
KY0078956	MSD0277	DEREK	R. GUTHRIE		OHIO RIVER	D RIVER NA					
Facility Type	Facility ID	Facility	Address	If Pump Station	n, Name of Static	Name of Station Recieving Stream		Discharge To			
Sewer Lift Station	SSPSDG- LAN1	9317 L	ANTANA DR	DEREK R. GUT	THRIE		PENNSYLVA	NIA RUN	DITCH		
Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3899282		2/16/2025 12:15:00 AM	SOSA I RODRIGUEZ	SOSA RODRIGUEZ	DOCUMENTED	3/18/2013 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE- WATERS	02/16/25 01:18 PM	

### Discharge Reporting:

Discharge Amount:	78,000 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	CLEANUP NOT POSSIBLE DUE TO MAGNITUDE OF STORM.
Control Zone:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.
Impact:	SEWAGE/DEBRIS/SOLIDS/PERSONAL HYGIENE PRODUCTS FOUND ON THE GROUND.
Repair:	SITE FOUND DURING RAIN EVENT RECON - WILL BE MONITORED AND EVALUATED FOR REPAIR.
Public Notification:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.

2/16/25 1:00 A	M	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
2/16/25 1:00 A	M	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



KPDES #	Facility ID	Water G	Quality Treatm	ent Center	Recieving Stea	m of Discharge	Region				
KY0034169	MSD0507	BCSD H	IILLVIEW #2		BROOKS RUN						
Facility Type	ype Facility ID Facility Address If Pump Station, Name of Station Recieving Stream		Discharge To								
Sewer Lift Station	SSPSH2- HLV2	H2- 319 WINSTON CT		BCSD HILLVIEW #2			BROOKS RUN		STREAM		
Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3899327		2/16/2025 11:00:00 AM	SOSA I RODRIGUEZ	GENERAL MAINTENANCE	DOCUMENTED	12/11/2021 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE- WATERS	02/16/25 01:00 PM	

### Discharge Reporting:

Discharge Amount:	3,960 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	CLEANUP NOT POSSIBLE DUE TO MAGNITUDE OF STORM.
Control Zone:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.
Impact:	SEWAGE/DEBRIS/SOLIDS/PERSONAL HYGIENE PRODUCTS FOUND IN THE STREAM.
Repair:	SITE FOUND DURING RAIN EVENT RECON - WILL BE MONITORED AND EVALUATED FOR REPAIR.
Public Notification:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.

2/16/	/25 1:00 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
2/16/	/25 1:00 PM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



KPDES #	Facility ID	Water C	Quality Treatm	ent Center	Recieving Stea	am of Discharge	Region				
KY0034177	MSD0508	BCSD H	HILLVIEW #3		BROOKS RUN	ROOKS RUN					
Facility Type	Facility ID Facility Address If Pump Station, Name of Station Recieving Stream		Discharge To								
Sewer Lift Station	SSPSH3- HLV3	169 SI	JMMERS DR	BCSD HILLVIE	N #3		BROOKS RU	N	STREAM		
Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3899169		2/15/2025 6:51:00 PM	JACKSON	MILES	DOCUMENTED	12/9/2021 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE- WATERS	02/18/25 09:13 AM	

### Discharge Reporting:

Discharge Amount:	420 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	NO CLEAN UP PERFORMED – PIPE DISCHARGING UNDERWATER, DIRECTLY INTO STREAM.
Control Zone:	PLACED TEMPORARY SIGNS AROUND THE IMPATED AREA.
Impact:	NO VISUAL OBSERVATIONS – PIPE DISCHARGING UNDERWATER, DIRECTLY INTO STREAM.
Repair:	SITE FOUND DURING RAIN EVENT RECON. WILL BE MONITORED AND EVALUATED FOR REPAIR.
Public Notification:	PLACED TEMPORARY SIGNS AROUND THE IMPATED AREA.

2/16/25 1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
2/16/25 1:00 AM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



KPDES #	Facility ID	Water (	Water Quality Treatment Center		Recieving Steam of Discharge		Region				
KY0022420	MSD0202	HITE C	CREEK		HITE CREEK		NA				
Facility Type	Facility ID	Facility Address If Pump Statio		on, Name of Statio	n, Name of Station		Recieving Stream D		Discharge To		
Sewer Lift Station	SSPSHC- KAVR	7520 ł RD	KAVANAUGH	HITE CREEK			HITE CREEK		GROUND		
Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3899308		2/16/2025 12:43:00 AM	HUBER IV	HUBER IV	DOCUMENTED	5/11/2003 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE- WATERS	02/17/25 07:58 AM	

### Discharge Reporting:

Discharge Amount:	27,000 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	CLEANED AND SANITIZED SURROUNDING AREAS.
Control Zone:	TEMPORARY SIGNS PLACED ON SITE.
Impact:	SEWAGE DEBRIS.
Repair:	SCADA INDICATED.
Public Notification:	TEMPORARY SIGNS PLACED ON SITE.

2/1	6/25 1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
2/1	6/25 1:00 AM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



KPDES #	Facility ID	Water 0	Water Quality Treatment Center		Recieving Steam of Discharge		Region				
KY0040126	MSD0411	KSR	KSR		CEDAR CREEK		NA				
Facility Type	Facility ID	Facility	Facility Address If Pump Station		n, Name of Station		Recieving Stream		Discharge To		
Sewer Lift Station	SSPSKS- DISW	1815 N STHY 393 KSR				CURRYS FORK		GROUND			
Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3897591		2/6/2025 7:14:00 AM	PARKER	PARKER	QUEUED FOR INVESTIGATIO N / REPAIR	1/12/2023 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE- WATERS	02/07/25 07:31 AM	

### Discharge Reporting:

Discharge Amount:	4,125 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	MSD PERSONNEL CLEANED AND SANITIZED THE IMPACTED AREA.
Control Zone:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.
Impact:	NONE OBSERVED BY MSD PERSONNEL.
Repair:	SITE FOUND DURING RAIN EVENT RECON - WILL BE MONITORED AND EVALUATED FOR REPAIR.
Public Notification:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.

2/6/25 1:00 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
2/6/25 1:00 PM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



KPDES #	Facility ID	Water Quality Treatment Center		Recieving Steam of Discharge		Region					
KY0040126	MSD0411	KSR	KSR		CEDAR CREEK		NA				
Facility Type	Facility ID	Facility	Facility Address If Pump Station		n, Name of Static	, Name of Station		Recieving Stream		Discharge To	
Sewer Lift Station	SSPSKS- DISW	1815 N STHY 393 KSR				CURRYS FORK		GROUND			
Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3897909		2/7/2025 7:51:00 AM	PARKER	PARKER	QUEUED FOR INVESTIGATIO N / REPAIR	1/12/2023 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE- WATERS	02/10/25 07:53 AM	

### Discharge Reporting:

Discharge Amount:	6,000 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	CLEANED AND SANITIZED THE IMPACTED AREA.
Control Zone:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.
Impact:	NONE OBSERVED BY MSD PERSONNEL.
Repair:	SITE FOUND DURING RAIN EVENT RECON - WILL BE MONITORED AND EVALUATED FOR REPAIR.
Public Notification:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.

2/7/25 1:00 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
2/7/25 1:00 PM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



KPDES #	Facility ID	Water Quality Treatment Center		Recieving Steam of Discharge		Region					
KY0040126	MSD0411	KSR	KSR		CEDAR CREEK		NA				
Facility Type	Facility ID	Facility	Facility Address If Pump Station,		, Name of Station		Recieving Stream		Discharge To		
Sewer Lift Station	SSPSKS- DISW	1815 N	STHY 393	KSR			CURRYS FO	RK	GROUND		
Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3899310		2/16/2025 12:55:00 AM	HUBER IV	HUBER IV	QUEUED FOR INVESTIGATIO N / REPAIR	1/12/2023 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE- WATERS	02/17/25 11:23 AM	

### Discharge Reporting:

Discharge Amount:	400 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	CLEANED AND SANITIZED IMPACTED AREA.
Control Zone:	PLACED TEMPORARY SIGNS.
Impact:	NONE PRESENT.
Repair:	FOUND DURING RECON.
Public Notification:	PLACED TEMPORARY SIGNS.

2/	(16/25 1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
2/	(16/25 1:00 AM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



KPDES #	Facility ID	Water 0	Water Quality Treatment Center		Recieving Steam of Discharge R		Region				
KY0106143	MSD0407		RIVER		OHIO RIVER		NA				
Facility Type	Facility ID	Facility	Facility Address If Pump Station,		n, Name of Statio	, Name of Station		Recieving Stream		Discharge To	
Sewer Lift Station	SSPSOR- CBRD	13301	STHY 329	OHIO RIVER			HARRODS C	REEK	GROUND		
Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3899292		2/15/2025 11:25:00 AN	HUBER IV	HUBER IV	QUEUED FOR INVESTIGATIO N / REPAIR	3/24/2023 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE- WATERS	02/17/25 07:48 AM	

### Discharge Reporting:

Discharge Amount:	51,000 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	CLEANUP NOT POSSIBLE DUE TO MAGNITUDE OF STORM.
Control Zone:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.
Impact:	SEWAGE FOUND ON THE GROUND.
Repair:	SITE FOUND DURING RAIN EVENT RECON - WILL BE MONITORED AND EVALUATED FOR REPAIR.
Public Notification:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.

2/16/25	1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
2/16/25	1:00 AM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



KPDES #	Facility ID	Water Quality Treatment Center		Recieving Steam of Discharge		Region					
KY0094307	MSD0511	WILLAE	ROOK		BROOKS RUN						
Facility Type	Facility ID	Facility	Facility Address If Pump Station,		n, Name of Station		Recieving Stream		Discharge To		
Sewer Lift Station	SSPSWB- MATL	3955 E RD	BLUE LICK	WILLABROOK			BROOKS RU	Ν	GROUND		
Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3897740		2/6/2025 8:02:00 AM	PARKER	PARKER	DOCUMENTED	1/1/1992 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE- WATERS	02/07/25 07:38 AM	

### Discharge Reporting:

Discharge Amount:	40,700 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	NO CLEAN UP PERFORMED – PIPE DISCHARGING UNDERWATER, DIRECTLY INTO STREAM.
Control Zone:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.
Impact:	NONE OBSERVED - OUTLETS SUBMERGED.
Repair:	SITE FOUND DURING RAIN EVENT RECON - WILL BE MONITORED AND EVALUATED FOR REPAIR.
Public Notification:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.

2/6/25 1:00 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
2/6/25 1:00 PM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



KPDES #	Facility ID	Water C	Water Quality Treatment Center		Recieving Steam of Discharge		Region				
KY0094307	MSD0511	WILLAE	BROOK		BROOKS RUN						
Facility Type	Facility ID	Facility	Facility Address If Pump Station		n, Name of Station		Recieving Stream		Discharge To		
Sewer Lift Station	SSPSWB- MATL	3955 E RD	BLUE LICK	WILLABROOK			BROOKS RU	Ν	GROUND		
Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3898580		2/12/2025 11:47:00 AM	BROADEN 1	BROADEN	DOCUMENTED	1/1/1992 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE- WATERS	02/12/25 11:54 AM	

### Discharge Reporting:

Discharge Amount:	4,000 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	NO CLEAN UP PERFORMED – PIPE DISCHARGING UNDERWATER, DIRECTLY INTO STREAM.
Control Zone:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.
Impact:	NONE OBSERVED - OUTLETS SUBMERGED.
Repair:	SITE FOUND DURING RAIN EVENT RECON - WILL BE MONITORED AND EVALUATED FOR REPAIR.
Public Notification:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.

2/12/25 1:00 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG,
		SAYRE.DENNIS@EPAMAIL.EPA.GOV



KPDES #	Facility ID	Water Quality Treatment Center		Recieving Steam of Discharge		Region					
KY0094307	MSD0511	WILLAE	ROOK		BROOKS RUN						
Facility Type	Facility ID	Facility	Facility Address If Pump Station,		, Name of Station		Recieving Stream		Discharge To		
Sewer Lift Station	SSPSWB- MATL	3955 E RD	BLUE LICK	WILLABROOK			BROOKS RU	Ν	GROUND		
Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3899138		2/15/2025 4:48:00 PM	JACKSON	MILES	DOCUMENTED	1/1/1992 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE- WATERS	02/18/25 09:18 AM	

### Discharge Reporting:

Discharge Amount:	27,700 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	NO CLEAN UP PERFORMED – PIPE DISCHARGING UNDERWATER, DIRECTLY INTO STREAM.
Control Zone:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.
Impact:	NONE OBSERVED BY MSD PERSONNEL.
Repair:	INVESTIGATION INDICATED THAT ADDITIONAL REPAIRS WERE NOT REQUIRED BY MSD.
Public Notification:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.

2/16/25	1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
2/16/25	1:00 AM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION