



700 West Liberty Street | Louisville, KY 40203-1911
Phone: 502.540.6000 | LouisvilleMSD.org

May 19, 2025

Crystal Dennis
300 Sower Blvd., 3rd Floor
Frankfort, Kentucky 40601

**RE: Cedar Creek WQTC, KPDES No: KY0098540
Discharge Monitoring Report for April 2025.**

Dear Mrs. Dennis:

Attached are the Discharge Monitoring Report (DMR) and the Monthly Operator Report (MOR) for the Cedar Creek WQTC, for the month of April 2025.

There were no exceedances or bypasses to report.

There were 4 overflows in the collection system due to rain event and lack of capacity.

Also attached is a Monthly Discharge Report.

If you have any questions concerning the attached DMR's, please contact me at (502)540-6717.

Sincerely,

A handwritten signature in blue ink, appearing to read 'Jon Baldrige', written over a light blue horizontal line.

Jon Baldrige
Process Supervisor

JOB/ Cedar Creek. 04/25.

Enclosures

Cc: V. Graves
B. Tinnell

EPA may make all the information submitted through this form (including all attachments) available to the public without further notice to you. Do not use this online form to submit personal information (e.g., non-business cell phone number or non-business email address), confidential business information (CBI), or if you intend to assert a CBI claim on any of the submitted information. Pursuant to 40 CFR 2.203(a), EPA is providing you with notice that all CBI claims must be asserted at the time of submission. EPA cannot accommodate a late CBI claim to cover previously submitted information because efforts to protect the information are not administratively practicable since it may already be disclosed to the public. Although we do not foresee a need for persons to assert a claim of CBI based on the types of information requested in this form, if persons wish to assert a CBI claim we direct submitters to contact the [NPDES eReporting Help Desk](#) for further guidance. Please note that EPA may contact you after you submit this report for more information.

This collection of information is approved by OMB under the Paperwork Reduction Act, 44 U.S.C. 3501 et seq. (OMB Control No. 2040-0004). Responses to this collection of information are mandatory in accordance with this permit and EPA NPDES regulations 40 CFR 122.41(l)(4)(i). An agency may not conduct or sponsor, and a person is not required to respond to, a collection of information unless it displays a currently valid OMB control number. The public reporting and recordkeeping burden for this collection of information are estimated to average 2 hours per outfall. Send comments on the Agency's need for this information, the accuracy of the provided burden estimates and any suggested methods for minimizing respondent burden to the Regulatory Support Division Director, U.S. Environmental Protection Agency (2821T), 1200 Pennsylvania Ave., NW, Washington, D.C. 20460. Include the OMB control number in any correspondence. Do not send the completed form to this address.

Permit

Permit #:
Major:

KY0098540
Yes

Permittee:
Permittee Address:

Cedar Creek WQTC MSD
700 W Liberty St
Louisville, KY 40203

Facility:
Facility Location:

CEDAR CREEK WQTC MSD
8405 CEDAR CREEK RD
LOUISVILLE, KY 40291

Permitted Feature:

001
External Outfall

Discharge:

001-1
MUNICIPAL DISCHARGE

Report Dates & Status

Monitoring Period:

From 04/01/25 to 04/30/25

DMR Due Date:

05/28/25

Status:

NetDMR Validated

Considerations for Form Completion

Principal Executive Officer

First Name:
Last Name:

James A.
Parrott

Title:

Executive Director

Telephone:

502-540-6000

No Data Indicator (NODI)

Form NODI:

--

Parameter		Monitoring Location	Season #	Param. NODI		Quantity or Loading					Quality or Concentration							# of Ex.	Frequency of Analysis	Sample Type
Code	Name					Qualifier 1	Value 1	Qualifier 2	Value 2	Units	Qualifier 1	Value 1	Qualifier 2	Value 2	Qualifier 3	Value 3	Units			
00300	Oxygen, dissolved [DO]	1 - Effluent Gross	0	--	Sample						=	7.9					19 - mg/L	0	01/07 - Weekly	GR - Grab
					Permit Req.						>=	7.0 INST MIN					19 - mg/L			
					Value NODI															
00400	pH	1 - Effluent Gross	0	--	Sample						=	7.6			=	8.1	12 - SU	0	01/07 - Weekly	GR - Grab
					Permit Req.						>=	6.0 MINIMUM			<=	9.0 MAXIMUM	12 - SU			
					Value NODI															
00530	Solids, total suspended	1 - Effluent Gross	0	--	Sample	=	298.0	=	422.0	26 - lb/d			=	6.0	=	10.0	19 - mg/L	0	01/07 - Weekly	CP - Composite
					Permit Req.	<=	1877.0 MO AVG	<=	2815.0 MX WK AV	26 - lb/d			<=	30.0 MO AVG	<=	45.0 MX WK AV	19 - mg/L			
					Value NODI															
00530	Solids, total suspended	G - Raw Sewage Influent	0	--	Sample								=	138.0	=	212.0	19 - mg/L	0	01/07 - Weekly	CP - Composite
					Permit Req.									Req Mon MO AVG		Req Mon MX WK AV	19 - mg/L			
					Value NODI															
00600	Nitrogen, total [as N]	1 - Effluent Gross	0	--	Sample								=	7.0	=	9.0	19 - mg/L	0	01/07 - Weekly	CP - Composite
					Permit Req.									Req Mon MO AVG		Req Mon MX WK AV	19 - mg/L			
					Value NODI															
00610	Nitrogen, ammonia total [as N]	1 - Effluent Gross	2	--	Sample	=	26.0	=	63.0	26 - lb/d			=	0.6	=	1.5	19 - mg/L	0	01/07 - Weekly	CP - Composite
					Permit Req.	<=	626.0 MO AVG	<=	939.0 MX WK AV	26 - lb/d			<=	10.0 MO AVG	<=	15.0 MX WK AV	19 - mg/L			
					Value NODI															
00665	Phosphorus, total [as P]	1 - Effluent Gross	2	--	Sample								=	0.31	=	0.6	19 - mg/L	0	01/07 - Weekly	CP - Composite
					Permit Req.								<=	2.0 MO AVG	<=	3.0 MX WK AV	19 - mg/L			
					Value NODI															
50050	Flow, in conduit or thru treatment plant	1 - Effluent Gross	0	--	Sample	=	8.362	=	15.855	03 - MGD								0	99/99 - Continuous	CN - Continuous
					Permit Req.		Req Mon MO AVG		Req Mon MX WK AV	03 - MGD										
					Value NODI															
50050	Flow, in conduit or thru treatment plant	G - Raw Sewage Influent	0	--	Sample	=	9.305	=	16.045	03 - MGD								0	99/99 - Continuous	CN - Continuous
					Permit Req.		Req Mon MO AVG		Req Mon MX WK AV	03 - MGD										
					Value NODI															
51040	E. coli	1 - Effluent Gross	0	--	Sample								=	2.0	=	7.0	13 - #/100mL	0	01/07 - Weekly	GR - Grab
					Permit Req.								<=	130.0 30DA GEO	<=	240.0 7 DA GEO	13 - #/100mL			

					Value NODI														
80082	BOD, carbonaceous [5 day, 20 C]	1 - Effluent Gross	0	--	Sample	=	163.0	=	256.0	26 - lb/d		=	3.0	=	3.0	19 - mg/L	0	01/07 - Weekly	24 - 24 Hour Composite
					Permit Req.	<=	626.0 MO AVG	<=	939.0 MX WK AV	26 - lb/d		<=	10.0 MO AVG	<=	15.0 MX WK AV	19 - mg/L		01/07 - Weekly	24 - 24 Hour Composite
					Value NODI														
80082	BOD, carbonaceous [5 day, 20 C]	G - Raw Sewage Influent	0	--	Sample							=	99.0	=	157.0	19 - mg/L	0	01/07 - Weekly	24 - 24 Hour Composite
					Permit Req.								Req Mon MO AVG		Req Mon MX WK AV	19 - mg/L		01/07 - Weekly	24 - 24 Hour Composite
					Value NODI														
80091	BOD, carb-5 day, 20 deg C, percent removal	K - Percent Removal	0	--	Sample					=	97.0					23 - %	0	01/30 - Monthly	CA - Calculated
					Permit Req.					>=	85.0 MO AV MN					23 - %		01/30 - Monthly	CA - Calculated
					Value NODI														
81011	Solids, suspended percent removal	K - Percent Removal	0	--	Sample					=	95.0					23 - %	0	01/30 - Monthly	CA - Calculated
					Permit Req.					>=	85.0 MO AV MN					23 - %		01/30 - Monthly	CA - Calculated
					Value NODI														

Submission Note

If a parameter row does not contain any values for the Sample nor Effluent Trading, then none of the following fields will be submitted for that row: Units, Number of Excursions, Frequency of Analysis, and Sample Type.

Edit Check Errors

No errors.

Comments

Attachments

Name	Type	Size
April_2025_All_Other_Service_Areas.pdf	pdf	213523.0
CCMOR042025.pdf	pdf	81944.0
Cedarcreekcover.pdf	pdf	37671.0

Report Last Saved By

Cedar Creek WQTC MSD

User:

kevin.thompson@louisvillemsd.org

Name:

Kevin Thompson

E-Mail:

kevin.thompson@louisvillemsd.org

Date/Time:

2025-05-19 12:27 (Time Zone: -04:00)

Report Last Signed By

User:

JON.BALDRIDGE@LOUISVILLEMSD.ORG

Name:

Jonathan Baldrige

E-Mail:

jon.baldrige@louisvillemsd.org

Date/Time:

2025-05-19 14:09 (Time Zone: -04:00)

NAME OF TREATMENT PLANT CEDAR CREEK WTP COUNTY JEFFERSON MONTH OF: April 2025
KPDOS PERMIT NUMBER KY0098540 PLANT CAPACITY 7.5 MGD RECEIVING STREAM CEDAR CREEK

DATE	TOTAL FLOW (MILLION GALLONS)	RAW SEWAGE		pH		SETTLEABLE SOLIDS (mg/L)			DISSOLVED OXYGEN (mg/L)			SUSPENDED SOLIDS (mg/L)			5 DAY CBOD (mg/L)			ACTIVATED SLUDGE			AERATION BASIN						SLUDGE HANDLING						FINAL		Total Phosphorus Total Nitrogen TOTAL FLOW INF. (MILLION GALLONS)			
		GRIT REMOVED (CUBIC FEET)	SCREENINGS (CUBIC FEET)	RAW	FINAL	RAW	PRIMARY EFFLUENT	FINAL EFFLUENT	STREAM ABOVE	FINAL EFFLUENT	STREAM BELOW	RAW	PRIMARY EFFLUENT	FINAL EFFLUENT	RAW	PRIMARY EFFLUENT	FINAL EFFLUENT	GAL/DAY X 1000	MLSS x1000	GAL/DAY X 1000	WASTED	DISOLVED OXYGEN (mg/L)	MLSS (mg/L) x 1000	MLVSS (mg/L) X 1000	SETTLED SLUDGE VOLUME		RAW		HAULED				NH3-N (mg/L)	ECOLI				
																									30 MIN.	60 MIN.	GALLONS X 1000	% DRY SOLIDS	% VOLATILE SOLIDS	% DRY SOLIDS	% VOLATILE SOLIDS	WITHDRAWN GALLONS X 1000						
1	7.66			7.5														7.07	4670	100000		3.9	2460	2150	840								100800				7.918482	
2	7.07			8.2	8.0					9.7		135		5	80		3	6.52	4450	125000		2.7	2450	2080	790								94500	0.27	1	0.2	5.56	7.343373
3	15.00			8.1														6.07	7000	125000		2.6	1910	1660	500								100800				16.81668	
4	21.91			7.5														6.77	6510	75000		4.4	1910	1630	540								94500				21.3165	
5	22.11																	6.78		75000		3.6			340								50400				21.83123	
6	22.28																	6.58		100000		3.8			380								0				21.90621	
7	14.95			7.1														7	6580	100000		3.8	2730	2080	650								100800				15.18116	
8	11.32			7.5														6.6	5950	100000		5.3	2600	2300	730								100800				11.8236	
9	10.24			7.1	7.6					11.1		56		3	40		3	6.81	6960	100000		4.6	3130	2730	780								100800	0.20	7	0.226	5.38	10.7303
10	8.94			7.4														6.06	6490	150000		4	3030	2640	880								100800				10.7303	
11	9.24			7.4														5.24	6690	195000		4	2690	2210	860								88200				19.30408	
12	7.17																	5.33		100000		4.5			850								50400				7.854347	
13	7.14																	4.24		80000		4.8			850								0				7.825891	
14	6.15			7.4														3.63	7380	185000		2.2	2900	2410	860								100800				6.961992	
15	5.30			7.1														3.41	7000	123914		3.1	3050	2550	830								100800				6.100519	
16	5.06			7.7	8.1					9.3		149		10	157		3	5870	131747		3.4	2640	2170	760									94500	1.50	1	0.556	7.83	5.6722
17	4.89			7.9														2.9	6000	123167		3.5	2690	2300	700								94500				5.464879	
18	4.85			7.6														2.73	5740	100000		3.2	2470	2090	700								75600				5.384037	
19	4.98																	2.78		50000		3.6			710								50400				5.42059	
20	4.82																	2.82		40000		2.3			670								0				5.305977	
21	5.12			7.4														2.14	5850	75000		1.9	2830	2370	700								100800				5.521511	
22	3.91			7.9														2.67	9770	150000		5	2250	1960	400								138600				5.254468	
23	3.74			7.6	7.9					7.9		212		7	119		3	3	4960	75000		4.3	2840	2410	640								100800	0.25		0.244	9.15	5.3394
24	5.08			6.6														2.64	6940	125000		3.7	2590	2230	600								138600				5.961108	
25	6.31			7.3														2.69	7220	100000		3.7	2550	2140	600								132300				7.558363	
26	6.32																	2.67		75000		3.1			570								50400				6.919654	
27	5.26																	2.68		75000		3.8			600								0				5.910156	
28	5.15			7.4														2.58	6030	150000		2.8	2770	2410	670								100800				5.761719	
29	4.60			7.5														2.41	6090	125000		3.1	2490	2210	570								132300				5.133144	
30	4.29			7.5														2.46	5980	75000		3.5	2410	2070	550								100800				4.905346	
31																																						
Tot.	250.86																	128.3																2494800				279.157216
Avg.	8.36			7.5	7.9					9.5		138		6	99		3	4.276	6370	106794		3.607	2609	2218	670.7								83160	0.56	2	0.307	6.98	9.305240533

RESIDENTIAL
COMMERCIAL
INDUSTRIAL

INDUSTRIAL WASTE POPULATION EQUIVALENT
79639
FLOW
40613
CBOD
45829
TSS

Chris Coomer
OPERATOR

18291
CERT. NO.

TOTAL NUMBER OF SEWER CONNECTIONS 0
SEWER CONNECTIONS 0 X 4 = 0 SEWERED POPULATION

502/540/6700
PLANT TELEPHONE



IMSAST0004
Overflow Report
4/1/2025 12:00:00 AM to 4/30/2025 12:00:00 AM

KPDES #	Facility ID	Water Quality Treatment Center		Receiving Stream of Discharge			Region				
KY0078956	MSD0277	DEREK R. GUTHRIE		OHIO RIVER			NA				
Facility Type	Facility ID	Facility Address	If Pump Station, Name of Station			Receiving Stream		Discharge To			
Sewer Manhole	115910	1720 E ROCKFORD LN	DEREK R. GUTHRIE			BIG RUN		CATCH BASIN			
Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3923069		4/4/2025 11:30:00 AM	HUBER IV	SMITH	BEYOND APPROVED DESIGN STORM	4/4/2025 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE-WATERS	04/05/25 02:35 AM	

Discharge Reporting:

Discharge Amount:	4,525 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	IMPACTED AREA WILL BE CLEANED AND SANITIZED AT CONCLUSION OF RAIN EVENT.
Control Zone:	TEMPORARY SIGNS PLACED AT SITE.
Impact:	NO DEBRIS OBSERVED AT SITE.
Repair:	DISCHARGE DISCOVERED DURING RECON ROUTE.
Public Notification:	TEMPORARY SIGNS PLACED AT SITE.

Notifications:

4/5/25 1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
4/5/25 1:00 AM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



IMSAST0004
Overflow Report
4/1/2025 12:00:00 AM to 4/30/2025 12:00:00 AM

KPDES #	Facility ID	Water Quality Treatment Center	Receiving Stream of Discharge	Region
KY0098540	MSD0289	CEDAR CREEK	CEDAR CREEK	NA

Facility Type	Facility ID	Facility Address	If Pump Station, Name of Station	Receiving Stream	Discharge To
Sewer Manhole	116108	10614 STONEBREAKER RD	CEDAR CREEK	BIG RUN	STREAM

Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3923174		4/4/2025 3:25:00 PM	VAUGHAN	VAUGHAN	BEYOND APPROVED DESIGN STORM	4/4/2025 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE- WATERS	04/07/25 01:11 PM	MAIN

Discharge Reporting:

Discharge Amount:	207,000 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	NONE POSSIBLE DUE TO MAGNITUDE OF STORM.
Control Zone:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.
Impact:	NO IMPACT OBSERVED – MAGNITUDE OF STORM FLUSHED SOLIDS AND DEBRIS FROM SITE.
Repair:	INVESTIGATION INDICATED THAT ADDITIONAL REPAIRS WERE NOT REQUIRED BY MSD.
Public Notification:	ADVISED CUSTOMER ON SITE.

Notifications:

4/5/25 1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
4/5/25 1:00 AM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



IMSAST0004
Overflow Report
4/1/2025 12:00:00 AM to 4/30/2025 12:00:00 AM

KPDES #	Facility ID	Water Quality Treatment Center	Receiving Stream of Discharge	Region
KY0078956	MSD0277	DEREK R. GUTHRIE	OHIO RIVER	NA

Facility Type	Facility ID	Facility Address	If Pump Station, Name of Station	Receiving Stream	Discharge To
Sewer Manhole	117174	8800 ADMIRAL DR	DEREK R. GUTHRIE	PENNSYLVANIA RUN	GROUND

Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3923034		4/4/2025 6:00:00 AM	HUBER IV	DIXON JR	BEYOND APPROVED DESIGN STORM	4/5/2025 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE- WATERS	04/05/25 01:07 AM	

Discharge Reporting:

Discharge Amount:	171,000 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	IMPACTED AREA WILL BE CLEANED AND SANITIZED AT CONCLUSION OF RAIN EVENT.
Control Zone:	TEMPORARY SIGNS PLACED AT SITE.
Impact:	SMALL AMOUNT OF DEBRIS OBSERVED AT SITE.
Repair:	DISCHARGE DISCOVERED DURING RECON ROUTE.
Public Notification:	TEMPORARY SIGNS PLACED AT SITE.

Notifications:

4/5/25 1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
4/5/25 1:00 AM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION

KPDES #	Facility ID	Water Quality Treatment Center			Recieving Steam of Discharge		Region				
KY0078956	MSD0277	DEREK R. GUTHRIE			OHIO RIVER		NA				
Facility Type	Facility ID	Facility Address		If Pump Station, Name of Station			Recieving Stream		Discharge To		
Sewer Manhole	117174	8800	ADMIRAL DR	DEREK R. GUTHRIE			PENNSYLVANIA RUN		GROUND		
Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3923342		4/5/2025 8:30:00 AM	SINGLETON	BUTLER	BEYOND APPROVED DESIGN STORM	4/5/2025 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE- WATERS	04/06/25 06:15 PM	

Discharge Reporting:

Discharge Amount:	321,750 GAL
Cause:	LACK OF SYSTEM CAPACITY DUE TO RAIN EVENT.
Clean Up:	CLEANED AND SANITIZED THE IMPACTED AREA
Control Zone:	TEMPORARY SIGNS PLACED AROUND THE AFFECTED AREA.
Impact:	DEBRIS AND SEWAGE OBSERVED AT SITE.
Repair:	DISCHARGE DISCOVERED DURING RAIN EVENT RECON.
Public Notification:	TEMPORARY SIGNS PLACED AROUND THE AFFECTED AREA.

Notifications:

4/5/25 1:00 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
4/5/25 1:00 PM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



IMSAST0004
Overflow Report
4/1/2025 12:00:00 AM to 4/30/2025 12:00:00 AM

KPDES #	Facility ID	Water Quality Treatment Center			Recieving Steam of Discharge		Region				
KY0106143	MSD0407	OHIO RIVER			OHIO RIVER		NA				
Facility Type	Facility ID	Facility Address		If Pump Station, Name of Station			Recieving Stream		Discharge To		
Sewer Manhole	122281	3014	ALBRECHT DR	OHIO RIVER			HUNTING CREEK		GROUND		
Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3923089		4/4/2025 8:20:00 AM	HUBER IV	MULLINS	BEYOND APPROVED DESIGN STORM	4/4/2025 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE-WATERS	04/05/25 03:57 AM	

Discharge Reporting:

Discharge Amount:	29,425 GAL
Cause:	LACK OF CAPACITY.
Clean Up:	IMPACTED AREA WILL BE CLEANED AND SANITIZED AT CONCLUSION OF RAIN EVENT.
Control Zone:	TEMPORARY SIGNS PLACED AT SITE.
Impact:	NO DEBRIS OBSERVED AT SITE.
Repair:	DISCHARGE DISCOVERED DURING RECON ROUTE.
Public Notification:	TEMPORARY SIGNS PLACED AT SITE.

Notifications:

4/5/25 1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
4/5/25 1:00 AM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION

KPDES #	Facility ID	Water Quality Treatment Center			Receiving Stream of Discharge		Region				
KY0106143	MSD0407	OHIO RIVER			OHIO RIVER		NA				
Facility Type	Facility ID	Facility Address		If Pump Station, Name of Station			Receiving Stream		Discharge To		
Sewer Manhole	123668	13009	STHY 329	OHIO RIVER			HUNTING CREEK		GROUND		
Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3922288		4/3/2025 3:17:00 AM	JACKSON	TIMMERING	BEYOND APPROVED DESIGN STORM	4/3/2025 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE- WATERS	04/03/25 05:00 AM	

Discharge Reporting:

Discharge Amount:	5,150 GAL
Cause:	LACK OF CAPACITY.
Clean Up:	CLEAN UP NOT POSSIBLE DUE TO MAGNITUDE OF STORM.
Control Zone:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.
Impact:	SEWAGE / DEBRIS / PERSONAL HYGIENE PRODUCTS FOUND IN THE AREA.
Repair:	SITE FOUND DURING RAIN EVENT RECON - WILL BE MONITORED AND EVALUATED FOR REPAIR.
Public Notification:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.

Notifications:

4/3/25 1:00 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
----------------	--------	---



IMSAST0004
Overflow Report
4/1/2025 12:00:00 AM to 4/30/2025 12:00:00 AM

KPDES #	Facility ID	Water Quality Treatment Center			Receiving Stream of Discharge		Region				
KY0106143	MSD0407	OHIO RIVER			OHIO RIVER		NA				
Facility Type	Facility ID	Facility Address	If Pump Station, Name of Station			Receiving Stream			Discharge To		
Sewer Main	124057-V	2702 MEADOW WOOD CT	OHIO RIVER			POND CREEK			DITCH		
Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISDW: DRY WEATHER DISCHARGE	3929435		4/17/2025 10:30:00 AM	PARKER	PARKER	REPAIRED - ISSUE RESOLVED	4/17/2025 12:00:00 AM	STRUCTURAL FAILURE	UNAUTHORIZED DISCHARGE- WATERS	04/18/25 07:07 AM	

Discharge Reporting:

Discharge Amount:	7,200 GAL
Cause:	STRUCTURAL FAILURE FORCE MAIN BREAK.
Clean Up:	MSD CONTRACTOR CLEANED AND SANITIZED THE AFFECTED AREA.
Control Zone:	PLACED BARRICADES AND CAUTION TAPE AROUND THE IMPACTED AREA.
Impact:	SEWAGE FOUND ON THE GROUND.
Repair:	CONTACTED CONTRACTORS TO MAKE REPAIRS AND HAUL STATION
Public Notification:	ADVISED ALL POSSIBLE IMPACTED PROPERTIES IN THE SURROUNDING AREA IN PERSON.

Notifications:

4/17/25 1:00 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO: DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
4/17/25 1:00 PM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



IMSAST0004
Overflow Report
4/1/2025 12:00:00 AM to 4/30/2025 12:00:00 AM

KPDES #	Facility ID	Water Quality Treatment Center	Receiving Stream of Discharge	Region
KY0078956	MSD0277	DEREK R. GUTHRIE	OHIO RIVER	NA

Facility Type	Facility ID	Facility Address	If Pump Station, Name of Station	Receiving Stream	Discharge To
Sewer Manhole	17404	8303 LINDA RD	DEREK R. GUTHRIE	ROBERSON RUN	GROUND

Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3923158		4/4/2025 12:35:00 PM	HENDRIX	GIBSON	BEYOND APPROVED DESIGN STORM	4/4/2025 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE- WATERS	04/07/25 10:00 AM	MAIN

Discharge Reporting:

Discharge Amount:	104,125 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	WATER HAS NOT RECEDED - CUSTOMER ADVISED TO CONTACT CUSTOMER RELATIONS WHEN WATER RECEDES.
Control Zone:	PLACED TEMPORARY DISCHARGE SIGNS AROUND MANHOLE.
Impact:	SEWAGE FOUND AROUND MANHOLE.
Repair:	INVESTIGATION INDICATED THAT ADDITIONAL REPAIRS WERE NOT REQUIRED BY MSD.
Public Notification:	ADVISED CUSTOMER ON SITE.

Notifications:

4/5/25 1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
----------------	--------	--

KPDES #	Facility ID	Water Quality Treatment Center	Receiving Stream of Discharge	Region
KY0078956	MSD0277	DEREK R. GUTHRIE	OHIO RIVER	NA

Facility Type	Facility ID	Facility Address	If Pump Station, Name of Station	Receiving Stream	Discharge To
Sewer Manhole	17445	4507 ST RITA DR	DEREK R. GUTHRIE	ROBERSON RUN	DITCH

Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3923167		4/4/2025 1:05:00 PM	HENDRIX	GIBSON	BEYOND APPROVED DESIGN STORM	4/4/2025 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE- WATERS	04/07/25 10:05 AM	MAIN

Discharge Reporting:

Discharge Amount:	103,500 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	WATER HAS NOT RECEDED - CUSTOMER ADVISED TO CONTACT CUSTOMER RELATIONS WHEN WATER RECEDES.
Control Zone:	PLACED TEMPORARY DISCHARGE SIGNS AROUND MANHOLE.
Impact:	SEWAGE FOUND AROUND MANHOLE.
Repair:	INVESTIGATION INDICATED THAT ADDITIONAL REPAIRS WERE NOT REQUIRED BY MSD.
Public Notification:	ADVISED CUSTOMER ON SITE.

Notifications:

4/5/25 1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
----------------	--------	--



IMSAST0004
Overflow Report
4/1/2025 12:00:00 AM to 4/30/2025 12:00:00 AM

KPDES #	Facility ID	Water Quality Treatment Center	Receiving Stream of Discharge	Region
KY0078956	MSD0277	DEREK R. GUTHRIE	OHIO RIVER	NA

Facility Type	Facility ID	Facility Address	If Pump Station, Name of Station	Receiving Stream	Discharge To
Sewer Manhole	25484	9317 LANTANA DR	DEREK R. GUTHRIE	PENNSYLVANIA RUN	STREAM

Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3923051		4/4/2025 6:15:00 AM	HUBER IV	DIXON JR	DOCUMENTED	1/13/2013 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE-WATERS	04/05/25 01:02 AM	

Discharge Reporting:

Discharge Amount:	40,700 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	IMPACTED AREA WILL BE CLEANED AND SANITIZED AT CONCLUSION OF RAIN EVENT.
Control Zone:	TEMPORARY SIGNS PLACED AT SITE.
Impact:	SEWAGE/DEBRIS FOUND AROUND MANHOLE.
Repair:	HAULED SEWAGE TO REDUCE DISCHARGE AMOUNT HAULOP #3923061.
Public Notification:	TEMPORARY SIGNS PLACED AT SITE.

Notifications:

4/5/25 1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
4/5/25 1:00 AM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



IMSAST0004
Overflow Report
4/1/2025 12:00:00 AM to 4/30/2025 12:00:00 AM

KPDES #	Facility ID	Water Quality Treatment Center	Receiving Stream of Discharge	Region
KY0078956	MSD0277	DEREK R. GUTHRIE	OHIO RIVER	NA

Facility Type	Facility ID	Facility Address	If Pump Station, Name of Station	Receiving Stream	Discharge To
Sewer Manhole	25484	9317 LANTANA DR	DEREK R. GUTHRIE	PENNSYLVANIA RUN	STREAM

Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3923423		4/5/2025 7:54:00 PM	JACKSON	TIMMERING	DOCUMENTED	1/13/2013 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE-WATERS	04/06/25 09:00 PM	

Discharge Reporting:

Discharge Amount:	150,600 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	CLEANED AND SANITIZED THE IMPACTED AREA.
Control Zone:	PLACED TEMPORARY SIGNS AROUND IMPACTED AREA.
Impact:	SEWAGE/DEBRIS/PERSONAL HYGIENE PRODUCTS FOUND AROUND IMPACTED AREA.
Repair:	SITE FOUND DURING RAIN EVENT RECON, WILL BE MONITORED AND EVALUATED FOR REPAIR.
Public Notification:	PLACED TEMPORARY SIGNS AROUND IMPACTED AREA.

Notifications:

4/6/25 1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
4/6/25 1:00 AM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



IMSAST0004
Overflow Report
4/1/2025 12:00:00 AM to 4/30/2025 12:00:00 AM

KPDES #	Facility ID	Water Quality Treatment Center	Receiving Stream of Discharge	Region
KY0098540	MSD0289	CEDAR CREEK	CEDAR CREEK	NA

Facility Type	Facility ID	Facility Address	If Pump Station, Name of Station	Receiving Stream	Discharge To
Sewer Manhole	29370	11105 ELECTRON DR	CEDAR CREEK	CHENOWETH RUN	GROUND

Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISDW: DRY WEATHER DISCHARGE	3935289		4/24/2025 1:00:00 PM	FERRELL		REPAIRED - ISSUE RESOLVED	4/24/2025 12:00:00 AM	OBSTRUCTION-NOT GREASE / ROOTS	UNAUTHORIZED DISCHARGE-WATERS	04/24/25 02:00 PM	MAIN

Discharge Reporting:

Discharge Amount:	600 GAL
Cause:	OBSTRUCTION IN MAIN SEWER.
Clean Up:	MSD PERSONNEL CLEANED AND SANITIZED THE IMPACTED AREA.
Control Zone:	MSD PERSONNEL ADVISED THE CUSTOMER TO AVOID CONTACT WITH SEWAGE PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.
Impact:	SEWAGE/WATER DISCHARGING FROM MANHOLE.
Repair:	FLUSHED MAIN SEWER 3935290.
Public Notification:	ADVISED CUSTOMER ON SITE.

Notifications:

4/25/25 1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO: DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
-----------------	--------	--



IMSAST0004
Overflow Report
4/1/2025 12:00:00 AM to 4/30/2025 12:00:00 AM

KPDES #	Facility ID	Water Quality Treatment Center	Receiving Stream of Discharge	Region
KY0078956	MSD0277	DEREK R. GUTHRIE	OHIO RIVER	NA

Facility Type	Facility ID	Facility Address	If Pump Station, Name of Station	Receiving Stream	Discharge To
Sewer Manhole	36419	6903 CHARLES LINDSEY CT	DEREK R. GUTHRIE	PENNSYLVANIA RUN	GROUND

Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISDW: DRY WEATHER DISCHARGE	3930124		4/18/2025 8:30:00 AM	SOSA RODRIGUEZ	PADUA MUNOZ	REPAIRED - ISSUE RESOLVED	4/18/2025 12:00:00 AM	POWER OUTAGE (LG&E)	UNAUTHORIZED DISCHARGE- WATERS	04/18/25 10:40 AM	

Discharge Reporting:

Discharge Amount:	2,250 GAL
Cause:	POWER OUTAGE (LG&E).
Clean Up:	CLEANED AND SANITIZED THE IMPACTED AREA.
Control Zone:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.
Impact:	SEWAGE FOUND AROUND MANHOLE.
Repair:	LG&E RESTORED POWER.
Public Notification:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.

Notifications:

4/18/25 1:00 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
-----------------	--------	---



IMSAST0004
Overflow Report
4/1/2025 12:00:00 AM to 4/30/2025 12:00:00 AM

KPDES #	Facility ID	Water Quality Treatment Center		Receiving Stream of Discharge		Region					
KY0078956	MSD0277	DEREK R. GUTHRIE		OHIO RIVER		NA					
Facility Type	Facility ID	Facility Address	If Pump Station, Name of Station		Receiving Stream		Discharge To				
Sewer Manhole	60679	9114 CINDERELLA LN	DEREK R. GUTHRIE		FISHPOOL CREEK		DITCH				
Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3922299		4/3/2025 4:30:00 AM	JACKSON	JOHNSON	DOCUMENTED	12/15/2007 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE-WATERS	04/06/25 07:59 PM	

Discharge Reporting:

Discharge Amount:	524,900 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	CLEANUP NOT POSSIBLE DUE TO MAGNITUDE OF STORM.
Control Zone:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.
Impact:	SEWAGE DEBRIS / SOLIDS / PERSONAL HYGIENE PRODUCTS FOUND AROUND MANHOLE.
Repair:	SITE FOUND DURING RAIN EVENT RECON - WILL BE MONITORED AND EVALUATED FOR REPAIR. HAULED STATION TO REDUCE DISCHARGE.
Public Notification:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.

Notifications:

4/3/25 1:00 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
4/3/25 1:00 PM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



IMSAST0004
Overflow Report
4/1/2025 12:00:00 AM to 4/30/2025 12:00:00 AM

KPDES #	Facility ID	Water Quality Treatment Center	Receiving Stream of Discharge	Region
KY0078956	MSD0277	DEREK R. GUTHRIE	OHIO RIVER	NA

Facility Type	Facility ID	Facility Address	If Pump Station, Name of Station	Receiving Stream	Discharge To
Sewer Manhole	71095	8321 STILLMEADOW DR	DEREK R. GUTHRIE	FERN CREEK	STREAM

Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3923185		4/4/2025 4:07:00 PM	OWENS	OWENS	BEYOND APPROVED DESIGN STORM	4/4/2025 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE- WATERS	04/07/25 01:42 PM	MAIN

Discharge Reporting:

Discharge Amount:	1,035 GAL
Cause:	LACK OF SYSTEM CAPACITY RAIN EVENT.
Clean Up:	NONE POSSIBLE DUE TO MAGNITUDE OF STORM.
Control Zone:	PLACED TEMPORARY SIGNS AROUND MANHOLE.
Impact:	SEWER WATER GOING IN TO CREEK.
Repair:	ADVISED CUSTOMER TO CALL BACK 48 HOURS AFTER RAIN STOP IF STILL HAVING ISSUE.
Public Notification:	ADVISED CUSTOMER BY TELEPHONE.

Notifications:

4/5/25 1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
----------------	--------	--



IMSAST0004
Overflow Report
4/1/2025 12:00:00 AM to 4/30/2025 12:00:00 AM

KPDES #	Facility ID	Water Quality Treatment Center	Receiving Stream of Discharge	Region
KY0078956	MSD0277	DEREK R. GUTHRIE	OHIO RIVER	NA

Facility Type	Facility ID	Facility Address	If Pump Station, Name of Station	Receiving Stream	Discharge To
Sewer Manhole	82428	8416 LOU CT	DEREK R. GUTHRIE	ROBERSON RUN	STREAM

Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3923096		4/4/2025 12:00:00 PM	HENDRIX	GIBSON	BEYOND APPROVED DESIGN STORM	4/4/2025 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE- WATERS	04/07/25 09:50 AM	MAIN

Discharge Reporting:

Discharge Amount:	104,750 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	WATER HAS NOT RECEDED - CUSTOMER ADVISED TO CONTACT CUSTOMER RELATIONS WHEN WATER RECEDES.
Control Zone:	PLACED TEMPORARY DISCHARGE SIGNS AROUND MANHOLE.
Impact:	SEWAGE FOUND AROUND MANHOLE.
Repair:	INVESTIGATION INDICATED THAT ADDITIONAL REPAIRS WERE NOT REQUIRED BY MSD.
Public Notification:	ADVISED CUSTOMER ON SITE.

Notifications:

4/5/25 1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
----------------	--------	--



IMSAST0004
Overflow Report
4/1/2025 12:00:00 AM to 4/30/2025 12:00:00 AM

KPDES #	Facility ID	Water Quality Treatment Center	Receiving Stream of Discharge	Region
KY0078956	MSD0277	DEREK R. GUTHRIE	OHIO RIVER	NA

Facility Type	Facility ID	Facility Address	If Pump Station, Name of Station	Receiving Stream	Discharge To
Sewer Manhole	84926	5007 LEA ANN WAY	DEREK R. GUTHRIE	NORTHERN DITCH	STREAM

Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3923421		4/5/2025 7:44:00 PM	JACKSON	ADAMS	BEYOND APPROVED DESIGN STORM	4/5/2025 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE- WATERS	04/06/25 10:48 PM	

Discharge Reporting:

Discharge Amount:	974,400 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	FOUND DURING RAIN EVENT AND WILL EVALUATE AND CLEAN ASAP.
Control Zone:	PLACED TEMPORARY SIGNS AROUND IMPACTED AREA. PLACED TEMPORARY SIGNS.
Impact:	PUMPED DIRECTLY TO CREEK.
Repair:	WILL BE MONITORED AND EVALUTATED FOR REPAIR.
Public Notification:	PLACED TEMPORARY SIGNS AROUND IMPACTED AREA.

Notifications:

4/6/25 1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
4/6/25 1:00 AM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



IMSAST0004
Overflow Report
4/1/2025 12:00:00 AM to 4/30/2025 12:00:00 AM

KPDES #	Facility ID	Water Quality Treatment Center	Receiving Stream of Discharge	Region
KY0078956	MSD0277	DEREK R. GUTHRIE	OHIO RIVER	NA

Facility Type	Facility ID	Facility Address	If Pump Station, Name of Station	Receiving Stream	Discharge To
Sewer Manhole	84926	5007 LEA ANN WAY	DEREK R. GUTHRIE	NORTHERN DITCH	STREAM

Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3923422		4/5/2025 7:55:00 PM	JACKSON	ADAMS	BEYOND APPROVED DESIGN STORM	4/5/2025 12:00:00 AM	PUMPED OVERFLOW	UNAUTHORIZED DISCHARGE- WATERS	04/06/25 09:43 PM	

Discharge Reporting:

Discharge Amount:	928,800 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	FOUND DURING RAIN EVENT RECON. WILL CLEAN AFTER EVENT.
Control Zone:	PLACED TEMPORAY SIGNS AROUND IMPACTED AREA.
Impact:	PUMPED DIRECTLY TO CREEK.
Repair:	FOUND DURING RAIN EVENT, WILL BE MONITORED AND EVALUATED FOR REPAIR.
Public Notification:	PLACED TEMPORAY SIGNS AROUND IMPACTED AREA.

Notifications:

4/6/25 1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
4/6/25 1:00 AM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



IMSAST0004
Overflow Report
4/1/2025 12:00:00 AM to 4/30/2025 12:00:00 AM

KPDES #	Facility ID	Water Quality Treatment Center	Receiving Stream of Discharge	Region
KY0078956	MSD0277	DEREK R. GUTHRIE	OHIO RIVER	NA

Facility Type	Facility ID	Facility Address	If Pump Station, Name of Station	Receiving Stream	Discharge To
Sewer Manhole	84926	5007 LEA ANN WAY	DEREK R. GUTHRIE	NORTHERN DITCH	STREAM

Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3923434		4/5/2025 8:00:00 PM	HUBER IV	ADAMS	BEYOND APPROVED DESIGN STORM	4/5/2025 12:00:00 AM	PUMPED OVERFLOW	UNAUTHORIZED DISCHARGE-WATERS	04/06/25 12:00 AM	

Discharge Reporting:

Discharge Amount:	138,600 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	NONE POSSIBLE DUE TO MAGNITUDE OF STORM.
Control Zone:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.
Impact:	NO IMPACT OBSERVED.
Repair:	SITE FOUND DURING RAIN EVENT RECON - WILL BE MONITORED AND EVALUATED FOR REPAIR.
Public Notification:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.

Notifications:

4/6/25 1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
4/6/25 1:00 AM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



IMSAST0004
Overflow Report
4/1/2025 12:00:00 AM to 4/30/2025 12:00:00 AM

KPDES #	Facility ID	Water Quality Treatment Center	Receiving Stream of Discharge	Region
KY0102784	MSD0294	FLOYDS FORK	FLOYDS FORK	NA

Facility Type	Facility ID	Facility Address	If Pump Station, Name of Station	Receiving Stream	Discharge To
Sewer Manhole	95118	702 S BECKLEY STATION RD	FLOYDS FORK	FLOYDS FORK	GROUND

Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISDW: DRY WEATHER DISCHARGE	3936038		4/28/2025 7:30:00 PM	GRIGSBY JR		REPAIRED - ISSUE RESOLVED	4/28/2025 12:00:00 AM	ROOTS	UNAUTHORIZED DISCHARGE- WATERS	04/28/25 09:00 PM	

Discharge Reporting:

Discharge Amount:	10 GAL
Cause:	ROOTS IN MAIN SEWER.
Clean Up:	WO#3936041.
Control Zone:	MSD PERSONNEL ADVISED THE CUSTOMER TO AVOID CONTACT WITH SEWAGE.
Impact:	OBSERVED BY MSD PERSONNEL..
Repair:	ROOT CUT THE MAIN 460 FEET 3936384.
Public Notification:	ADVISED CUSTOMER ON SITE.

Notifications:

4/29/25 1:00 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
-----------------	--------	---



IMSAST0004
Overflow Report
4/1/2025 12:00:00 AM to 4/30/2025 12:00:00 AM

KPDES #	Facility ID	Water Quality Treatment Center	Receiving Stream of Discharge	Region
KY0098540	MSD0289	CEDAR CREEK	CEDAR CREEK	NA

Facility Type	Facility ID	Facility Address	If Pump Station, Name of Station	Receiving Stream	Discharge To
Sewer Manhole	97363	10800 FAIRMOUNT RD	CEDAR CREEK	BIG RUN	STREAM

Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3922934		4/4/2025 12:00:00 PM	HUBER IV	CATALANO JR	BEYOND APPROVED DESIGN STORM	4/4/2025 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE- WATERS	04/06/25 07:24 PM	

Discharge Reporting:

Discharge Amount:	516,600 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	MSD PERSONNEL CLEANED AND SANITIZED THE IMPACTED AREA.
Control Zone:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.
Impact:	DEBRIS OBSERVED ON GROUND.
Repair:	SITE FOUND DURING RAIN EVENT RECON - WILL BE MONITORED AND EVALUATED FOR REPAIR.
Public Notification:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.

Notifications:

4/4/25 1:00 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
4/4/25 1:00 PM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



IMSAST0004
Overflow Report
4/1/2025 12:00:00 AM to 4/30/2025 12:00:00 AM

KPDES #	Facility ID	Water Quality Treatment Center	Receiving Stream of Discharge	Region
KY0098540	MSD0289	CEDAR CREEK	CEDAR CREEK	NA

Facility Type	Facility ID	Facility Address	If Pump Station, Name of Station	Receiving Stream	Discharge To
Sewer Manhole	98024	8809 CEDAR CREEK RD	CEDAR CREEK	CEDAR CREEK	GROUND

Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3923103		4/4/2025 10:00:00 AM	DODDS		BEYOND APPROVED DESIGN STORM	4/4/2025 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE-WATERS	04/06/25 01:04 PM	

Discharge Reporting:

Discharge Amount:	306,000 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	CLEANED AND SANITIZED THE IMPACTED AREA.
Control Zone:	PERMANENT SIGN IN PLACE – NO ADDITIONAL CONTROL ZONE SET UP.
Impact:	SEWAGE FOUND AROUND MANHOLE.
Repair:	A SOLUTION FOR THIS LOCATION IS INCLUDED IN THE INTEGRATED OVERFLOW ABATEMENT PLAN.
Public Notification:	ADVISED CUSTOMER ON SITE.

Notifications:

4/5/25 1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
4/5/25 1:00 AM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



IMSAST0004
Overflow Report
4/1/2025 12:00:00 AM to 4/30/2025 12:00:00 AM

KPDES #	Facility ID	Water Quality Treatment Center	Receiving Stream of Discharge	Region
KY0106143	MSD0407	OHIO RIVER	OHIO RIVER	NA

Facility Type	Facility ID	Facility Address	If Pump Station, Name of Station	Receiving Stream	Discharge To
Sewer Treatment Plant	MSD0407	1818 LANDING RD	OHIO RIVER	OHIO RIVER	STREAM

Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3923377		4/5/2025 10:12:00 AM	BALDRIDGE		REPAIRED - ISSUE RESOLVED	4/5/2025 12:00:00 AM	BYPASS AT WQTC	UNAUTHORIZED DISCHARGE-WATERS	04/05/25 10:20 AM	

Discharge Reporting:

Discharge Amount:	50 GAL
Cause:	LACK OF SYSTEM CAPACITY (HEAVY FLOW DURING RAIN WITH GRINDER FAULT).
Clean Up:	CLEANED AND SANITIZED THE IMPACTED AREA.
Control Zone:	OVERFLOW CONTAINED ON MSD PROPERTY.
Impact:	OBSERVED SEWAGE ON FLOOR.
Repair:	REPAIRED THE (OPERATOR RESET GRINDER FAULT. GRINDER STARTED FLOW WENT DOWN).
Public Notification:	INSIDE MSD FACILITY.

Notifications:

4/6/25 1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
----------------	--------	---



IMSAST0004
Overflow Report
4/1/2025 12:00:00 AM to 4/30/2025 12:00:00 AM

KPDES #	Facility ID	Water Quality Treatment Center	Receiving Stream of Discharge	Region
KY0111716	MSD0414	SOUTH OLDHAM	SOUTH FORK HARRODS CREEK	NA

Facility Type	Facility ID	Facility Address	If Pump Station, Name of Station	Receiving Stream	Discharge To
Sewer Treatment Plant	MSD0414	6115 HITT LN	SOUTH OLDHAM	SOUTH FORK HARRODS CREEK	STREAM

Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3923263		4/4/2025 4:15:00 PM	LONG	STEVENS	BEYOND APPROVED DESIGN STORM	4/4/2025 12:00:00 AM	BYPASS AT WQTC	UNAUTHORIZED DISCHARGE-WATERS	04/04/25 05:15 PM	

Discharge Reporting:

Discharge Amount:	150 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	MSD PERSONNEL CLEANED AND SANITIZED THE IMPACTED AREA.
Control Zone:	TEMPORARY SIGNS HAVE BEEN POSTED.
Impact:	NONE OBSERVED.
Repair:	SITE FOUND DURING RAIN EVENT RECON.
Public Notification:	TEMPORARY SIGNS HAVE BEEN POSTED.



IMSAST0004
Overflow Report
4/1/2025 12:00:00 AM to 4/30/2025 12:00:00 AM

KPDES #	Facility ID	Water Quality Treatment Center	Receiving Stream of Discharge	Region
KY0034169	MSD0507	BCSD HILLVIEW #2	BROOKS RUN	

Facility Type	Facility ID	Facility Address	If Pump Station, Name of Station	Receiving Stream	Discharge To
Sewer Treatment Plant	MSD0507	376 NORWOOD DR	BCSD HILLVIEW #2	BROOKS RUN	STREAM

Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3922280		4/3/2025 1:06:00 AM	BALDRIDGE		DOCUMENTED	12/6/2021 12:00:00 AM	BYPASS AT WQTC	UNAUTHORIZED DISCHARGE- WATERS	04/07/25 06:00 AM	

Discharge Reporting:

Discharge Amount:	151,000 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	CLEANED & SANITIZED THE AREA.
Control Zone:	PERMANENT SIGN IN PLACE – NO ADDITIONAL CONTROL ZONE SET UP.
Impact:	SEWAGE FOUND DITCH INSIDE MSD FENCE.
Repair:	A SOLUTION FOR THIS LOCATION IS INCLUDED IN THE INTEGRATED OVERFLOW ABATEMENT PLAN.
Public Notification:	ADVISED CUSTOMER ON SITE.

Notifications:

4/3/25 1:00 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
4/3/25 1:00 PM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



IMSAST0004
Overflow Report
4/1/2025 12:00:00 AM to 4/30/2025 12:00:00 AM

KPDES #	Facility ID	Water Quality Treatment Center	Receiving Stream of Discharge	Region
KY0034177	MSD0508	BCSD HILLVIEW #3	BROOKS RUN	

Facility Type	Facility ID	Facility Address	If Pump Station, Name of Station	Receiving Stream	Discharge To
Sewer Treatment Plant	MSD0508	126 WESTERN RD	BCSD HILLVIEW #3	BROOKS RUN	STREAM

Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3922279		4/3/2025 1:05:00 AM	BALDRIDGE		DOCUMENTED	3/29/2023 12:00:00 AM	BYPASS AT WQTC	UNAUTHORIZED DISCHARGE- WATERS	04/06/25 07:55 PM	

Discharge Reporting:

Discharge Amount:	163,800 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	CLEANED & SANITIZED THE AREA.
Control Zone:	PERMANENT SIGN IN PLACE – NO ADDITIONAL CONTROL ZONE SET UP.
Impact:	OVERFLOWS TO DITCH WITH PLANT EFFLUENT.
Repair:	A SOLUTION FOR THIS LOCATION IS INCLUDED IN THE INTEGRATED OVERFLOW ABATEMENT PLAN.
Public Notification:	INSIDE MSD FENCE.

Notifications:

4/3/25 1:00 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
4/3/25 1:00 PM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



IMSAST0004
Overflow Report
4/1/2025 12:00:00 AM to 4/30/2025 12:00:00 AM

KPDES #	Facility ID	Water Quality Treatment Center	Receiving Stream of Discharge	Region
KY0034177	MSD0508	BCSD HILLVIEW #3	BROOKS RUN	

Facility Type	Facility ID	Facility Address	If Pump Station, Name of Station	Receiving Stream	Discharge To
Sewer Treatment Plant	MSD0508	126 WESTERN RD	BCSD HILLVIEW #3	BROOKS RUN	STREAM

Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3935636		4/25/2025 10:20:00 AM	SMITHER	SMITHER	DOCUMENTED	3/29/2023 12:00:00 AM	BYPASS AT WQTC	UNAUTHORIZED DISCHARGE-WATERS	04/25/25 10:25 AM	

Discharge Reporting:

Discharge Amount:	500 GAL
Cause:	ELECTRICAL PROBLEM WITH MSD EQUIPMENT/ASSET (BLOWN FUSE GOING TO BLOWER BUILDING AND UV SYSTEM).
Clean Up:	CLEANUP NOT POSSIBLE, OPERATOR PUT IN CHLORINE TABLETS ONCE FOUND.
Control Zone:	PERMANENT SIGN IN PLACE – NO ADDITIONAL CONTROL ZONE SET UP.
Impact:	NONE OBSERVED
Repair:	REPAIRED THE ELECTRICAL SERVICE, REPLACED FUSE.
Public Notification:	PERMANENT SIGN IN PLACE.

Notifications:

4/25/25 1:00 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
4/25/25 1:00 PM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



IMSAST0004
Overflow Report
4/1/2025 12:00:00 AM to 4/30/2025 12:00:00 AM

KPDES #	Facility ID	Water Quality Treatment Center	Receiving Stream of Discharge	Region
KY0034185	MSD0512	PIONEER VILLAGE #1	BROOKS RUN	

Facility Type	Facility ID	Facility Address	If Pump Station, Name of Station	Receiving Stream	Discharge To
Sewer Treatment Plant	MSD0512	815 JOHN HARPER HWY	PIONEER VILLAGE #1	BROOKS RUN	STREAM

Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3922281		4/3/2025 12:31:00 AM	BALDRIDGE		DOCUMENTED	3/8/2023 12:00:00 AM	BYPASS AT WQTC	UNAUTHORIZED DISCHARGE-WATERS	04/07/25 08:59 AM	

Discharge Reporting:

Discharge Amount:	126,000 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	CLEANED & SANITIZED THE AREA.
Control Zone:	PERMANENT SIGN IN PLACE – NO ADDITIONAL CONTROL ZONE SET UP.
Impact:	SEWAGE FOUND AROUND MANHOLE.
Repair:	A SOLUTION FOR THIS LOCATION IS INCLUDED IN THE INTEGRATED OVERFLOW ABATEMENT PLAN.
Public Notification:	ADVISED CUSTOMER ON SITE.

Notifications:

4/3/25 1:00 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
4/3/25 1:00 PM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



IMSAST0004
Overflow Report
4/1/2025 12:00:00 AM to 4/30/2025 12:00:00 AM

KPDES #	Facility ID	Water Quality Treatment Center	Receiving Stream of Discharge	Region
KY0034801	MSD0509	BULLITT HILLS	TANYARD BRANCH	

Facility Type	Facility ID	Facility Address	If Pump Station, Name of Station	Receiving Stream	Discharge To
Sewer Lift Station	SSPSBH-PRVL	191 WILMA AVE	BULLITT HILLS	TANYARD BRANCH	GROUND

Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3923433		4/5/2025 8:30:00 PM	HUBER IV	TIMMERING	DOCUMENTED	6/20/2023 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE- WATERS	04/06/25 08:38 PM	

Discharge Reporting:

Discharge Amount:	144,800 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	MSD PERSONNEL CLEANED AND SANITIZED THE IMPACTED AREA.
Control Zone:	TEMPORARY SIGNS HAVE BEEN POSTED.
Impact:	NO DEBRIS OBSERVED AT SITE.
Repair:	SITE FOUND DURING RAIN EVENT RECON - WILL BE MONITORED AND EVALUATED FOR REPAIR.
Public Notification:	TEMPORARY SIGNS HAVE BEEN POSTED.

Notifications:

4/6/25 1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
4/6/25 1:00 AM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION
4/6/25 1:00 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
4/6/25 1:00 PM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



IMSAST0004
Overflow Report
4/1/2025 12:00:00 AM to 4/30/2025 12:00:00 AM

KPDES #	Facility ID	Water Quality Treatment Center	Receiving Stream of Discharge	Region
KY0034169	MSD0507	BCSD HILLVIEW #2	BROOKS RUN	

Facility Type	Facility ID	Facility Address	If Pump Station, Name of Station	Receiving Stream	Discharge To
Sewer Lift Station	SSPSH2-HLV2	319 WINSTON CT	BCSD HILLVIEW #2	BROOKS RUN	STREAM

Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3922569		4/3/2025 8:15:00 PM	MILES	TIMMERING	DOCUMENTED	12/11/2021 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE- WATERS	04/03/25 08:27 PM	

Discharge Reporting:

Discharge Amount:	1,800 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	MSD PERSONNEL CLEANED AND SANITIZED THE IMPACTED AREA.
Control Zone:	TEMPORARY SIGNS HAVE BEEN POSTED.
Impact:	NONE OBSERVED.
Repair:	SITE FOUND DURING RAIN EVENT RECON.
Public Notification:	TEMPORARY SIGNS HAVE BEEN POSTED.

Notifications:

4/4/25 1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
----------------	--------	--



IMSAST0004
Overflow Report
4/1/2025 12:00:00 AM to 4/30/2025 12:00:00 AM

KPDES #	Facility ID	Water Quality Treatment Center	Receiving Stream of Discharge	Region
KY0034169	MSD0507	BCSD HILLVIEW #2	BROOKS RUN	

Facility Type	Facility ID	Facility Address	If Pump Station, Name of Station	Receiving Stream	Discharge To
Sewer Lift Station	SSPSH2-HLV2	319 WINSTON CT	BCSD HILLVIEW #2	BROOKS RUN	STREAM

Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3922612		4/4/2025 12:49:00 AM	MILES	TIMMERING	DOCUMENTED	12/11/2021 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE- WATERS	04/04/25 11:45 PM	

Discharge Reporting:

Discharge Amount:	32,800 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	CLEANUP NOT POSSIBLE DUE TO MAGNITUDE OF STORM.
Control Zone:	TEMPORARY AND PERMANENT SIGNS PLACED.
Impact:	NO IMPACT OBSERVED STORM FLUSHED DEBRIS FROM SITE.
Repair:	SITE FOUND DURING RECON WILL BE MONITORED AND EVALUATED FOR REPAIR.
Public Notification:	TEMPORARY AND PERMANENT SIGNS PLACED.

Notifications:

4/4/25 1:00 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
4/4/25 1:00 PM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



IMSAST0004
Overflow Report
4/1/2025 12:00:00 AM to 4/30/2025 12:00:00 AM

KPDES #	Facility ID	Water Quality Treatment Center	Receiving Stream of Discharge	Region
KY0034177	MSD0508	BCSD HILLVIEW #3	BROOKS RUN	

Facility Type	Facility ID	Facility Address	If Pump Station, Name of Station	Receiving Stream	Discharge To
Sewer Lift Station	SSPSH3-HLV3	169 SUMMERS DR	BCSD HILLVIEW #3	BROOKS RUN	STREAM

Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3922287		4/3/2025 2:39:00 AM	JACKSON	MILES	DOCUMENTED	12/8/2021 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE- WATERS	04/07/25 06:30 AM	

Discharge Reporting:

Discharge Amount:	113,775 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	CLEAN UP NOT POSSIBLE DUE TO MAGNITUDE OF STORM.
Control Zone:	PLACED TEMPORARY SIGNS AROUND IMPACTED AREA.
Impact:	SEWAGE / DEBRIS / SOLIDS / PERSONAL HYGIENE PRODUCTS FOUND AROUND IMPACTED AREA.
Repair:	REPORTED BY BASE 4 - SITE WILL BE MONITORED AND EVALUATED FOR REPAIR.
Public Notification:	PLACED TEMPORARY SIGNS AROUND IMPACTED AREA.

Notifications:

4/3/25 1:00 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
4/3/25 1:00 PM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



IMSAST0004
Overflow Report
4/1/2025 12:00:00 AM to 4/30/2025 12:00:00 AM

KPDES #	Facility ID	Water Quality Treatment Center	Receiving Stream of Discharge	Region
KY0022420	MSD0202	HITE CREEK	HITE CREEK	NA

Facility Type	Facility ID	Facility Address	If Pump Station, Name of Station	Receiving Stream	Discharge To
Sewer Lift Station	SSPSHC-BRCR	5000 CHAMBERLAIN LN	HITE CREEK	WOLF PEN BRANCH	STREAM

Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3923673		4/8/2025 12:50:00 AM	MILES	MILES	REPAIRED - ISSUE RESOLVED	4/8/2025 12:00:00 AM	MECHANICAL FAILURE	UNAUTHORIZED DISCHARGE- WATERS	04/08/25 07:15 AM	

Discharge Reporting:

Discharge Amount:	38,500 GAL
Cause:	MECHANICAL FAILURE.
Clean Up:	CLEAN AND SANITIZE AREA UPON COMPLETION.
Control Zone:	FENCE AND SIGNS.
Impact:	DEBRIS ON THE GROUND.
Repair:	HAUL STATION TILL REPAIRED.
Public Notification:	TEMPORARY AND PERMANENT SIGNS.

Notifications:

4/8/25 1:00 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
4/8/25 1:00 PM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



IMSAST0004
Overflow Report
4/1/2025 12:00:00 AM to 4/30/2025 12:00:00 AM

KPDES #	Facility ID	Water Quality Treatment Center	Receiving Stream of Discharge	Region
KY0106143	MSD0407	OHIO RIVER	OHIO RIVER	NA

Facility Type	Facility ID	Facility Address	If Pump Station, Name of Station	Receiving Stream	Discharge To
Sewer Lift Station	SSPSOR-CWDR	1108 CLIFFWOOD DR	OHIO RIVER	LITTLE HUCKLEBERRY CREEK	GROUND

Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3923098		4/4/2025 8:55:00 AM	HUBER IV	MULLINS	BEYOND APPROVED DESIGN STORM	4/4/2025 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE- WATERS	04/07/25 08:30 AM	

Discharge Reporting:

Discharge Amount:	322,125 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	MSD PERSONNEL CLEANED AND SANITIZED THE IMPACTED AREA.
Control Zone:	TEMPORARY SIGNS HAVE BEEN POSTED.
Impact:	NO DEBRIS OBSERVED AT SITE.
Repair:	SITE FOUND DURING RAIN EVENT RECON - WILL BE MONITORED AND EVALUATED FOR REPAIR.
Public Notification:	TEMPORARY SIGNS HAVE BEEN POSTED.

Notifications:

4/5/25 1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
4/5/25 1:00 AM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



IMSAST0004
Overflow Report
4/1/2025 12:00:00 AM to 4/30/2025 12:00:00 AM

KPDES #	Facility ID	Water Quality Treatment Center	Receiving Stream of Discharge	Region
KY0034185	MSD0512	PIONEER VILLAGE #1	BROOKS RUN	

Facility Type	Facility ID	Facility Address	If Pump Station, Name of Station	Receiving Stream	Discharge To
Sewer Lift Station	SSPSPV-HUHL	165 OCTAGON AVE	PIONEER VILLAGE #1	BROOKS RUN	STREAM

Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3922285		4/3/2025 1:28:00 AM	JACKSON	MILES	DOCUMENTED	12/21/2022 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE- WATERS	04/08/25 06:31 AM	

Discharge Reporting:

Discharge Amount:	1,259,600 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	NO CLEAN UP PERFORMED – PIPE DISCHARGING UNDERWATER, DIRECTLY INTO STREAM.
Control Zone:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.
Impact:	NONE OBSERVED- OUTLET SUBMERGED.
Repair:	REPORTED BY BASE 4, WILL BE MONITORED AND EVALUATED FOR REPAIR.
Public Notification:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.

Notifications:

4/3/25 1:00 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
4/3/25 1:00 PM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION

KPDES #	Facility ID	Water Quality Treatment Center	Receiving Stream of Discharge	Region
KY0034185	MSD0512	PIONEER VILLAGE #1	BROOKS RUN	

Facility Type	Facility ID	Facility Address	If Pump Station, Name of Station	Receiving Stream	Discharge To
Sewer Lift Station	SSPSPV-HUHL	165 OCTAGON AVE	PIONEER VILLAGE #1	BROOKS RUN	STREAM

Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3925909		4/10/2025 8:40:00 PM	SOSA RODRIGUEZ	SOSA RODRIGUEZ	DOCUMENTED	12/21/2022 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE- WATERS	04/14/25 08:45 AM	

Discharge Reporting:

Discharge Amount:	21,400 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	NO CLEAN UP PERFORMED – PIPE DISCHARGING UNDERWATER, DIRECTLY INTO STREAM.
Control Zone:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.
Impact:	NONE OBSERVED- OUTLET SUBMERGED.
Repair:	REPORTED BY BASE 4, WILL BE MONITORED AND EVALUATED FOR REPAIR.
Public Notification:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.

Notifications:

4/11/25 1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
4/11/25 1:00 AM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



IMSAST0004
Overflow Report
4/1/2025 12:00:00 AM to 4/30/2025 12:00:00 AM

KPDES #	Facility ID	Water Quality Treatment Center	Receiving Stream of Discharge	Region
KY0034185	MSD0512	PIONEER VILLAGE #1	BROOKS RUN	

Facility Type	Facility ID	Facility Address	If Pump Station, Name of Station	Receiving Stream	Discharge To
Sewer Lift Station	SSPSPV-HUHL	165 OCTAGON AVE	PIONEER VILLAGE #1	BROOKS RUN	STREAM

Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3925986		4/11/2025 7:55:00 AM	BROADEN	BROADEN	DOCUMENTED	12/21/2022 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE- WATERS	04/14/25 08:54 AM	

Discharge Reporting:

Discharge Amount:	1 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	NO CLEAN UP PERFORMED – PIPE DISCHARGING UNDERWATER, DIRECTLY INTO STREAM.
Control Zone:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.
Impact:	NONE OBSERVED- OUTLET SUBMERGED.
Repair:	REPORTED BY BASE 4, WILL BE MONITORED AND EVALUATED FOR REPAIR.
Public Notification:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.

Notifications:

4/11/25 1:00 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
4/11/25 1:00 PM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



IMSAST0004
Overflow Report
4/1/2025 12:00:00 AM to 4/30/2025 12:00:00 AM

KPDES #	Facility ID	Water Quality Treatment Center	Receiving Stream of Discharge	Region
KY0034185	MSD0512	PIONEER VILLAGE #1	BROOKS RUN	

Facility Type	Facility ID	Facility Address	If Pump Station, Name of Station	Receiving Stream	Discharge To
Sewer Lift Station	SSPSPV-HUHL	165 OCTAGON AVE	PIONEER VILLAGE #1	BROOKS RUN	STREAM

Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3935706		4/25/2025 4:03:00 PM	MILES		DOCUMENTED	12/21/2022 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE- WATERS	04/27/25 09:02 AM	

Discharge Reporting:

Discharge Amount:	16,200 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	NO CLEAN UP PERFORMED – PIPE DISCHARGING UNDERWATER, DIRECTLY INTO STREAM.
Control Zone:	PERMANENT SIGNS SUPPLEMENTED WITH TEMPORARY SIGNS AND CONES.
Impact:	NONE OBSERVED- OUTLET SUBMERGED.
Repair:	REPORTED BY BASE 4, WILL BE MONITORED AND EVALUATED FOR REPAIR.
Public Notification:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.

Notifications:

4/26/25 1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
4/26/25 1:00 AM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



IMSAST0004
Overflow Report
4/1/2025 12:00:00 AM to 4/30/2025 12:00:00 AM

KPDES #	Facility ID	Water Quality Treatment Center	Receiving Stream of Discharge	Region
KY0094307	MSD0511	WILLABROOK	BROOKS RUN	

Facility Type	Facility ID	Facility Address	If Pump Station, Name of Station	Receiving Stream	Discharge To
Sewer Lift Station	SSPSWB-MATL	3955 E BLUE LICK RD	WILLABROOK	BROOKS RUN	GROUND

Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	3922286		4/3/2025 2:08:00 AM	JACKSON	MILES	DOCUMENTED	1/1/1992 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE-WATERS	04/08/25 10:17 PM	

Discharge Reporting:

Discharge Amount:	728,200 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	CLEANUP NOT POSSIBLE DUE TO MAGNITUDE OF STORM.
Control Zone:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.
Impact:	SEWAGE / DEBRIS / SOLIDS / PERSONAL HYGIENE PRODUCTS FOUN IN THE AREA.
Repair:	REPORTED BY BASE 4 WILL BE MONITORED AND EVALUATED FOR REPAIR.
Public Notification:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.

Notifications:

4/3/25 1:00 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
4/3/25 1:00 PM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION