



700 West Liberty Street | Louisville, KY 40203-1911
Phone: 502.540.6000 | LouisvilleMSD.org

Aug 20, 2026

Crystal Dennis
300 Sower Boulevard, 3rd Floor
Frankfort, KY 40601

RE: Bullitt Hills STP, KPDES No. KY0034801
Discharge Monitoring Report – July 2026

Dear Ms. Dennis:

Attached is the Discharge Monitoring Report (DMR) for Bullitt Hills STP for the month of July 2026.

There were no exceedances or bypasses.

Please see the attached overflow report for details

If you have any questions concerning the attached DMR's, please contact me on (502) 540-6000.

Sincerely,

Jesse Howard
Process Supervisor

JH/BH 8/26

cc: V. Teague, B. Tinnel

EPA may make all the information submitted through this form (including all attachments) available to the public without further notice to you. Do not use this online form to submit personal information (e.g., non-business cell phone number or non-business email address), confidential business information (CBI), or if you intend to assert a CBI claim on any of the submitted information. Pursuant to 40 CFR 2.203(a), EPA is providing you with notice that all CBI claims must be asserted at the time of submission. EPA cannot accommodate a late CBI claim to cover previously submitted information because efforts to protect the information are not administratively practicable since it may already be disclosed to the public. Although we do not foresee a need for persons to assert a claim of CBI based on the types of information requested in this form, if persons wish to assert a CBI claim we direct submitters to contact the [NPDES eReporting Help Desk](#) for further guidance. Please note that EPA may contact you after you submit this report for more information.

This collection of information is approved by OMB under the Paperwork Reduction Act, 44 U.S.C. 3501 et seq. (OMB Control No. 2040-0004). Responses to this collection of information are mandatory in accordance with this permit and EPA NPDES regulations 40 CFR 122.41(l)(4)(i). An agency may not conduct or sponsor, and a person is not required to respond to, a collection of information unless it displays a currently valid OMB control number. The public reporting and recordkeeping burden for this collection of information are estimated to average 2 hours per outfall. Send comments on the Agency's need for this information, the accuracy of the provided burden estimates and any suggested methods for minimizing respondent burden to the Regulatory Support Division Director, U.S. Environmental Protection Agency (2821T), 1200 Pennsylvania Ave., NW, Washington, D.C. 20460. Include the OMB control number in any correspondence. Do not send the completed form to this address.

Permit

Permit #:
Major:

KY0034801
No

Permittee:
Permittee Address:

Louisville and Jefferson County MSD
1600 W Hill St
Louisville, KY 40210

Facility:
Facility Location:

BCSD BULLITT HILLS SUBDIVISION
12105 PRESTON HWY
HILLVIEW, KY 40229

Permitted Feature:

001
External Outfall

Discharge:

001-1
Domestic Wastewater

Report Dates & Status

Monitoring Period:

From 07/01/26 to 07/31/26

DMR Due Date:

08/28/26

Status:

NetDMR Validated

Considerations for Form Completion

Principal Executive Officer

First Name:
Last Name:

James
Parrott

Title:

Executive Director

Telephone:

502-540-6000

No Data Indicator (NODI)

Form NODI: --

Parameter		Monitoring Location	Season #	Param. NODI		Quantity or Loading					Quality or Concentration							# of Ex.	Frequency of Analysis	Sample Type
Code	Name					Qualifier 1	Value 1	Qualifier 2	Value 2	Units	Qualifier 1	Value 1	Qualifier 2	Value 2	Qualifier 3	Value 3	Units			
00300	Oxygen, dissolved [DO]	1 - Effluent Gross	0	--	Sample						=	7.1					19 - mg/L	0	01/07 - Weekly	GR - Grab
					Permit Req.						>=	7.0 INST MIN					19 - mg/L		01/07 - Weekly	GR - Grab
					Value NODI															
00400	pH	1 - Effluent Gross	0	--	Sample						=	7.1			=	7.6	12 - SU	0	01/07 - Weekly	GR - Grab
					Permit Req.						>=	6.0 MINIMUM			<=	9.0 MAXIMUM	12 - SU		01/07 - Weekly	GR - Grab
					Value NODI															
00530	Solids, total suspended	1 - Effluent Gross	0	--	Sample								=	6.0	=	9.0	19 - mg/L	0	01/07 - Weekly	CP - Composite
					Permit Req.								<=	30.0 MO AVG	<=	45.0 MX WK AV	19 - mg/L		01/07 - Weekly	CP - Composite
					Value NODI															
00600	Nitrogen, total [as N]	1 - Effluent Gross	0	--	Sample								=	16.7	=	27.1	19 - mg/L	0	01/07 - Weekly	CP - Composite
					Permit Req.									Req Mon MO AVG		Req Mon MX WK AV	19 - mg/L		01/07 - Weekly	CP - Composite
					Value NODI															
00610	Nitrogen, ammonia total [as N]	1 - Effluent Gross	1	--	Sample								=	0.48	=	0.9	19 - mg/L	0	01/07 - Weekly	CP - Composite
					Permit Req.								<=	4.0 MO AVG	<=	6.0 DAILY MX	19 - mg/L		01/07 - Weekly	CP - Composite
					Value NODI															
00665	Phosphorus, total [as P]	1 - Effluent Gross	0	--	Sample								=	2.74	=	3.74	19 - mg/L	0	01/07 - Weekly	CP - Composite
					Permit Req.									Req Mon MO AVG		Req Mon DAILY MX	19 - mg/L		01/07 - Weekly	CP - Composite
					Value NODI															
50050	Flow, in conduit or thru treatment plant	1 - Effluent Gross	0	--	Sample	=	0.1331	=	0.446	03 - MGD								0	99/99 - Continuous	RC - Recorder (auto)
					Permit Req.		Req Mon MO AVG		Req Mon DAILY MX	03 - MGD									01/07 - Weekly	IN - Instantaneous
					Value NODI															
50060	Chlorine, total residual	1 - Effluent Gross	0	--	Sample								=	0.0	=	0.0	19 - mg/L	0	01/07 - Weekly	GR - Grab
					Permit Req.								<=	0.011 MO AVG	<=	0.019 DAILY MX	19 - mg/L		01/07 - Weekly	GR - Grab
					Value NODI															
51040	E. coli	1 - Effluent Gross	0	--	Sample								=	1.5	=	4.0	13 - #/100mL	0	01/07 - Weekly	GR - Grab
					Permit Req.								<=	130.0 30DA GEO	<=	240.0 7 DA GEO	13 - #/100mL		01/07 - Weekly	GR - Grab
					Value NODI															
80082	BOD, carbonaceous [5 day, 20 C]	1 - Effluent Gross	0	--	Sample								=	3.0	=	3.0	19 - mg/L	0	01/07 - Weekly	CP - Composite
					Permit Req.								<=	25.0 MO AVG	<=	37.5 MX WK AV	19 - mg/L		01/07 - Weekly	CP - Composite

					Value NODI													
Submission Note																		
If a parameter row does not contain any values for the Sample nor Effluent Trading, then none of the following fields will be submitted for that row: Units, Number of Excursions, Frequency of Analysis, and Sample Type.																		
Edit Check Errors																		
No errors.																		
Comments																		
Attachments																		
Name															Type		Size	
DischargeReportJuly2026.pdf															pdf		104002.0	
BullittHillscoverJuly2026.pdf															pdf		33575.0	
BULLITTHILLSLIMSPCSSPREADSHEET011323072026.xls															xls		193536.0	
Report Last Saved By																		
Louisville and Jefferson County MSD																		
User:					JESSE.HOWARD@LOUISVILLEMSD.ORG													
Name:					Jesse Howard													
E-Mail:					jesse.howard@louisvillemSD.org													
Date/Time:					2026-08-21 09:10 (Time Zone: -04:00)													
Report Last Signed By																		
User:					JESSE.HOWARD@LOUISVILLEMSD.ORG													
Name:					Jesse Howard													
E-Mail:					jesse.howard@louisvillemSD.org													
Date/Time:					2026-08-21 09:30 (Time Zone: -04:00)													

	A	C	G	I	K	L	O	P	Q	R	V	Y	Z	AN	AP	AR	AT
1	"Ctrl+Shift+E" to export Bullitt Hills July-26 July																
2	Plant Effluent																
3	DATE	Flow	Effl. CBOD	Effl. TSS	Effl. NH3	<	Effl. T-Phos.	ECOLI MPN	Effl. pH	Effl. DO	Eff. TN	Eff. Total Res. Cl2	<	Effluent CBOD	Effluent TSS	Eff NH3	Eff. Phos.
4		(MGD)	(mg/L)	(mg/L)	(mg/L)	>	(mg/L)	(Colonies)		(mg/L)	(mg/L)	(mg/L)	>	pounds	pounds	pounds	pounds
5	7/1/2026	0.136				<							<				
6	7/2/2026	0.118	3	4	0.25	<	0.417	4.00	7.3	7.5	9.97	<0.01	<	0	0	0	0
7	7/3/2026	0.109				<							<				
8	7/4/2026	0.098				<							<				
9	7/5/2026	0.110				<							<				
10	7/6/2026	0.112				<							<				
11	7/7/2026	0.114				<							<				
12	7/8/2026	0.109				<							<				
13	7/9/2026	0.107	3	4	0.51	<	3.6	1.00	7.6	7.9	27.10	<0.01	<	0	0	0	0
14	7/10/2026	0.144				<							<				
15	7/11/2026	0.446				<							<				
16	7/12/2026	0.227				<							<				
17	7/13/2026	0.138				<							<				
18	7/14/2026	0.103				<							<				
19	7/15/2026	0.117				<							<				
20	7/16/2026	0.120	3	6	0.25	<	3.74	1.00	7.1	7.2	15.00	<0.01	<	0	0	0	0
21	7/17/2026	0.117				<							<				
22	7/18/2026	0.123				<							<				
23	7/19/2026	0.134				<							<				
24	7/20/2026	0.121				<							<				
25	7/21/2026	0.177				<							<				
26	7/22/2026	0.160				<							<				
27	7/23/2026	0.086	3	9	0.9	<	3.22	1.00	7.1	7.1	14.80	<0.01	<	0	0	0	0
28	7/24/2026	0.089				<							<				
29	7/25/2026	0.128				<							<				
30	7/26/2026	0.132				<							<				
31	7/27/2026	0.120				<							<				
32	7/28/2026	0.120				<							<				
33	7/29/2026	0.105				<							<				
34	7/30/2026	0.105				<							<				
35	7/31/2026	0.102				<							<				
36	TOTAL	4.125												0.00	0.00	0	0.00
37	AVERAGE*	0.133	3	6	0.48	<	2.74	1.414214	7.3	7.4	16.72	0.000	<	0	0	0	0.0
38	MINIMUM	0.086	3	4	0.25	<	0.42	1	7.1	7.1	9.97	0.000	<	0	0	0	0.0
39	MAXIMUM	0.446	3	9	0.90	<	3.74	4	7.6	7.9	27.10	0.000	<	0	0	0	0.0
40	*For E. Coli: Calculation is for Geometric Mean (not Average).																
41	Max.Wk Avg	0.182	0	0	2.0		3.7	0			27			0	0	0	0.0
42	Exceed.	0	0	0	0		3	0	0	0				0	0	0	0
43	MxWkAvg																
44	Exceed		0	0	0		0	0	0					0	0	0	0
45	Mo Avg																
46	Exceed		0	0	0		0	0	0	0				0	0	0	0
47	Total KLBS Treated																
48	Summer Limits																

Month

	BD
1	
2	
3	<
4	>
5	<
6	<
7	<
8	<
9	<
10	<
11	<
12	<
13	<
14	<
15	<
16	<
17	<
18	<
19	<
20	<
21	<
22	<
23	<
24	<
25	<
26	<
27	<
28	<
29	<
30	<
31	<
32	<
33	<
34	<
35	<
36	
37	<
38	<
39	<
40	
41	
42	
43	
44	
45	
46	
47	



IMSAST0004
Overflow Report
7/1/2026 12:00:00 AM to 7/31/2026 12:00:00 AM

KPDES #	Facility ID	Water Quality Treatment Center	Receiving Stream of Discharge	Region
KY0102784	WQTCFF	FLOYDS FORK WQTC	FLOYDS FORK	JEFFERSON

Facility Type	Facility ID	Facility Address	Receiving Stream	Discharge To
Sewer Manhole	46316	1120 BLACKTHORN RD		

Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISDW:DRY WEATHER DISCHARGE	4133008		7/24/2026 8:45:00 AM	FERRELL		REPAIRED - ISSUE RESOLVED	7/24/2026 12:00:00 AM	MECHANICAL FAILURE	UNAUTHORIZED DISCHARGE-WATERS	07/24/26 10:15 AM	MAIN

Discharge Reporting:

Discharge Amount:	100 GAL
Cause:	MECHANICAL FAILURE OF PUMP STATION.
Clean Up:	MSD PERSONNEL WILL CLEAN AND SANITIZE IMPACTED AREA DISCLN 4133010.
Control Zone:	ADVISED CUSTOMER TO AVOID CONTACT WITH IMPACTED AREA/LEFT TEMPORARY SIGNS ON SITE.
Impact:	SEWAGE DISCHARGING FROM MANHOLE.
Repair:	REPAIRED PUMPS AT STATION.
Public Notification:	ADVISED CUSTOMER ON SITE.

Notifications:

7/24/26 1:00 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
-----------------	--------	---



IMSAST0004
Overflow Report
7/1/2026 12:00:00 AM to 7/31/2026 12:00:00 AM

KPDES #	Facility ID	Water Quality Treatment Center	Receiving Stream of Discharge	Region
KY0102784	WQTCFF	FLOYDS FORK WQTC	FLOYDS FORK	JEFFERSON

Facility Type	Facility ID	Facility Address	Receiving Stream	Discharge To
Sewer Manhole	85054	14102 OVERLANDER CT		

Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	4124835		7/10/2026 11:30:00 AM	GIBSON		REPAIRED - ISSUE RESOLVED	7/10/2026 12:00:00 AM	OBSTRUCTION-NOT GREASE / ROOTS	UNAUTHORIZED DISCHARGE- WATERS	07/10/26 01:00 PM	MAIN

Discharge Reporting:

Discharge Amount:	10 GAL
Cause:	OBSTRUCTION IN MAIN SEWER.
Clean Up:	MSD PERSONNEL CLEANED AND SANITIZED THE IMPACTED AREA DISCLN 4124842.
Control Zone:	MSD PERSONNEL ADVISED THE CUSTOMER TO AVOID CONTACT WITH SEWAGE.
Impact:	SEWAGE/WATER DISCHARGING FROM MANHOLE.
Repair:	FLUSHED THE OBSTRUCTION / DEBRIS FROM THE SEWER 4124838.
Public Notification:	ADVISED CUSTOMER ON SITE.

Notifications:

7/11/26 1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
-----------------	--------	--



IMSAST0004
Overflow Report
7/1/2026 12:00:00 AM to 7/31/2026 12:00:00 AM

KPDES #	Facility ID	Water Quality Treatment Center	Receiving Stream of Discharge	Region
KY0034801	WQTCBH	BULLITT HILLS WQTC	TANYARD BRANCH	BULLITT

Facility Type	Facility ID	Facility Address	Receiving Stream	Discharge To
Sewer Main	SSPSBH-GROK	203 DEEP CREEK DR	TANYARD BRANCH	DITCH

Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISDW: DRY WEATHER DISCHARGE	4132917		7/23/2026 7:05:00 PM	MILES	MILES	REPAIRED - ISSUE RESOLVED	7/23/2026 12:00:00 AM	STRUCTURAL FAILURE	UNAUTHORIZED DISCHARGE- WATERS	07/24/26 02:00 AM	

Discharge Reporting:

Discharge Amount:	24,900 GAL
Cause:	STRUCTURAL FAILURE (FORCE MAIN BREAK).
Clean Up:	MSD CONTRACTOR CLEANED AND SANITIZED THE IMPACTED AREA.
Control Zone:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.
Impact:	SEWAGE/DEBRIS/SOLIDS/PERSONAL HYGIENE PRODUCTS FOUND IN THE DITCH.
Repair:	HAULED SEWAGE UNTIL POWER COULD BE RESTORED AND/OR REPAIRS MADE.
Public Notification:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.

Notifications:

7/24/26 1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
7/24/26 1:00 AM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



IMSAST0004
Overflow Report
7/1/2026 12:00:00 AM to 7/31/2026 12:00:00 AM

KPDES #	Facility ID	Water Quality Treatment Center	Receiving Stream of Discharge	Region
KY0022420	WQTCHC	HITE CREEK WQTC	HITE CREEK	JEFFERSON

Facility Type	Facility ID	Facility Address	Receiving Stream	Discharge To
Sewer Lift Station	SSPSHC-BRCR	5000 CHAMBERLAIN LN	WOLF PEN BRANCH	STREAM

Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISDW: DRY WEATHER DISCHARGE	4124064		7/7/2026 11:56:00 PM	BROADEN	BROADEN	REPAIRED - ISSUE RESOLVED	7/8/2026 12:00:00 AM	ELECTRICAL PROBLEMS AT MSD	UNAUTHORIZED DISCHARGE- WATERS	07/08/26 12:28 AM	

Discharge Reporting:

Discharge Amount:	1,200 GAL
Cause:	ELECTRICAL PROBLEM WITH MSD EQUIPMENT (PUMP FAILURE).
Clean Up:	DISCLN 4124067.
Control Zone:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.
Impact:	SEWAGE/DEBRIS/SOLIDS/PERSONAL HYGIENE PRODUCTS FOUND AROUND WET WELL.
Repair:	REPAIRED THE MOTOR.
Public Notification:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.

Notifications:

7/8/26 1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO: DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
----------------	--------	--



IMSAST0004
Overflow Report
7/1/2026 12:00:00 AM to 7/31/2026 12:00:00 AM

KPDES #	Facility ID	Water Quality Treatment Center			Recieving Steam of Discharge		Region				
KY0022420	WQTCHC	HITE CREEK WQTC			HITE CREEK		JEFFERSON				
Facility Type	Facility ID	Facility Address				Recieving Stream		Discharge To			
Sewer Lift Station	SSPSHC-BRCR	5000 CHAMBERLAIN LN				WOLF PEN BRANCH		STREAM			
Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISDW: DRY WEATHER DISCHARGE	4124082		7/8/2026 7:23:00 AM	SANTEE	SANTEE	REPAIRED - ISSUE RESOLVED	7/8/2026 12:00:00 AM	MECHANICAL FAILURE	UNAUTHORIZED DISCHARGE- WATERS	07/08/26 01:25 PM	

Discharge Reporting:

Discharge Amount:	9,050 GAL
Cause:	MECHANICAL FAILURE (ASSET PUMP FAILURE).
Clean Up:	MSD PERSONNEL CLEANED AND SANITIZED THE IMPACTED AREA DISCLN 4124067.
Control Zone:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.
Impact:	SEWAGE/DEBRIS/SOLIDS/PERSONAL HYGIENE PRODUCTS FOUND AROUND WET WELL.
Repair:	REBUILD PUMP STATION.
Public Notification:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.

Notifications:

7/8/26 1:00 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
7/8/26 1:00 PM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



IMSAST0004
Overflow Report
7/1/2026 12:00:00 AM to 7/31/2026 12:00:00 AM

KPDES #	Facility ID	Water Quality Treatment Center			Receiving Stream of Discharge		Region				
KY0106143	WQTCOR	OHIO RIVER WQTC			OHIO RIVER		OLDHAM				
Facility Type	Facility ID	Facility Address				Receiving Stream			Discharge To		
Sewer Lift Station	SSPSOR-CRCT	3210 CROSSHILL CT				POND CREEK			GROUND		
Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISDW: DRY WEATHER DISCHARGE	4123935		7/7/2026 9:00:00 AM	SANTEE	SANTEE	REPAIRED - ISSUE RESOLVED	7/7/2026 12:00:00 AM	STRUCTURAL FAILURE	UNAUTHORIZED DISCHARGE- WATERS	07/07/26 01:05 PM	

Discharge Reporting:

Discharge Amount:	24,300 GAL
Cause:	STRUCTURAL FAILURE (8" FORCEMAIN BREAK).
Clean Up:	CLEANED AND SANITIZED THE IMPACTED AREA.
Control Zone:	REPAIRED THE FORCEMAIN.
Impact:	SEWAGE FOUND IN THE STREAM.
Repair:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.
Public Notification:	ADVISED ALL POSSIBLE IMPACTED PROPERTIES IN THE SURROUNDING AREA.

Notifications:

7/7/26 1:00 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
7/7/26 1:00 PM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION

KPDES #	Facility ID	Water Quality Treatment Center			Recieving Steam of Discharge		Region				
KY0078956	WQTC DG	DEREK R. GUTHRIE WQTC			OHIO RIVER		JEFFERSON				
Facility Type	Facility ID	Facility Address				Recieving Stream		Discharge To			
Sewer Lift Station	SSPSWB-MATL	3955 E BLUE LICK RD				BROOKS RUN		STREAM			
Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	4132492		7/21/2026 7:12:00 PM	MILES	MILES	DOCUMENTED	7/21/2026 12:00:00 AM	LACK OF SYSTEM CAPACITY	UNAUTHORIZED DISCHARGE- WATERS	07/22/26 03:15 PM	

Discharge Reporting:

Discharge Amount:	2,800 GAL
Cause:	LACK OF SYSTEM CAPACITY.
Clean Up:	NO CLEAN UP PERFORMED – PIPES DISCHARGE UNDERWATER, DIRECTLY INTO STREAM.
Control Zone:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.
Impact:	NONE OBSERVED BY MSD PERSONNEL.
Repair:	INVESTIGATION INDICATED THAT ADDITIONAL REPAIRS WERE NOT REQUIRED BY MSD.
Public Notification:	PLACED TEMPORARY SIGNS AROUND THE IMPACTED AREA.

Notifications:

7/22/26 1:00 AM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
7/22/26 1:00 AM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION



IMSAST0004
Overflow Report
7/1/2026 12:00:00 AM to 7/31/2026 12:00:00 AM

KPDES #	Facility ID	Water Quality Treatment Center	Receiving Stream of Discharge	Region
KY0034177	WQTC3	HILLVIEW #3 WQTC	BROOKS RUN	BULLITT

Facility Type	Facility ID	Facility Address	Receiving Stream	Discharge To
Sewer Treatment Plant	WQTC3	126 WESTERN RD	BROOKS RUN	STREAM

Activity Code / Description	WO #	Ref #	Initiated on	Initiated By	Assigned To	Dish Status	Event Date	Problem Desc	Result	Completed	Condition
DISREV:RAIN EVENT DISCHARGE	4125730		7/11/2026 11:30:00 AM	SMITHER	SMITHER	REPAIRED - ISSUE RESOLVED	7/11/2026 12:00:00 AM	ELECTRICAL PROBLEMS AT MSD	UNAUTHORIZED DISCHARGE- WATERS	07/11/26 01:57 PM	

Discharge Reporting:

Discharge Amount:	1,000 GAL
Cause:	ELECTRICAL PROBLEM WITH MSD EQUIPMENT/ASSET (UV SYSTEM BREAKER IS TRIPPING).
Clean Up:	CLEANUP NOT POSSIBLE DUE TO BEING DISCHARGED TO THE CREEK.
Control Zone:	SIGN AT DISCHARGE LOCATION.
Impact:	NONE.
Repair:	ADDED TABLETS TO PLANT DISCHARGE FOR DISINFECTION, ELECTRICIAN WORKING ON REPAIR.
Public Notification:	SIGN AT DISCHARGE LOCATION.

Notifications:

7/11/26 1:00 PM	DISNOT	EMAIL NOTIFICATION OF UNAUTHORIZED DISCHARGE SENT TO:DISCHARGENOTICES@LOUISVILLEMSD.ORG, SAYRE.DENNIS@EPAMAIL.EPA.GOV
7/11/26 1:00 PM	DISSNO	WAITING TO COMPLETE THE DISCHARGE INFORMATION